

JTB00549NAS3

TECHNICAL BULLETIN

29 MAY 2019



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

SECTION:

413-13

SUBJECT/CONCERN:

Parking Aid System Sounds With No Objects Nearby

AFFECTED VEHICLE RANGE:

| MODEL: | MODEL YEAR: | VIN: | ASSEMBLY PLANT: |
|---------------|-------------|---------------|-----------------|
| F-PACE (X761) | 2017 | 045068-099996 | Solihull |
| F-PACE (X761) | 2017 | 488002-499998 | Solihull |
| F-PACE (X761) | 2017 | 880002-899840 | Solihull |

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:

SITUATION:

The front Parking Aid System may sound when no objects are near the vehicle.

CAUSE:

This may be caused by the front bumper interfering with the parking aid sensor reporting area.

ACTION:

Should a Customer express this concern, follow the procedure(s) below.

PARTS:

No Parts Required

TOOLS:

E192494

Jaguar Land Rover-approved
Midtronics battery
power supply



E179225

Jaguar Land Rover-approved
diagnostic tool with
latest SDD
software

WARRANTY:**NOTES:**

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Use TOPIx to obtain the latest repair time.
- The JLR claims submission system requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

| DESCRIPTION | SRO | TIME (HOURS) | CONDITION CODE | CAUSAL PART |
|---|----------|--------------|----------------|-------------|
| Configure Parking Assist Control Module (PAM) | 86.98.17 | 0.20 | 42 | C2D50699 |

 **NOTE:**

Normal Warranty procedures apply.

DIAGNOSTIC PROCEDURE: **CAUTIONS:**

- A Jaguar Land Rover-approved battery power supply must be connected to the vehicle startup battery.
- All ignition ON/OFF requests **MUST** be performed; failure to do these steps may cause damage to vehicle control modules.

1 Connect the Jaguar Land Rover-approved battery power supply to the vehicle startup battery.

2

 **NOTE:**

The Jaguar Land Rover-approved diagnostic tool must be loaded with DVD156.06 and Calibration File 317 (or later).

Connect the Jaguar Land Rover-approved diagnostic equipment to the vehicle and begin a new session.

3 Follow all on-screen instructions.

4 If the hyperlink is not available:

- 1 Switch the ignition ON (engine not running).
- 2 Connect the Jaguar Land Rover-approved diagnostic equipment to the vehicle and begin a new session.
- 3 Follow the on-screen prompts, allowing the diagnostic equipment to read the VIN, identify the vehicle, and initiating the data collect sequence.
- 4 Select **Diagnosis** from the Session Type screen.
- 5 Select the **Selected Symptoms** tab.

- 6 Select **Electrical - Driving aids - Parking aid**.
 - 7 Select **continue**.
 - 8 Select the **Recommendations** tab.
 - 9 Select **Run** to perform the '**Configure existing module - Parking assist control module**' option.
-

5 Follow all on-screen instructions until the application completes successfully.

- 1 When prompted, select the **Clear DTCs** option following completion of the software download.
 - 2 Follow the on-screen instructions until the application finishes successfully.
-

6 Exit the current session.

- 1 Select the **Session** tab.
 - 2 Select the **Close Session** option.
-

7 Disconnect the diagnostic equipment and battery power supply from the vehicle.