



SI B01 21 18  
Warranties

June 2019  
Technical Service

## **UPDATE!** N63 ENGINE: OIL CONSUMPTION CLASS ACTION SETTLEMENT DIAGNOSIS AND REPAIR PROCEDURES (VERSION 10.0)

New information provided by this revision is preceded by this symbol **UPDATE!**.

This Service Information bulletin supersedes SI B01 21 18 **dated March 2019**

### What's New:

- Model descriptions added
- Procedure updated
- Parts section updated
- Checklists updated
- Instructions updated with repair hints

## **UPDATE!** CLASS VEHICLES (MODELS)

Certain of the following US-specification BMW vehicles sold or leased in the United States and Puerto Rico are included:

E70 (X5 xDrive50i) (N63) Model Years (MY) 2010, 2011, 2012 and 2013	E71 (X6 xDrive50i) (N63) MY 2009, 2010, 2012, 2013 and 2014	E72 (ActiveHybrid X6) (N63) MY 2009, 2010 and 2011	F01 (750i Sedan & ALPINA B7) (N63) MY 2009, 2010, 2011 and 2012
F01 (750i xDrive Sedan & ALPINA B7) (N63) MY 2010, 2011 and 2012	F02 (750Li Sedan & ALPINA B7) (N63) MY 2009, 2010, 2011 and 2012	F02 (750Li xDrive Sedan & ALPINA B7) (N63) MY 2010, 2011 and 2012	F04 (ActiveHybrid 750i) (N63) MY 2010 (one VIN), 2011, 2012 and 2013
F07 (550i Gran Turismo) (N63) MY 2010, 2011 and 2012	F07 (550i x Drive Gran Turismo) (N63) MY 2010, 2011 and 2012	F10 (550i Sedan) (N63) MY 2010, 2011, 2012 and 2013	F10 (550i xDrive Sedan) (N63) MY 2010, 2011, 2012 and 2013
F12 (650i Convertible) (N63) MY 2011 and 2012	F12 (650i xDrive Convertible) (N63) MY 2011 and 2012	F13 (650i Coupe) (N63) MY 2011 and 2012	F13 (650i xDrive Coupe) (N63) MY 2011 and 2012

## INFORMATION

This Service Information bulletin applies to:

- Class vehicles in operation on the road (Applicable N63 engine model vehicles); by
- Class members (Class Vehicle owners on the date this settlement became effective),

And it provides diagnostic/repairs instructions, as well as, Warranty Information for performed remedies.

Also, please familiarize yourself with other important Service Bulletins pertaining to the N63 Class Action Settlement:

- SI [B01 29 18](#) - N63 Engine Vehicles: Class Action Settlement For Engine Oil Consumption/Battery Drain / OVERVIEW
- SI [B01 22 18](#) - N63 Engine Class Action Settlement: BATTERY SERVICE BENEFIT
- SI [B01 23 18](#) - N63 Engine Oil Consumption/Battery Drain Class Action Law Suit Settlement: FUTURE ENGINE OIL SERVICE BENEFIT
- SI [B01 28 18](#) - N63 Engine Repairs: RENTAL CARS for OUT of SERVICE VEHICLES

## SITUATION

While engine oil consumption may create a customer inconvenience, in the short term, it should not cause any drivability problems that would prevent normal day-to-day operational use of the vehicle.

**Some Class Vehicles will “pass” the oil consumption test (No repair necessary) even though a “Low Oil Level” indicator/message” displayed between required engine oil services.**

**It is important that the engine oil level stays and is maintained above the minimum (“Low Oil Level” indicator/message is not displaying).**


Refer to the Procedure section for information on diagnosing the oil consumption issue.

## PROCEDURE

**Engine serial number verification (Included in the engine diagnosis labor operations):**

Verify the proper engine serial number is installed in the vehicle before starting any diagnosis or repairs.

**NOTE:** Only vehicles equipped with the original engines (engine serial number matching the serial number in PuMA), or with BMW Replacement Engine (purchased from BMW PDCs, and replaced under Warranty, or customer pay) are eligible to participate in this Class Action Settlement.



The engine serial number is located at the lower front right corner of the engine block.

Engine serial number (1)

Engine type Number (2)

**UPDATE !**

Regardless if you are requesting an engine repair or an engine replacement each TSARA case requires a picture of the engine serial number.

**UPDATE !**

To reduce processing time also state the engine serial number in the case comments before submitting.

**UPDATE !**

All engine serial numbers will be verified at the Warranty Part Return Center.

**IMPORTANT NOTE:**

Only a Shop Foreman is authorized to approve the final results of N63 Class Action diagnosis and repair.

The complete N63 Oil Consumption Checklist, or N63 Smoke Checklist, along with the relevant photographs have to be submitted via a TSARA TeileClearing Hotline case titled N63 Class\_Action.

**IMPORTANT NOTE:**

Do not attach pictures which are not relevant, vague, not clear, and which are not providing a clear evidence/source of an observed major leak. A TC case with an excessive number of poor quality pictures requires more time to process, resulting in a delayed response.

Please specify in the case details the picture description. Renaming the picture is not necessary

For example:

Front engine cover = X1234.jpg

Turbo inspection = X5678.jpg

The TSARA TeileClearing “N63 Class Action” process has started on November 1st, 2018. Weekend and holiday submissions are required, and they must wait for a response on the following business day before starting any repairs.

The AutoStamp submission process has been deactivated as of 11/01/2018.

It is the Shop Forman’s responsibility to provide a complete and accurate diagnosis documentation, as described below.

Including follow-up/updates to the original TSARA TeileClearing case prior to performing any additional related work that is found needed during the repair process.

Incomplete, missing, or misleading “N63 Class Settlement” engine diagnosis and repairs will result in debiting of the Warranty claim.

**IMPORTANT NOTE:**

**UPDATE !** The parts stock of the N63 Replacement engine will remain extremely limited until **September 2019**. In case, an engine replacement is required as a result of the Class Action Diagnosis, please advise the customer that such a repair will be performed at a future date, when N63 engines are available. The vehicle’s mileage for Customer’s Contribution will be taken from the date of final, 5-step diagnosis.

**UPDATE !** Refer to the section that applies to the vehicle situation.

**IMPORTANT: Do not drain and measure the engine oil. Follow the applicable instructions to use the electronic oil level measurement.**

When the customer’s complaint is “smoke from the exhaust system”, proceed to Section 1, Step 1 below. If the customer complains only about frequent engine oil top-offs, go to Step 2.

**Section 1 – Visually diagnose the vehicle for smoke from the exhaust tail pipes:**

Do not drain and measure the engine oil. Follow the applicable instructions to use the electronic oil level measurement:

1. Start the vehicle and allow it to reach to reach operating temperature, approximately 15 minutes or less. Quickly push-and-release the accelerator pedal from idle position to between 2,000 and 3,000 RPM, then immediately allow the engine to return to idle and observe the exhaust tail pipes for smoke. If the vehicle is smoking then refer to the following two attachments. If the vehicle is not smoking then proceed to step 2.

- N63 Smoke Instructions

- N63 Smoke Checklist

Note: Document all results in the “B01\_21\_18\_N63 Smoke Checklist” simultaneously while following the instructions.

**IMPORTANT:** Take a picture of a smoke emitted from the exhaust pipes during this test, and attach it to a TSARA TeileClearing Hotline case.

2. If the vehicles does not exhibit any smoke from the tailpipes then an oil consumption test will need to be started using the following attachment.

- N63 Oil Consumption Instructions (only perform steps 1 and 2 in this document until the vehicle returns for the measurement described in section 2)

**UPDATE!** **IMPORTANT: Apply tamper-proof markings to the engine oil drain plug, engine oil filter and engine oil fill cap. Ensure these have not been tampered with when the vehicle returns for the oil consumption measurement.**

### Section 2 – The vehicle has returned for the oil consumption measurement:

Measure the oil consumption. Refer to the following attachments.

- N63 OC Instructions (Resume the procedure at step 3 in this document)
- N63 Oil Consumption Checklist

Note: Document all results in the “N63 Oil Consumption Checklist” simultaneously while following the instructions.

### Section 3 – Documenting the results of the visual inspection, failed oil consumption test and or vehicle inspection steps.

1. The “N63 Oil Consumption Checklist”, or “N63 Smoke Checklist” must be completed and photographed (both pages side by side in one photo).
2. Capture photos of the failed or leaking components.
3. **UPDATE!** Document the inspection/test results in a TSARA TeileClearing Hotline case, describe in the case what repair you are requesting, submit the case and wait for a response before continuing with repairs.

**If the vehicle is not smoking or the vehicle passes the oil consumption test or the vehicle does not require any repairs then do not enter a TSARA TeileClearing Hotline case.**

### Calculating Oil Consumption by Milliliters

If the customer has driven much further than recommended then the result of the test plan and the miles driven can be determined using a calculator. The calculation below will determine the exact oil consumption level of the engine.

Calculation:

Milliliters of oil consumed ÷ miles driven = X.XXX milliliters (ml) per mile driven

**The oil consumption specification of this calculation is 1.333 milliliters (ml) per mile driven.**

For example, 1000ml ÷ 750 miles = **1.333 ml per mile**, this is the 1 liter per 750 miles specification.

If the result of the calculation is 1.333 per mile and greater then you have to continue with the diagnosis and address the customer complaint.

If the result of the calculation is less than or equal to 1.332 then the customers complaint **does not exceed** the allowable engine oil consumption specification. Take no further action.

**Example:**

900ml consumed ÷ 750 miles driven = **1.2 ml per mile** – Take no further action and release the vehicle.

**Engine Repairs and Replacements:**

Replacement engine assemblies are **NOT pre-filled** with engine oil.

**After replacing an engine with a new or remanufactured engine assembly, the engine oil level must be verified as outlined in the procedure below first, before starting the engine for the first time.**

If the replacement engine is started to determine electronically if the engine is filled with the appropriate amount of engine oil, damage to the replacement engine can occur immediately. The engine may have some residual engine oil from assembly, but this is not enough engine oil to properly lubricate the engine to measure the engine oil level electronically when it is started for the first time.

Further, the electronic engine oil measurement is only operational when the engine is running at its full operating temperature. Checking the engine oil without the engine running at operating temperature will lead to an incorrect or incomplete measurement.

After replacing the engine or making engine repairs that require the replacement or removal of the engine bearings, VANOS gears, camshafts, bed plate resealing, engine oil pump, engine oil filter housing, cylinder head, engine oil cooler or anything that interrupts the engine oil supply circuit of the engine requires a short oil pump and oil supply circuit priming procedure.

Refer to [SIB11 09 15](#) for the detailed bleeding procedure (the time to perform this procedure is included in the applicable special repair labor operations that are provided in the attachments to this Service Information bulletin).

**After engine repairs or replacement, pay attention to a proper installation of all engine ground connections. Mark the various ground connections with a small parts tag or colored tape.**

In particular, follow the recommendations from [SIB12 24 14](#) (N63: Proper Ignition Harness Installation and Ground Connections) for the ignition harness grounding. Any consequential damage to DME, alternator, or QLT sensor resulted from a loose ground (causing BSD communication faults), **is not covered** under N63 Class Settlement

**UPDATE!**

**If the engine malfunction warning is illuminated and lean mixture faults are stored in the DME:**

1. Double check all basic induction system connections, ensure no leaks are present.
2. Adaptation Procedure:
  - Disconnect the tank ventilation valve (purge valve) electrical connector and allow the engine to idle for 15 minutes. This procedure will allow the DME to readapt.
  - After 15 minutes of idling, reconnect the tank ventilation valve (purge valve) electrical connector
  - Clear the fault memory
  - Test drive the vehicle to ensure all faults do not reoccur

**UPDATE!**

**Workshop Cleanliness:**

Always ensure the high pressure fuel system parts are properly stored in a clean location. Use caps or bags to keep contamination from occurring. It is good practice to immediately cap the high pressure pumps and

store them in the upright position so that the plunger does not dry out. The appropriate caps can be found in the N63 Valve Seal Replacement Tool Kit P/N 83 30 2 408 268.

## PARTS INFORMATION

Based on the results from the inspections and testing select the appropriate parts to repair the vehicle.

**Engine replacement only if the vehicle is found smoking or the measured oil consumption is too high and failing any one of the 5 point checks.**

### IMPORTANT NOTE:

The parts stock of the N63 Replacement engine will remain extremely limited until September 2019. In case, an engine replacement is required as a result of the Class Action Diagnosis, please advise the customer that such a repair will be performed at a future date, when N63 engines are available. The vehicle's mileage for Customer's Contribution will be taken from the date of final, 5-step diagnosis.

Part Number	Description	Quantity
Refer to ETK using the vin number of the vehicle	Remanufactured engine	1
07 12 9 904 707	ISA screw with washer	1
11 42 7 634 679	Oil pipe	1

**Valve seal and engine oil separator replacement only if the vehicle is found smoking or the measured oil consumption is too high and all 5 point checks are found to be good.**

Part Number	Description	Quantity
11 34 0 054 492	Valve seal repair kit	2
11 15 8 636 540	Oil separators, set (kit with bolts)	1
11 12 7 566 281	Timing chain tensioner cover gasket	2
11 12 8 636 401	High-pressure pump profile gasket	2
11 36 7 564 346	VANOS central screws	4
11 42 7 583 220	Engine oil filter	1
13 53 7 584 315	Injector gasket ring seal	8
13 53 7 564 751	Injector decoupling element	8

**Also, if found defective (cracked, leaking), the following crankcase ventilation hoses need to be replaced:**

Part Number	Description	Quantity
11 15 7 575 640	Vent pipe	1
11 15 7 575 641	Vent pipe	1
11 15 7 646 086	Connecting line	1
11 15 7 646 087	Connecting line	1

**Also, if found leaking, turbocharger oil return pipes, return cover and gaskets.**

Part Number	Description	Quantity

11 65 7 577 016	Oil return cover	1
11 42 8 624 158	Gasket, asbestos free	2
11 42 7 577 010	Oil return pipe, cylinder 1-4	1
11 42 7 577 011	Oil return pipe, cylinder 5-8	1

**Turbo replacement only if found leaking.**

Part Number	Description	Quantity
11 65 7 646 092	Turbocharger	2

**Rear cover and rear crankshaft seal replacement only if found leaking.**

Part Number	Description	Quantity
11 14 2 446 298	Updated, end cover, rear kit	1
Refer to ETK	Cap with rear seal (rear crankshaft seal)	1

Refer to the ETK and the applicable repair instructions for one-time use fasteners and/or component information regarding additional, in-conjunction parts/kits or replacement screws, gaskets, seals and clamps that need to be installed and claimed.

**All repairs (as needed):****Bulk Materials - Sublet**

Part Number	Description	Quantity
83 21 2 466 454 Or 83 21 2 365 950	5W30 BMW Engine Oil 1 liter Or 0W-30 BMW engine oil 1 liter	Up to 9.6 liters
		(E72, F04 8.5)
82 14 1 467 704	Antifreeze	See Sublet
		(1 Gallon)
83 29 0 429 576	Hydraulic fluid CHF 11 S (F01, F02, F04, F07)	See Sublet
		(up to 1)

1 Gallon Antifreeze = 2 Gallons at a 50/50 mixture solution.

**WARRANTY INFORMATION**

The engine diagnosis and repair procedures outlined in this bulletin are covered under the terms of this Class Action Settlement (as noted below) for first 10 years or 120,000 miles, whichever occurs first, as determined by the original in-service date.

**However, in no event less than 1 year or 12,000 miles from the Effective Day of the settlement date (repair dates up to and including 10/11/2019, coverage is 11 years or 132,000 miles, whichever occurs first).**

Should an eligible Class Member return for another oil consumption-related issue with their Class Vehicle, qualifying diagnosis and repairs (full or Contribution Matrix as applicable) are covered by the remaining portion of the coverage period above that applies.

Parts replaced to perform “settlement-related repairs” that fail for “non- oil consumption-related issues” are covered under the BMW Limited Parts Warranty for 24 month without mileage limitation.

#### **Engine diagnosis:**

A. Up to three (3) engine oil consumption (two-part setup/test) diagnosis procedures may be eligible to be performed or upon verification of blue smoke from the exhaust pipes reimbursement is at 100%.

Based on the results of the engine diagnosis, when applicable:

B. Eligible “**engine repairs**” are reimbursed at 100%.

C. Eligible “**complete engine assembly replacements**” (including supplemental/in conjunction repairs) are reimbursed according to the customer contribution percentage matrix.

<b>Engine Assembly Replacement - Customer Contribution Percentage Matrix (Item C)</b>			
<b>Odometer Miles*</b>		<b>Customer's Contribution</b>	<b>BMW's Contribution</b>
Up to	50,000	0% (None)	100%
50,001	60,000	5%	95%
60,001	70,000	15%	85%
70,001	80,000	30%	70%
80,001	90,000	45%	55%
90,001	100,000	60%	40%
100,001	110,000	75%	25%
110,001	120,000	90%	10%
120,001	And higher	100%	0% (None)

#### **Applying the Contribution Matrix\***

When an eligible vehicle returns to a BMW authorized center for an oil consumption issue and the vehicle's engine either:

- Fails the oil consumption measure test (part two); or there is
- Visible blue smoke from the exhaust pipes; **and** the
- Vehicle's engine fails the one of the other required inspections (5 point checks); then



Use the vehicle's "odometer miles" when the **above occurred** to determine the customer's contribution. This documented odometer mileage is to be also used when the **qualifying engine replacement** is delayed due to awaiting parts from BMW.

Please ensure to document this information on the repair order and in the claim comments.

### **BMW Certified Pre-owned (CPO) Vehicles**

Qualifying N63 engine "replacements" are covered under the terms of the applicable CPO coverage.

Should the CPO covered component fail again, this component is covered by the remaining portion of the CPO coverage period.

### **Consequential Repairs**

When additional work and/or parts are required as a "direct result" of performing an eligible repair that is outlined in this Service Information bulletin, claim these items under the applicable defect code, including prior TeileClearing (TC) approval (when required) together with the corresponding labor operations listed in the AIR.

Please explain the reason for this consequential repair work (the why and what) on the repair order and in the claim comments section.

### **Overlapping Labor Procedure – Other Repairs**

If invoicing the AIR flat rate labor operation codes for other repair work results in overlapping labor, for those flat rate labor operations that are affected, you are able to:

- Replace the stated AIR "FRU allowance" with a "reduced FRU value" to eliminate the overlapping labor.

For help in identifying the overlapping labor, please refer to the AIR FRU Plausibility Check (Overlapping Labor Tool) that is located in the AIR Client.

Eligible other repair work being claimed under a different defect code will require separate punch times.

On the repair order and in the claim comment section, please identify and itemize those labor operations being claimed with a "reduced FRU value."

### **Attachments for Defect Code and Labor Operation information for Repair Invoicing and Claim Submission**

For oil consumption diagnosis and repair-related defect codes and labor operations, see the attachment:

- B01 21 18 N63 Oil Consumption (OC) Wty Info 03\_07\_19; or

For visible blue smoke diagnosis and repair-related defect codes and labor operations, see the attachment:

- B01 21 18 N63 Blue Smoke (BS) Wty Info 03\_07\_19; and

**Refer to AIR for the corresponding flat rate unit (FRU) allowances.**

## **ATTACHMENTS**

View PDF attachment [B01 21 18 N63 Blue Smoke \(BS\) Wty Info 03 07 19](#).

View PDF attachment [B01 21 18 N63 Oil Consumption \(OC\) Wty Info 03 07 19](#).

View PDF attachment [B01 21 18 N63 Blue Smoke Checklist 06 21 19](#).

View PDF attachment [B01 21 18 N63 Oil Consumption Checklist 06 21 19](#).

View PDF attachment [B01 21 18 N63 Oil Consumption Instructions 06 21 19](#).

View PDF attachment [B01 21 18 N63 Smoke Instructions 06 21 19.](#)

[ Copyright ©2019 BMW of North America, Inc. ]

**SI B01 21 18: Engine has Visible (Blue) Smoke from the Exhaust Tailpipes**

<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 66 287	Refer to AIR	Visual inspection for the exhaust tailpipes for blue smoke (includes running engine to operating temperature) (Main work)
Or		
00 66 995	Refer to AIR	Visual inspection for the exhaust tailpipes for blue smoke (includes running engine to operating temperature) (Plus work)

And:

<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 66 997	Refer to AIR	Remove and install clean air pipes, underbody paneling/visual inspection of the: <ul style="list-style-type: none"> <li>• exhaust turbochargers and both turbochargers/oil return lines and return line cover; and the</li> <li>• front cover, upper oil pan; and the</li> <li>• engine backside (Transmission) for oil leakage; and</li> <li>• borescope inspect the engine valley as necessary</li> </ul>
Or:		
00 66 998	Refer to AIR	Remove and install clean air pipes, underbody paneling/ visual inspection of the: <ul style="list-style-type: none"> <li>• exhaust turbochargers and both turbochargers/oil return lines and return line cover; and the</li> <li>• front cover, upper oil pan; and the</li> <li>• engine backside (Transmission) for oil leakage;</li> <li>• perform the timing chain test plan; and</li> <li>• borescope inspect the engine valley as necessary</li> </ul>
Or:		
00 66 999	Refer to AIR	Remove and install clean air pipes, underbody paneling/ visual inspection of: <ul style="list-style-type: none"> <li>• exhaust turbocharger both turbochargers/oil return lines and return line cover;</li> <li>• front cover, upper oil pan;</li> <li>• engine backside (Transmission) for oil leakage;</li> <li>• perform the timing chain test plan; and</li> <li>• cylinder compression test; and</li> <li>• borescope inspect the engine valley as necessary</li> </ul>
And:		
00 58 677	1 FRU	TeileClearing, lump-sum fee (B01 01 07)

## SI B01 21 18: Engine has Visible (Blue) Smoke from the Exhaust Tailpipes

<b>Engine Fails One of the Inspections/Test Procedures - Engine Replacement is Necessary</b>
--

The owner “**approves**” the repair, however, the qualifying N63 engine replacement repair **is pending** due to **awaiting parts** to become available from BMW, then claim the applicable diagnosis labor operations above and submit using the Defect Code below.

<b>Defect Code:</b>	<b>1100901700</b>	<b>E7x F0x F1x N63 Measured engine oil consumption excessive, diagnosis, engine replacement pending</b>
---------------------	-------------------	---

Or:

If the vehicle owner “**rejects**” a N63 engine replacement procedure that qualifies, then claim the applicable diagnosis labor operations above and submit using the Defect Code below.

<b>Defect Code:</b>	<b>1100901800</b>	<b>E7x F0x F1x N63 Engine diagnosis, engine replacement rejected by customer</b>
---------------------	-------------------	--

Or:

The qualifying engine replacement procedure **can be performed** during the current workshop visit, then claim and submit for the applicable diagnosis above and the N63 engine replacement using the Defect Code below that applies

<b>Defect Code:</b>	<b>1100901100</b>	<b>E7x F0x F1x N63 Additional diagnosis leads to engine replacement</b>
Or:		
<b>Defect Code:</b>	<b>1100901200</b>	<b>E7x F0x F1x N63 Additional diagnosis leads to engine and turbocharger replacement</b>
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 67 500	Refer to AIR	Replace the engine (includes remove and install the old turbochargers or replace both turbochargers)

Or, if the vehicles **does not fail** one of the above inspections/test procedures, then:

**SI B01 21 18: Engine has Visible (Blue) Smoke from the Exhaust Tailpipes**

**Blue Smoke/Engine Does Not Fail One of the Inspections/Test Procedures - Engine Replacement is Not Necessary**

<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 66 287	Refer to AIR	Visual inspection for the exhaust tailpipes for blue smoke (includes running engine to operating temperature) (Main work)
Or		
00 66 995	Refer to AIR	Visual inspection for the exhaust tailpipes for blue smoke (includes running engine to operating temperature) (Plus work)
And:		
00 66 999	Refer to AIR	Remove and install clean air pipes, underbody paneling/ visual inspection of: <ul style="list-style-type: none"> <li>• exhaust turbocharger both turbochargers/oil return lines and return line cover;</li> <li>• front cover, upper oil pan;</li> <li>• engine backside (Transmission) for oil leakage;</li> <li>• perform the timing chain test plan; and</li> <li>• cylinder compression test; and</li> <li>• borescope inspect the engine valley as necessary</li> </ul>
And:		
00 58 677	1 FRU	TeileClearing, lump-sum fee (B01 01 07)

And, with the applicable labor above together with the engine repair performed:

<b>Defect Code:</b>	<b>1100900900</b>	<b>E7x F0x F1x N63 Additional diagnosis leads to engine repairs (valve seals, cylinder head cover oil separators)</b>
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 67 501	Refer to AIR	Perform additional diagnosis, replace the: <ul style="list-style-type: none"> <li>• valve stem seals; and the</li> <li>• cylinder head covers oil separators</li> </ul>

Or, **with** turbocharger-related repairs

<b>Defect Code:</b>	<b>1100901000</b>	<b>E7x F0x F1x N63 Additional diagnosis leads to engine repairs (valve seals, cylinder head cover oil separators, turbochargers)</b>
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 67 502	Refer to AIR	Perform additional diagnosis, replace the: <ul style="list-style-type: none"> <li>• valve stem seals;</li> <li>• cylinder head cover oil separators; and</li> <li>• replace both turbochargers and/or the oil return line seals and return line cover</li> </ul>

Or:

**SI B01 21 18: Engine has Visible (Blue) Smoke from the Exhaust Tailpipes**

<b>Defect Code:</b>	<b>1100902200</b>	<b>E7x F0x F1x N63 Additional diagnosis, replace valve seals, cylinder head covers, turbos, repair oil leaks</b>
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 67 688	Refer to AIR	Perform additional diagnosis, replace the <ul style="list-style-type: none"> <li>• valve stem seals;</li> <li>• cylinder head cover oil separators;</li> <li>• rear crankshaft and rear engine cover seals;</li> <li>• lower oil pan gasket; and</li> <li>• replace both turbochargers; and/or the oil return line seals and return line cover</li> </ul>
Or:		
00 67 689	Refer to AIR	Perform additional diagnosis, replace the <ul style="list-style-type: none"> <li>• valve stem seals;</li> <li>• cylinder head cover oil separators;</li> <li>• rear crankshaft and rear engine cover seals; and</li> <li>• replace both turbochargers; and/or the oil return line seals and return line cover</li> </ul>
Or:		
00 67 690	Refer to AIR	Perform additional diagnosis, replace the <ul style="list-style-type: none"> <li>• valve stem seals;</li> <li>• cylinder head cover oil separators; and the</li> <li>• lower oil pan gasket; and</li> <li>• replace both turbochargers; and/or the oil return line seals and return line cover</li> </ul>

Or, **without** turbocharger-related repairs

<b>Defect Code:</b>	<b>1100902100</b>	<b>E7x F0x F1x N63 Additional diagnosis, replace valve seals, cylinder. head covers, repair leaks</b>
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 67 691	Refer to AIR	Perform additional diagnosis, replace the <ul style="list-style-type: none"> <li>• valve stem seals; and the</li> <li>• cylinder head cover oil separators; and the</li> <li>• rear crankshaft and rear engine cover seals;</li> <li>• lower oil pan gasket</li> </ul>
Or:		
00 67 692	Refer to AIR	Perform additional diagnosis, replace the <ul style="list-style-type: none"> <li>• valve stem seals; and the</li> <li>• cylinder head cover oil separators; and the</li> <li>• rear crankshaft and rear engine cover seals</li> </ul>
Or:		
00 67 693	Refer to AIR	Perform additional diagnosis, replace the <ul style="list-style-type: none"> <li>• valve stem seals; and the</li> <li>• cylinder head cover oil separators; and the</li> <li>• lower oil pan gasket</li> </ul>

**SI B01 21 18: Engine has Visible (Blue) Smoke from the Exhaust Tailpipes**

And, applicable:

**Sublet – Materials**

<b>Sublet Code 4</b>	See sublet reimbursement calculation below	Reimbursement for used quantities of required operating fluids, including engine oil only when it is not claimed under the BMW Maintenance Program (applicable BMW part numbers). Please do not use these part numbers for claim submission.
----------------------	--	--

Sublet calculation:

Reimbursement for used quantities of required operating fluids (applicable BMW part numbers) at dealer net plus handling.

Enter the material cost in sublet and itemize the amount in the claim comment section.

**SI B01 21 18: Engine Oil Consumption (OC) Set up and Measure (No Visible Smoke from Tailpipes)****Set up oil consumption tests for 1, 2, or 3 as applicable (Close the RO and submit)**

<b>Defect Code:</b>	<b>1100900100</b>	<b>E7x F0x F1x N63 Set up engine oil consumption test</b>
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 66 283	Refer to AIR	Engine oil consumption test set-up (includes connecting an approved battery charger/power supply and performing a vehicle test, use ISTA/D Motor Oil Quantity Test Plan, mark the oil pan drain plug and the filter cap) (Main work)
00 66 979	Refer to AIR	Engine oil consumption test set-up (includes connecting an approved battery charger/power supply and performing a vehicle test, use ISTA/D Motor Oil Quantity Test Plan, mark the oil pan drain plug and the filter cap) (Plus work)

After the first set up for oil consumption test (DC 1100900100 and applicable labor on a prior separate repair order):

**Measure engine oil consumption (New Repair Order) - Passes the first time**

<b>Defect Code:</b>	<b>1100900200</b>	<b>E7x F0x F1x N63 Measure engine oil consumption, no oil consumption found (1st completed test)</b>
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 66 284	Refer to AIR	Vehicle returns: perform a vehicle test (includes connecting an approved battery charger/power supply and performing a vehicle test, use ISTA/D Motor Oil Quantity Test Plan, mark the oil pan drain plug and the filter cap) (Main work)
Or:		
00 66 983	Refer to AIR	Vehicle returns: perform a vehicle test (includes connecting an approved battery charger/power supply and performing a vehicle test, use ISTA/D Motor Oil Quantity Test Plan, mark the oil pan drain plug and the filter cap) (Plus work)

And again, after the second set up for oil consumption test (DC 1100900100 and applicable labor on a prior separate repair order):



**SI B01 21 18: Engine Oil Consumption (OC) Set up and Measure (No Visible Smoke from Tailpipes)**

**Measure engine oil consumption (New Repair Order) - Passes the second time**

<b>Defect Code:</b>	<b>1100900300</b>	<b>E7x F0x F1x N63 Measure engine oil consumption, no oil consumption found (2nd completed test)</b>
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 66 285	Refer to AIR	Vehicle returns: perform a vehicle test (includes connecting an approved battery charger/power supply and performing a vehicle test, use ISTA/D Motor Oil Quantity Test Plan, mark the oil pan drain plug and the filter cap) (Main work)
Or:		
00 66 985	Refer to AIR	Vehicle returns: perform a vehicle test (includes connecting an approved battery charger/power supply and performing a vehicle test, use ISTA/D Motor Oil Quantity Test Plan, mark the oil pan drain plug and the filter cap) (Plus work)

And again, after the third set up for oil consumption test (DC 1100900100 and applicable labor on a prior separate repair order):

**Measure engine oil consumption (New Repair Order) - Passes the third time**

<b>Defect Code:</b>	<b>1100900400</b>	<b>E7x F0x F1x N63 Measure engine oil consumption, no oil consumption found (3rd completed test)</b>
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 66 286	Refer to AIR	Vehicle returns: perform a vehicle test (includes connecting an approved battery charger/power supply and performing a vehicle test, use ISTA/D Motor Oil Quantity Test Plan, mark the oil pan drain plug and the filter cap) (Main work)
Or:		
00 66 987	Refer to AIR	Vehicle returns: perform a vehicle test (includes connecting an approved battery charger/power supply and performing a vehicle test, use ISTA/D Motor Oil Quantity Test Plan, mark the oil pan drain plug and the filter cap) (Plus work)

Or, when the:

<b>Measure Engine Oil Consumption Does not Pass/Fails</b>
---

**New Repair Order for 1, 2 or 3 as applicable**

<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 66 284; 00 66 285; or 00 66 286	Refer to AIR	Vehicle returns: perform a vehicle test (includes connecting an approved battery charger/power supply and performing a vehicle test, use ISTA/D Motor Oil Quantity Test Plan, mark the oil pan drain plug and the filter cap) (Main work)

**SI B01 21 18: Engine Oil Consumption (OC) Set up and Measure (No Visible Smoke from Tailpipes)**

Or:		
00 66 983; 00 66 985; or 00 66 987	Refer to AIR	Vehicle returns: perform a vehicle test (includes connecting an approved battery charger/power supply and performing a vehicle test, use ISTA/D Motor Oil Quantity Test Plan, mark the oil pan drain plug and the filter cap) (Plus work)

Then, work through the following diagnosis as needed:

<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 66 989	Refer to AIR	Remove and install clean air pipes, underbody paneling/visual inspection of the: <ul style="list-style-type: none"> <li>• exhaust turbochargers and both turbochargers/oil return lines and return line cover; and the</li> <li>• front cover, upper oil pan; and the</li> <li>• engine backside (Transmission) for oil leakage; and</li> <li>• borescope inspect the engine valley as necessary</li> </ul>
Or:		
00 66 990	Refer to AIR	Remove and install clean air pipes, underbody paneling/ visual inspection of the: <ul style="list-style-type: none"> <li>• exhaust turbochargers and both turbochargers/oil return lines and return line cover; and the</li> <li>• front cover, upper oil pan; and the</li> <li>• engine backside (Transmission) for oil leakage;</li> <li>• perform the timing chain test plan; and</li> <li>• borescope inspect the engine valley as necessary</li> </ul>
Or:		
00 66 991	Refer to AIR	Remove and install clean air pipes, underbody paneling/ visual inspection of: <ul style="list-style-type: none"> <li>• exhaust turbocharger both turbochargers/oil return lines and return line cover;</li> <li>• front cover, upper oil pan;</li> <li>• engine backside (Transmission) for oil leakage;</li> <li>• perform the timing chain test plan; and</li> <li>• cylinder compression test; and</li> <li>• borescope inspect the engine valley as necessary</li> </ul>
And:		
00 58 677	1 FRU	TeileClearing, lump-sum fee (SI B01 01 07)

**SI B01 21 18: Engine Oil Consumption (OC) Set up and Measure (No Visible Smoke from Tailpipes)**

<b>Engine Fails One of the Inspections/Test Procedures - Engine Replacement is Necessary</b>
--

The owner “**approves**” the repair, however, the qualifying N63 engine replacement repair **is pending** due to **awaiting parts** to become available from BMW, then claim the applicable diagnosis labor operations above and submit using the Defect Code below.

<b>Defect Code:</b>	<b>1100901600</b>	<b>E7x F0x F1x N63 Measured engine oil consumption excessive, diagnosis, engine replacement pending</b>
---------------------	-------------------	---

Or:

If the vehicle owner “**rejects**” a N63 engine replacement procedure that qualifies, then claim the applicable diagnosis labor operations above and submit using the Defect Code below.

<b>Defect Code:</b>	<b>1100901800</b>	<b>E7x F0x F1x N63 Engine diagnosis, engine replacement rejected by customer</b>
---------------------	-------------------	--

Or:

The qualifying engine replacement procedure **can be performed** during the current workshop visit, then claim and submit for the applicable diagnosis above and the N63 engine replacement using the Defect Code below that applies

<b>Defect Code:</b>	<b>1100900700</b>	<b>E7x F0x F1x N63 Measured engine oil consumption excessive, diagnosis and replace engine</b>
Or:		
<b>Defect Code:</b>	<b>1100900800</b>	<b>E7x F0x F1x N63 Measured engine oil consumption excessive, diagnosis, replace engine and both turbochargers</b>
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 66 992	Refer to AIR	Replace the engine (includes remove and install the old turbochargers or replacing both turbochargers)

Or, if the vehicles **does not fail** one of the above inspections/test procedures, then:

**SI B01 21 18: Engine Oil Consumption (OC) Set up and Measure (No Visible Smoke from Tailpipes)**

**Measure Engine Oil Consumption Does not Pass but the Engine Does Not Fail One of the Inspections/Test Procedures - Engine Replacement is Not Necessary**

**Measure Engine Oil Consumption 1, 2 or 3 and Diagnosis**

<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 66 284; 00 66 285; or 00 66 286	Refer to AIR	Vehicle returns: perform a vehicle test (includes connecting an approved battery charger/power supply and performing a vehicle test, drain and measure the engine oil, mark the oil pan drain plug and the filter cap) (Main work)
Or:		
00 66 983; 00 66 985; or 00 66 987	Refer to AIR	Vehicle returns: perform a vehicle test (includes connecting an approved battery charger/power supply and performing a vehicle test, drain and measure the engine oil, mark the oil pan drain plug and the filter cap) (Plus work)
And:		
00 66 991	Refer to AIR	Remove and install clean air pipes, underbody paneling/ visual inspection of: <ul style="list-style-type: none"> <li>• exhaust turbocharger both turbochargers/oil return lines and return line cover;</li> <li>• front cover, upper oil pan;</li> <li>• engine backside (Transmission) for oil leakage;</li> <li>• perform the timing chain test plan; and</li> <li>• cylinder compression test; and</li> <li>• borescope inspect the engine valley as necessary</li> </ul>
And:		
00 58 677	1 FRU	TeileClearing, lump-sum fee (B01 01 07)

And, with the applicable labor above together with the engine repair performed:

<b>Defect Code:</b>	<b>1100900500</b>	<b>E7x F0x F1x N63 Measured engine oil consumption excessive, diagnosis, replace engine valve stem seals and replace cylinder head cover oil separators</b>
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 66 993	Refer to AIR	Perform additional diagnosis, replace the: <ul style="list-style-type: none"> <li>• valve stem seals; and the</li> <li>• cylinder head covers oil separators</li> </ul>

Or, **with** turbocharger-related repairs

**SI B01 21 18: Engine Oil Consumption (OC) Set up and Measure (No Visible Smoke from Tailpipes)**

<b>Defect Code:</b>	<b>1100900600</b>	<b>E7x F0x F1x N63 Measured engine oil consumption excessive, diagnosis, replace the engine valve stem seals, replace cylinder head cover oil separators and replace both turbochargers</b>
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 66 994	Refer to AIR	Perform additional diagnosis, replace the: <ul style="list-style-type: none"> <li>• valve stem seals;</li> <li>• cylinder head cover oil separators; and</li> <li>• replace both turbochargers and/or the oil return line seals and return line cover</li> </ul>

Or:

<b>Defect Code:</b>	<b>1100902000</b>	<b>E7x F0x F1x N63 Excessive oil consumption, diagnose engine, replace valve seals, cylinder head cover, turbos, repair oil leaks</b>
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 67 682	Refer to AIR	Perform additional diagnosis, replace the <ul style="list-style-type: none"> <li>• valve stem seals;</li> <li>• cylinder head cover oil separators;</li> <li>• rear crankshaft and rear engine cover seals;</li> <li>• lower oil pan gasket; and</li> <li>• replace both turbochargers; and/or the oil return line seals and return line cover</li> </ul>
Or:		
00 67 683	Refer to AIR	Perform additional diagnosis, replace the <ul style="list-style-type: none"> <li>• valve stem seals;</li> <li>• cylinder head cover oil separators;</li> <li>• rear crankshaft and rear engine cover seals; and</li> <li>• replace both turbochargers; and/or the oil return line seals and return line cover</li> </ul>
Or:		
00 67 684	Refer to AIR	Perform additional diagnosis, replace the <ul style="list-style-type: none"> <li>• valve stem seals;</li> <li>• cylinder head cover oil separators; and the</li> <li>• lower oil pan gasket; and</li> <li>• replace both turbochargers; and/or the oil return line seals and return line cover</li> </ul>

Or, **without** turbocharger-related repairs

**SI B01 21 18: Engine Oil Consumption (OC) Set up and Measure (No Visible Smoke from Tailpipes)**

<b>Defect Code:</b>	<b>1100901900</b>	<b>E7x F0x F1x N63 Excessive oil consumption, diagnose engine, replace valve seals, cylinder head cover, repair leaks</b>
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 67 685	Refer to AIR	Perform additional diagnosis, replace the <ul style="list-style-type: none"> <li>• valve stem seals; and the</li> <li>• cylinder head cover oil separators; and the</li> <li>• rear crankshaft and rear engine cover seals;</li> <li>• lower oil pan gasket</li> </ul>
Or:		
00 67 686	Refer to AIR	Perform additional diagnosis, replace the <ul style="list-style-type: none"> <li>• valve stem seals; and the</li> <li>• cylinder head cover oil separators; and the</li> <li>• rear crankshaft and rear engine cover seals</li> </ul>
Or:		
00 67 687	Refer to AIR	Perform additional diagnosis, replace the <ul style="list-style-type: none"> <li>• valve stem seals; and the</li> <li>• cylinder head cover oil separators; and the</li> <li>• lower oil pan gasket</li> </ul>

And, applicable:

**Sublet – Materials**

<b>Sublet Code 4</b>	See sublet reimbursement calculation below	Reimbursement for used quantities of required operating fluids, including engine oil only when it is not claimed under the BMW Maintenance Program (applicable BMW part numbers). Please do not use these part numbers for claim submission.
----------------------	--	--

Sublet calculation:

Reimbursement for used quantities of required operating fluids (applicable BMW part numbers) at dealer net plus handling.

Enter the material cost in sublet and itemize the amount in the claim comment section.

## N63 ENGINE BLUE SMOKE CHECKLIST

Date:		<b>Record the results of the vehicle's engine inspection and measurements below.</b>
Dealer Number:	VIN (7)	
RO number	Engine Serial Number	

**Use this checklist for "blue smoke" complaints only.**

Concern is "blue smoke" for tailpipes.	Visual inspection for the exhaust tailpipes for blue smoke	Labor operations	00 66 287 (995)
--	--	------------------	-----------------

1. Is there blue smoke emitting from the tailpipes (Running engine to operating temperature) as described in B01 21 18? YES or No (No further repair)

**Five Point Check and Results:** Only provide the answers to the applicable questions in steps 2 through 9, unless otherwise directed.

2. Is the front engine cover leaking?	YES or NO
3. Is the upper engine oil pan leaking?	YES or NO
4. Is the engine oil leaking from the lower bell housing area?	YES or NO
5. Only if 2 or 3 or 4 are answered with "YES". Use the bore scope (10). Is the oil return cover or oil return line gaskets leaking oil? Provide photo in the case using the borescope regardless if it is found wet or dry.	YES or NO If <b>YES</b> , do not replace the engine for oil leakage and proceed to step 6.
6. Are the turbochargers leaking engine oil?	YES or NO
7. Did the vehicle fail the timing chain test plan?	YES or NO
8. Was a cylinder compression test performed?	YES or NO

**Note:** The cylinder compression test should be performed after the engine has reached operating temperature. When performing this test, count the rotations of the engine crankshaft and apply the same rotations to each additional cylinder of the compression test. The industry standard is four (4) rotations per cylinder.

9. Test Plan Compression Test Results: Did the cylinders exceed the specification	YES or NO
--	-----------

When comparing the values of all cylinders, the compression results should not vary by more than 2.5 bar or 36.25 PSI. If the difference is greater than 2.5 bar or 36.25 PSI, then the complete engine will need to be replaced.


If the test plan was not used, then document the compression test results by cylinder in the table below

1.	2.	3.	4.
5.	6.	7.	8.

**Vehicles that FAIL any of tests:** Take a photo of only page 1 and submit a case with the other required pictures for authorization to the TSARA TeileClearing Hotline and wait for a response. Weekend and holiday submissions must wait for a response on the following business day before starting any repairs.

**Vehicles that PASS all of the tests:** Do not require any engine repairs and do not need a TSARA TeileClearing authorization.

## **N63 ENGINE BLUE SMOKE CHECKLIST**

	<b>The diagnosis scenarios are listed below, check the one that best describes the diagnosis result.</b>	<b>Recommended Repair Procedures</b>	<b>Labor Op Main (Plus) Code</b>	<b>Defect Code</b>
	<b>Vehicle fails engine oil consumption measure test/inspections</b>		Plus (see above):	
	Engine oil leakage (2 and/or 3) found	Replace the engine		<b>1100901100</b>
	Engine oil leakage (2 and/or 3) and turbochargers found leaking oil (6)	Replace the engine and turbochargers	00 66 997 & 00 67 500	<b>1100901200</b>
	Only the timing chain test fails (7)	Replace engine		<b>1100901100</b>
	Timing chain test fails (7), and turbochargers (5) are leaking oil.	Replace engine and turbochargers	00 66 998 & 00 67 500	<b>1100901200</b>
	Only the cylinder compression test fails (8)	Replace engine		<b>1100901100</b>
	Cylinder compression test (8) fails and turbochargers (5) are leaking oil	Replace engine and turbochargers	00 66 999 & 00 67 500	<b>1100901200</b>
	Replacement engine is not available, claim applicable diagnosis labor operations with this defect code		See B01 21 18 and above	<b>1100901700</b>
	Customer rejects replacement engine, claim applicable diagnosis labor operations with this defect code		See B01 21 18 and above	<b>1100901800</b>
	<b>Steps 2, 3, 7 and 9 – OK, engine replacement is not necessary: performed additional diagnosis and found:</b>			
	All other items ok	(A) Replace the valve stem seals and cylinder head covers oil separators	00 66 999 & 00 67 501	<b>1100900900</b>
	Turbos and/or lines (6) leaking	With (A), replace both turbochargers and/or the oil return line seals/return line cover seals	00 66 999 & 00 67 502	<b>1100901000</b>
	Rear oil leak (4), found valley dry (10) and the lower oil pan and turbos and/or lines (6) leaking	With (A), replace rear crankshaft and rear engine cover seals; lower oil pan gasket; replace both turbochargers; and/or the oil return line seals/return line cover seals	00 66 999 & 00 67 688	<b>1100902200</b>
	Found Step (10) ok, found rear oil leak (4), and turbos and/or lines (6) leaking	With (A) replace; rear crankshaft and rear engine cover seals; replace both turbochargers; and/or the oil return line seals/return line cover seals	00 66 999 & 00 67 689	
	Found Step (4 and 10) ok, found the lower oil pan and turbos and/or lines (6) leaking	With (A) replace the lower oil pan gasket; replace both turbochargers; and/or the oil return line seals/return line cover seals	00 66 999 & 00 67 690	
	Rear oil leak (4), found valley dry (10) and a lower oil pan leak	With (A). replace the rear crankshaft and rear engine cover seals and lower oil pan gasket	00 66 999 & 00 67 691	<b>1100902100</b>
	Found Step (10) ok, found rear oil leak (4)	With (A) replace the rear crankshaft and rear engine cover seals	00 66 999 & 00 67 692	
	Found Step (4 and 10) ok, found lower oil pan leak	With (A) replace the lower oil pan gasket	00 66 999 & 00 67 683	

Retain copy of this checklist (both pages) in the vehicle file. Provide copy of page 2 to your booker/warranty admin for claims processing.



## N63 ENGINE OIL CONSUMPTION CHECKLIST

Date:		<b>Record the results of the vehicle's engine inspection and measurements below.</b>  <b>Use this checklist for "oil consumption" complaints only.</b>
Dealer Number:	VIN (7)	
RO number	Engine Serial Number	

	Concern is "oil consumption."	Perform Consumption Test	Labor Operations:	00 66 284 (983); or 00 66 285 (985); or 00 66 286 (987)
--	-------------------------------	--------------------------	-------------------	---

1. Was an engine oil consumption test started and measured (Completed)? YES or No (No further repair) If yes, what was the level of engine oil consumption? _____ Did the vehicle fail the oil consumption test? YES or NO (If yes, proceed to the five point check)
--


**Five Point Check and Results:** Only provide the answers to the applicable questions in steps 2 through 9, unless otherwise directed.

2. Is the front engine cover leaking?	YES or NO		
3. Is the upper engine oil pan leaking?	YES or NO		
4. Is the engine oil leaking from the lower bell housing area?	YES or NO		
5. Only if 2, 3 and/or 4 are answered with "YES," then use the borescope: Is the oil return cover and/or oil return line gaskets leaking (10) oil? Provide photo in the case using the borescope regardless if it is found wet or dry.	YES or NO  <b>If <u>YES</u>, do not replace the engine for oil leakage, proceed to step 6.</b>		
6. Are the turbochargers leaking engine oil?	YES or NO		
7. Did the vehicle fail the timing chain test plan?	YES or NO		
8. Was a cylinder compression test performed?	YES or NO		
<b>Note:</b> The cylinder compression test should be performed after the engine has reached operating temperature. When performing this test, count the rotations of the engine crankshaft and apply the same rotations to each additional cylinder of the compression test. The industry standard is four (4) rotations per cylinder.			
9. Test Plan Compression Test Results: Did the cylinders exceed the specification	YES or NO		
When comparing the values of all cylinders, the compression results should not vary by more than 2.5 bar or 36.25 PSI. If the difference is greater than 2.5 bar or 36.25 PSI, then the complete engine will need to be replaced.			
If the test plan was not used, then document the compression test results by cylinder in the table below			
1.	2.	3.	4.
5.	6.	7.	8.

**Vehicles that FAIL the oil consumption test:** Take a photo of only page 1 and submit a case with the other required pictures for authorization to the TSARA TeileClearing Hotline and wait for a response. Weekend and holiday submissions must wait for a response on the following business day before starting any repairs.

**Vehicles that PASS the oil consumption test:** Do not require any engine repairs and do not need a TSARA TeileClearing authorization.

## N63 ENGINE OIL CONSUMPTION CHECKLIST

	The diagnosis scenarios are listed below, check the one that best describes the diagnosis result.	Recommended Repair Procedures	Labor Op Main (Plus) Code	Defect Code
	<b>Vehicle fails engine oil consumption measure test/inspections</b>		Plus (see above):	
	Engine oil leakage (2 and/or 3) found	Replace the engine		<b>1100900700</b>
	Engine oil leakage (2 and/or 3) and turbochargers found leaking oil (6)	Replace the engine and turbochargers	00 66 989 & 00 66 992	<b>1100900800</b>
	Only the timing chain test fails (7)	Replace engine		<b>1100900700</b>
	Timing chain test fails (7), and turbochargers (5) are leaking oil	Replace engine and turbochargers	00 66 990 & 00 66 992	<b>1100900800</b>
	Only the cylinder compression test fails (8).	Replace engine		<b>1100900700</b>
	Cylinder compression test (8) fails and turbochargers (5) are leaking oil	Replace engine and turbochargers	00 66 991 & 00 66 992	<b>1100900800</b>
	Replacement engine is not available, claim applicable diagnosis labor operations with this defect code		See B01 21 18 and above	<b>1100901600</b>
	Customer rejects replacement engine, claim applicable diagnosis labor operations with this defect code		See B01 21 18 and above	<b>1100901800</b>
	<b>Steps 2, 3, 7 and 9 – OK, engine replacement is not necessary: performed additional diagnosis and found:</b>			
	All other items ok	(A) Replace the valve stem seals and cylinder head covers oil separators	00 66 991 & 00 66 993	<b>1100900500</b>
	Turbos and/or lines (6) leaking	With (A), replace both turbochargers and/or the oil return line seals/return line cover seals	00 66 991 & 00 66 994	<b>1100900600</b>
	Rear oil leak (4), found valley dry (10) and the lower oil pan and turbos and/or lines (6) leaking	With (A), replace rear crankshaft and rear engine cover seals; lower oil pan gasket; replace both turbochargers; and/or the oil return line seals/return line cover seals	00 66 991 & 00 67 682	<b>1100902000</b>
	Found Step (10) ok, found rear oil leak (4), and turbos and/or lines (6) leaking	With (A) replace; rear crankshaft and rear engine cover seals; replace both turbochargers; and/or the oil return line seals/return line cover seals	00 66 991 & 00 67 683	
	Found Step (4 and 10) ok, found the lower oil pan and turbos and/or lines (6) leaking	With (A) replace the lower oil pan gasket; replace both turbochargers; and/or the oil return line seals/return line cover seals	00 66 991 & 00 67 684	
	Rear oil leak (4), found valley dry (10) and a lower oil pan leak	With (A). replace the rear crankshaft and rear engine cover seals and lower oil pan gasket	00 66 991 & 00 67 685	<b>1100901900</b>
	Found Step (10) ok, found rear oil leak (4)	With (A) replace the rear crankshaft and rear engine cover seals	00 66 991 & 00 67 686	
	Found Step (4 and 10) ok, found lower oil pan leak	With (A) replace the lower oil pan gasket	00 66 991 & 00 67 687	

Retain copy of this checklist (both pages) in the vehicle file. Provide copy of page 2 to your booker/warranty admin for claims processing.

Changes are highlighted with  .

**1. Do not drain and measure the engine oil. Follow the applicable instructions to use the electronic oil level measurement.**

**Do not reprogram the vehicle.**

The engine oil must be measured using the electronic measurement test plan called “Motor Oil Quantity” found in ISTA/D 4.14.XX or higher.

Test Plan Path:

Select “Vehicle management”  
 Select “Powertrain”  
 Select “Engine electronics, quality control valve (MSV)”  
 Select “Engine oil”  
 Select “ABL Motor oil quantity”  
 Select “Display”

Follow the onscreen prompts. The test plan will measure the engine oil in 100 ml increments.

**Top the engine oil accordingly and perform the test plan a second time (after topping) to ensure the proper full engine oil level is reached.**

The vehicle must be driven by the customer roughly 750 to 1,000 miles or until the next low engine oil message appears (whichever comes first). After the customer returns the engine oil must be measured again using the electronic measurement test plan called “Motor Oil Quantity” found in ISTA/D 4.14.XX or higher (see test plan path above).

If the oil consumption is not greater than 1 liter per 750 miles then top the engine oil and return the vehicle to the customer.

OR

If the engine oil consumption is greater than 1 liter per 750 miles then proceed to step 2.

For additional information on oil consumption refer to B11 03 13.

**2. Inspect or measure the following 5 items in order. Note the inspection results on the attached “B01\_21\_18\_N63\_Oil\_Consumption\_Checklist.”**

- Engine front cover
- Engine upper oil pan
- Lower bell housing
- Perform the timing chain test plan
- Perform a compression test.

All components or measurements that are found to be outside the specification need to be documented with pictures and submitted for authorization via a TSARA TeileClearing Hotline case at the end of this procedure.

Vehicles that require an oil consumption test, have passed the oil consumption test or do not require any repairs do not need authorization.

**IMPORTANT!**


**If the engine is leaking engine oil, the oil leak must be an active major engine oil leak, not seepage or wetness.**

**GENERAL NOTES REGARDING ENGINE OIL LEAKS:**

“Oil Leaks” are being defined as clearly visible oil presence (like oil drops) at the engine components (e.g. area of oil pan, front cover, etc.), and in their vicinity. Also, a large visible oil stains (or oil accumulation) on the underbody panels are indication of oil leaks, causing a substantial oil capacity loss.

The black (dirt stained) “wetness” marks on the engine components, **DO NOT** qualify as oil leaks.


3. Inspect the front engine cover for engine oil leakage.



If the front timing cover is not leaking. Go to step 4.

If the front timing cover is leaking. Go to step 6.

4. Inspect the upper engine oil pan for engine oil leakage.



If the upper engine oil pan is not leaking. Go to step 5.

If the upper engine oil pan is leaking. Go to step 6.




5. Inspect the lower bell housing for engine oil leakage



The lower bell housing is not leaking. Go to step 7.

The lower bell housing is leaking. Go to step 6.

6. Turbocharger oil line diagnosis.

	<p>Remove the heat shield (1) to diagnose the engine oil leak.</p> <p>Refer to Repair Instruction 11 65 180 Removing and installing/replacing heat shield at top.</p>
	<p>The illustration shows an overview of the components found on cylinder bank 1.</p> <p>Cylinder head cover (1)</p> <p>Cylinder # 4 (2)</p> <p>Inspection location (3)</p>
	<p>The illustration shows an overview of the components found on cylinder bank 1.</p> <p>Cylinder head cover (1)</p> <p>Bank 1 post O2 sensor (2)</p> <p>Heat shield mounting hole (3)</p>



Preparing for the inspection:

Bore scope specifications:


The recommended diameter of the fiber optic cable (imager) should not be greater than 5.5 mm. The 8 mm fiber optic cable (imager) will work but it is very tight and damage may occur to the larger cable and imager.

The recommended borescope and imager can be found at [www.centersolutions.com](http://www.centersolutions.com) or refer to SI B04 19 15 for more information about the BMW Equipment Program.

Equipment Program Part Numbers:

107 - BK5000 - SNAP ON Video Scope

107- BK8000 – 5.5 mm Dual View Side Imager






The illustration shows an overview of the components frond on cylinder bank 1.

Cylinder head cover (1)




Bank 1 post O2 sensor (2)




Heat shield mounting hole (3)


Insert bore scope here (4) on an angle downward.

	<p>Approach angle of the bore scope (1) is approximately 45 degrees.</p>
	<p>After inserting the bore scope you must locate the cylinder head gasket tab. (1).</p> <p>The tab is approximately 135 mm straight down from original entry point.</p> <p>Cylinder head gasket tab (1)</p> <p>Gap in heat shields (2)</p> <p>Cylinder head (3)</p>
	<p>Feed the bore scope past the left side (1) of the cylinder head gasket tab (2) towards the vacuum reservoir (3).</p>



 <p>A bore scope view showing a metal vacuum reservoir (1) and an engine valley drain hole (2). The reservoir is on the right, and the drain hole is on the left.</p>	<p>Continue to push the bore scope towards the vacuum reservoir (1). The engine valley drain hole is location is just to the left of the vacuum reservoir (2).</p> <p>Metal vacuum reservoir shown in photo.</p> <p>As the bore scope approaches the drain hole it will become more apparent.</p>
 <p>A bore scope view showing a close-up of the engine valley drain hole (1) and the metal vacuum reservoir (2). The drain hole is on the left, and the reservoir is on the right.</p>	<p>Inspect the surrounding area of the engine valley drain hole (1).</p> <p>Engine valley drain hole (1)</p> <p>Metal vacuum reservoir (2) shown.</p> <p>This is a clean picture. No oil can be seen in the oil drain hole (1).</p> <p>The dark material at the bottom of the photo is dust and dirt. This material appears to be reflective but it is dry</p>
 <p>An illustration of a black plastic vacuum reservoir (1) with mounting screws (2) and a tab (3). A red arrow points to the right, labeled 'Front of Engine'.</p>	<p>It is possible that a black plastic vacuum reservoir (1) is installed. This illustration provides an overview of the entire component and specific points of the component.</p> <p>Reservoir (1)</p> <p>Reservoir mounting screw (2)</p> <p>Plastic vacuum reservoir tab (3)</p>

	<p>Plastic vacuum reservoir tab (1)</p> <p>Mounting screw (2)</p>
	<p>Diagnosis in the vehicle:</p> <p>It may be more difficult to position the bore scope but it will only take a few minutes more to make the diagnosis.</p> <p>Engine valley drain hole (1)</p> <p>Plastic vacuum reservoir tab (2)</p> <p>Reservoir mounting screw (3)</p>
	<p>Continue to push bore scope down ward towards the plastic vacuum reservoir tab (2).</p> <p>The bore scope needs to be moved towards the direction of the red arrow and under the tab (2) to have the best viewing angle of the engine valley drain hole (1).</p> <p>Engine valley drain hole (1)</p> <p>Plastic vacuum reservoir tab (2)</p> <p>Reservoir mounting screw (3)</p>

	<p>Once the borescope has gone under the plastic reservoir tab then the engine valley drain hole (1) and surrounding area can be clearly inspected.</p> <p>The dark material at the bottom of the photo is dust and dirt. This material appears to be reflective but it is dry.</p> <p>Engine valley drain hole (1)</p> <p>Plastic vacuum reservoir (2)</p>
---	---

**If engine oil is found in the valley area, then the root cause of the engine oil leak resides in the components on top of the engine i.e. turbocharger oil line cover, turbo charger, etc. Further basic diagnosis will be needed to find the root cause this engine oil leak. Do not remove the transmission from the vehicle. Go to Step 7.**

**If NO engine oil residue is found at the engine valley drain hole, but an original visual inspection indicated leak in the bell housing area, the root cause of the engine leak resides in the rear main seal and rear engine cover. Do not remove transmission from the vehicle. Go to step 7.**

**If NO engine oil residue is found at the engine valley drain hole, then the root cause of the engine oil leak will be related to the original visual inspection of front cover, or oil pan. Go to step 12.**

**Using the borescope, provide a picture of the engine valley drain hole regardless if oil is present or not.**

7. Perform the timing chain test plan.

**All Models: Timing Chains Test Plan path:**

1. Select "Vehicle management"
2. Select "Troubleshooting"
3. Select "Function structure"
4. Select "Powertrain"
5. Select "Engine electronics, quality control valve (MSV)"
6. Select "Valve gear"
7. Select "Start search"
8. From the list of available test plans, select "VANOS solenoid valve, exhaust" or "Exhaust Camshaft Sensor"

9. Select "Continue"
10. Select "VANOS Solenoid Valve"
11. Select "Display"
12. Select "Continue test module" and "Next"
13. Select "Timing chain test" and follow the steps to complete the test plan.
14. If the test plan asks "Solenoid valves ok?" Select "Yes".
15. Follow the test plan steps to check the timing chain.
16. Test plan will conclude with the statement "Timing chain is OK" or "Timing chain is not OK".

If the test plan results indicate the timing chains are not stretched ("OK"), then go to step 8.

Or

If the test plan results indicate the timing chains are stretched ("not OK"), then go to step 12.

8. Perform the compression test.

#### Test Plan Path:

1. Select "Vehicle management"
2. Select "Service functions"
3. Select "Powertrain"
4. Select "Engine Electronics quality control (MSV)"
5. Select "Compression test"
6. The compression test plan and the compression test repair instructions will be shown on the screen. Review the compression test repair instruction to become more familiar with the tools and the procedure before starting the compression test plan.
7. Select "ABL Compression test"
8. Follow the test plan steps to complete the compression tests.

For reference the compression test procedure instructions can also be found in Repair Instruction 11 00 039 "Checking compression of all cylinders"

The compression test should be performed after the engine has reached operating temperature. When performing the test count the rotations of the engine crankshaft and apply the same rotations to each cylinder compression test. The industry standard is 4 rotations per cylinder.

When comparing the values of all cylinders the compression results should not vary by more than 2.5 bar or 36.25 psi. If the difference is greater than 2.5 bar or 36.25 psi then proceed to step 11.

The test plan will record the measurements but you will have to determine if they are within specification or not.

If the BMW special tools are not available at the dealer then a manual gauge procedure can be substituted, record all values in the oil consumption checklist. Use the limit values listed above to determine if the values are within specification.

If the engine passes the compression test then proceed to step 9.

9. Inspect the turbochargers for engine oil leakage.



The turbocharger is OK.  
No engine oil can be seen around the turbocharger impeller.



The turbocharger is OK.  
No engine oil can be seen around the turbocharger impeller.



The turbocharger is not OK.  
The turbocharger impeller seals are leaking engine oil.



The turbocharger is not OK.

The turbocharger impeller seals are leaking engine oil.

If the turbocharger inspection is "OK", then go to step 10.

Or

If the turbocharger inspection is "NOT OK", then replace the turbochargers in conjunction with the recommendations in step 10. Go to step 10.



10. Replace the intake and exhaust valve seals using the N63 Valve Seal Replacement Tool Kit P/N 83 30 2 408 268 as per SI B11 08 15 or Repair Instruction 11 34 570 "Replace all valve stem seals using special tool 83 30 2 408 268 (N63)".

Refer to SI [B04 15 15](#) for additional ordering information.

**NOTE:**


Prior to proceeding with VANOS units removal, and after removing the valve covers, make sure that the timing chain guides are intact (not broken).

Specifically, turn the engine manually 2-3 times over, while listening for any unusual noises coming from the timing chains area.

Using borescope, run the probe down the chains on both banks, to inspect for possible guides breakage/cracks.

If any chain guide(s) damage is found, supplement your TSARA TC case with additional information and pictures, and wait for response before proceeding further.

Replace the cylinder head cover oil separators as per Repair Instruction 11 15 140 "Replace oil separator"

	<p>If the turbocharger inspection is “not OK” then replace the turbochargers. Refer to repair instruction 11 65 025 “Removing and installing exhaust turbocharger, cylinders 1-4” and Repair Instruction 11 65 030 “Removing and installing exhaust turbocharger, cylinders 5-8”</p> <p>Do not replace the turbo chargers if they are not leaking.</p> <p>If engine oil is found under the turbos using a borescope then the oil return line cover (1) or the oil return line gaskets (2) are leaking engine oil.</p> <p>(1) The oil return cover comes with all 3 O-rings. Use P/N 11 42 7 935 572.</p> <p>(2) Gasket asbestos free. Use P/N 11 42 8 624 158.</p> <p>If the bell housing area shows a major oil leak, but engine valley area is dry (no oil puddle present), then also replace the rear main oil seal (find the correct PN in the ETK), with the rear engine cover (PN 11 14 2 446 298). Follow repair instructions found in SI B11 09 16.</p>
--	---

<p>11. Complete the “B01_21_18_N63_Oil_Consumption_Checklist”</p> <p>All components or measurements that are found to be outside the specification need to be documented with pictures and submitted for authorization via a TSARA TeileClearing Hotline case and wait for a response. Weekend and holiday submissions must wait for a response on the following business day before starting any repairs.</p> <p>Vehicles that require an oil consumption test, have passed the oil consumption test or do not require any repairs do not need authorization.</p>	
--	--

<p><b>12. Only continue if one of the 5 inspections above have failed in steps 3 – 8 and there is no engine oil found under the turbo chargers using the borescope.</b></p> <p>Inspect the turbochargers for engine oil leakage.</p>	
--	--



The turbocharger is OK.  
No engine oil can be seen around the turbocharger impeller.



The turbocharger is OK.  
No engine oil can be seen around the turbocharger impeller.



The turbocharger is not OK.  
The turbocharger impeller seals are leaking engine oil.





The turbocharger is not OK.

The turbocharger impeller seals are leaking engine oil.

If the turbocharger inspection is "OK", then go to step 13.

Or,

If the turbocharger inspection is "NOT OK", then replace the turbochargers in conjunction with the recommendations in step 12. Go to step 13.

### 13. Replace the engine.

If the turbocharger inspection is "not OK" then replace the turbochargers. Refer to repair instruction 11 65 025 "Removing and installing exhaust turbocharger, cylinders 1-4" and Repair Instruction 11 65 030 "Removing and installing exhaust turbocharger, cylinders 5-8"

Do not replace the turbo chargers if they are not leaking.

Complete the "B01\_21\_18\_N63\_Oil\_Consumption\_Checklist"

All components or measurements that are found to be outside the specification need to be documented with pictures and submitted for authorization via a TSARA TeileClearing Hotline case and wait for a response. Weekend and holiday submissions must wait for a response on the following business day before starting any repairs.

Vehicles that require an oil consumption test, have passed the oil consumption test or do not require any repairs do not need authorization.

### **Engine Repairs and Replacements:**

Replacement engine assemblies are **NOT pre-filled** with engine oil.

**After replacing an engine with a new or remanufactured engine assembly, the engine oil level must be verified as outlined in the procedure below first, before starting the engine for the first time.**

If the replacement engine is started to determine electronically if the engine is filled with the appropriate amount of engine oil, damage to the replacement engine can occur immediately.

The engine may have some residual engine oil from assembly, but this is **not enough** engine oil to properly lubricate the engine to measure the engine oil level electronically when it is started for the first time.

Further, the electronic engine oil measurement is only operational when the engine is running at its full operating temperature. Checking the engine oil without the engine running at operating temperature will lead to an incorrect or incomplete measurement.

After replacing the engine or making engine repairs that require the replacement or removal of the engine bearings, VANOS gears, camshafts, bed plate resealing, engine oil pump, engine oil filter housing, cylinder head, engine oil cooler or anything that interrupts the engine oil supply circuit of the engine requires a short oil pump and oil supply circuit priming procedure.

Refer to SI B11 09 15 for the detailed bleeding procedure.

**After engine repair or replacement, pay attention to a proper installation of all engine ground connections.**

In particular, follow the recommendations from SI B12 24 14 (N63: Proper Ignition Harness Installation and Ground Connections) for the ignition harness grounding. Any consequential damage to DME, alternator, or QLT sensor resulted from a loose ground (causing BSD communication faults), is not covered under N63 Class Settlement.

**If the engine malfunction warning is illuminated and lean mixture faults are stored in the DME:** 

1. Double check all basic induction system connections, ensure no leaks are present.
2. Adaptation Procedure: Disconnect the tank ventilation valve (purge valve) electrical connector and allow the engine to idle for 15 minutes. This procedure will allow the DME to readapt. After 15 minutes of idling reconnect the tank ventilation valve (purge valve) electrical connector and clear the fault memory. Test drive the vehicle to ensure all faults do not reoccur.

**Workshop Cleanliness:** 

Always ensure the high pressure fuel system parts are properly stored in a clean location. Use caps or bags to keep contamination from occurring. It is good practice to immediately cap the high pressure pumps and store them in the upright position so that the plunger does not dry out. The appropriate caps can be found in the N63 Valve Seal Replacement Tool Kit P/N 83 30 2 408 268.

Changes are highlighted with  .

1. Start the vehicle and allow it to reach operating temperature, approximately 15 minutes or less.



2. Quickly push-and-release the accelerator pedal from idle position to between 2,000 and 3,000 RPM, then immediately allow the engine to return to idle and observe the exhaust tail pipes for smoke.

If smoke is present continue to step 3.

If smoke is **NOT** present then refer to the “N63 Oil Consumption Instructions” attached to SI B01 21 18.

**IMPORTANT!** 

- **If the vehicle is smoking from the exhaust then a clear video or picture of the smoke must be submitted with the TSARA TeileClearing Hotline case. The video or picture must include the license plate.**

3. Inspect or measure the following 5 items in order. Note the inspection results on the attached “N63 Smoke Checklist.”

- Engine front cover
- Engine upper oil pan
- Lower bell housing/cylinder heads valley area
- Perform the timing chain test plan
- Perform a compression test

**IMPORTANT!**

**• If the engine is leaking engine oil, the oil leak must be an active major engine oil leak, not seepage or wetness.**

All components or measurements that are found to be outside the specification need to be documented with pictures and submitted for authorization via a TSARA TeileClearing Hotline case at the end of this procedure.


Vehicles that are not smoking or do not require any repairs do not need authorization.

**GENERAL NOTES REGARDING ENGINE OIL LEAKS:**

“Oil Leaks” are being defined as clearly visible oil presence (like oil drops) at the engine components (e.g. area of oil pan, front cover, etc.), and in their vicinity. Also, large visible oil stains (or oil accumulation) on the underbody panels are indication of oil leaks, causing a substantial oil capacity loss.

The black (dirt stained) “wetness” marks on the engine components, **DO NOT** qualify as oil leaks.

4. Inspect the front engine cover for engine oil leakage.



Front cover is **not** leaking. Go to step 5.

Front cover is leaking. Go to step 7.

5. Inspect the upper engine oil pan for engine oil leakage.



The upper engine oil pan is **not** leaking.  
Go to step 6.




The upper engine oil pan is leaking.  
Go to step 7.

6. Inspect the lower bell housing for engine oil leakage



The lower bell housing is **not** leaking. Go to step 8.

The lower bell housing is leaking. Go to step 7.

<p>7. Turbocharger oil line diagnosis.</p>	
	<p>Remove the heat shield (1) to diagnose the engine oil leak.</p> <p>Refer to Repair Instruction 11 65 180 Removing and installing/replacing heat shield at top.</p>
	<p>The illustration shows an overview of the components found on cylinder bank 1.</p> <p>Cylinder head cover (1)</p> <p>Cylinder # 4 (2)</p> <p>Inspection location (3)</p>
	<p>The illustration shows an overview of the components frond on cylinder bank 1.</p> <p>Cylinder head cover (1)</p> <p>Bank 1 post O2 sensor (2)</p> <p>Heat shield mounting hole (3)</p>



Preparing for the inspection:

Bore scope specifications:


The recommended diameter of the fiber optic cable (imager) should not be greater than 5.5 mm. The 8 mm fiber optic cable (imager) will work but it is very tight and damage may occur to the larger cable and imager.

The recommended borescope and imager can be found at [www.centersolutions.com](http://www.centersolutions.com) or refer to SI B04 19 15 for more information about the BMW Equipment Program.

Equipment Program Part Numbers:

107 - BK5000 - SNAP ON Video Scope

107- BK8000 – 5.5 mm Dual View Side Imager




The illustration shows an overview of the components found on cylinder bank 1.

Cylinder head cover (1)


Bank 1 post O2 sensor (2)

Heat shield mounting hole (3)

Insert bore scope here (4) on an angle downward.



Approach angle of the bore scope (1) is approximately 45 degrees.




After inserting the bore scope you must locate the cylinder head gasket tab. (1).

The tab is approximately 135 mm straight down from original entry point.

Cylinder head gasket tab (1)




Gap in heat shields (2)




Cylinder head (3)




Feed the bore scope past the left side (1) of the cylinder head gasket tab (2) towards the vacuum reservoir (3).



	<p>Continue to push the bore scope towards the vacuum reservoir (1). The engine valley drain hole is location is just to the left of the vacuum reservoir (2).</p> <p>Metal vacuum reservoir shown in photo.</p> <p>As the bore scope approaches the drain hole it will become more apparent.</p>
	<p>Inspect the surrounding area of the engine valley drain hole (1).</p> <p>Engine valley drain hole (1)</p> <p>Metal vacuum reservoir (2) shown.</p> <p>This is a clean picture. No oil can be seen in the oil drain hole (1).</p> <p>The dark material at the bottom of the photo is dust and dirt. This material appears to be reflective but it is dry</p>
	<p>It is possible that a black plastic vacuum reservoir (1) is installed. This illustration provides an overview of the entire component and specific points of the component.</p> <p>Reservoir (1)</p> <p>Reservoir mounting screw (2)</p> <p>Plastic vacuum reservoir tab (3)</p>

	<p>Plastic vacuum reservoir tab (1)</p> <p>Mounting screw (2)</p>
	<p>Diagnosis in the vehicle:</p> <p>It may be more difficult to position the bore scope but it will only take a few minutes more to make the diagnosis.</p> <p>Engine valley drain hole (1)</p> <p>Plastic vacuum reservoir tab (2)</p> <p>Reservoir mounting screw (3)</p>
	<p>Continue to push bore scope down ward towards the plastic vacuum reservoir tab (2).</p> <p>The bore scope needs to be moved towards the direction of the red arrow and under the tab (2) to have the best viewing angle of the engine valley drain hole (1).</p> <p>Engine valley drain hole (1)</p> <p>Plastic vacuum reservoir tab (2)</p> <p>Reservoir mounting screw (3)</p>



Once the bore scope has gone under the plastic reservoir tab then the engine valley drain hole (1) and surrounding area can be clearly inspected.

The dark material at the bottom of the photo is dust and dirt. This material appears to be reflective but it is dry.

Engine valley drain hole (1)

Plastic vacuum reservoir (2)

**If engine oil is found in the valley area, then the root cause of the engine oil leak resides in the components on top of the engine i.e. turbocharger oil lines cover, turbo charger, etc. Further basic diagnosis will be needed to find the root cause this engine oil leak. Do not remove the transmission from the vehicle. Go to Step 8.**

**If NO engine oil residue is found at the engine valley drain hole, but an original visual inspection indicated leak in the bell housing area, the root cause of the engine leak resides in the rear main seal and rear engine cover. Do not remove transmission from the vehicle. Go to step 8.**

**If NO engine oil residue is found at the engine valley drain hole, then the root cause of the engine oil leak will be related to the original visual inspection of front cover, or oil pan. Go to step 12.**

**Using the borescope, provide a picture of the engine valley drain hole regardless if oil is present or not.**

8. Perform the timing chain test plan.

**All Models: Timing Chains Test Plan path:**

1. Select "Vehicle management"
2. Select "Troubleshooting"
3. Select "Function structure"
4. Select "Powertrain"
5. Select "Engine electronics, quality control valve (MSV)"
6. Select "Valve gear"
7. Select "Start Search"
8. From the list of available test plans, select "VANOS solenoid valve, exhaust" or "Exhaust Camshaft Sensor"
9. Select "Continue"
10. Select "VANOS Solenoid Valve"
11. Select "Display"
12. Select "Continue test module" and "Next"
13. Select "Timing chain test" and follow the steps to complete the test plan.
14. If the test plan asks "Solenoid valves ok?" Select "Yes".
15. Follow the test plan steps to check the timing chain.
16. Test plan will conclude with the statement "Timing chain is OK" or "Timing chain is not OK".

If the test plan results indicate the timing chains are not stretched ("OK"), then go to step 9.

Or

If the test plan results indicate the timing chains are stretched ("not OK"), then go to step 14.

9. Perform the compression test.

Test Plan path:

1. Select "Vehicle management"
2. Select "Service functions"
3. Select "Powertrain"
4. Select "Engine Electronics quality control (MSV)"
5. Select "Compression test"
6. The compression test plan and the compression test repair instructions will be shown on the screen. Review the compression test repair instruction to become more familiar with the tools and the procedure before starting the compression test plan.
7. Select "ABL Compression test"
8. Follow the test plan steps to complete the compression tests.

For reference the compression test procedure instructions can also be found in Repair Instruction 11 00 039 "Checking compression of all cylinders"

For the compression test procedure instructions refer to Repair Instruction 11 00 039 "Checking compression of all cylinders"

The compression test should be performed after the engine has reached operating temperature. When performing the test count the rotations of the engine crankshaft and apply the same rotations to each cylinder compression test. The industry standard is 4 rotations per cylinder.

When comparing the values of all cylinders the compression results should not vary by more than 2.5 bar or 36.25 psi. If the difference is greater than 2.5 bar or 36.25 psi then proceed to step 14.

The test plan will record the measurements but you will have to determine if they are within specification or not.

If the BMW special tools are not available at the dealer then a manual gauge procedure can be substituted, record all values in the oil consumption checklist. Use the limit values listed above to determine if the values are within specification.

If the engine passes the compression test then proceed to step 10.

10. Inspect the turbochargers for engine oil leakage.



The turbocharger is OK.  
No engine oil can be seen around the turbocharger impeller.



The turbocharger is OK.  
No engine oil can be seen around the turbocharger impeller.



The turbocharger is not OK.  
The turbocharger impeller seals are leaking engine oil.



The turbocharger is not OK.  
The turbocharger impeller seals are leaking engine oil.

If the turbocharger inspection is "OK", then go to step 11.

Or

If the turbocharger inspection is "NOT OK", then replace the turbochargers in conjunction with the recommendations in step 11. Go to step 11.



GRUSB1115-11

11. Replace the intake and exhaust valve seals using the N63 Valve Seal Replacement Tool Kit P/N 83 30 2 408 268 as per SI B11 08 15 or Repair Instruction 11 34 570 "Replace all valve stem seals using special tool 83 30 2 408 268 (N63)".

Refer to SI [B04 15 15](#) for additional ordering information.

**NOTE:**

Prior to proceeding with VANOS units removal, and after removing the valve covers, make sure that the timing chain guides are intact (not broken). Specifically, turn the engine manually 2-3 times over, while listening for any unusual noises coming from the timing chains area.


Using borescope, run the probe down the chains on both banks, to inspect for possible guides breakage/cracks.

If any chain guide(s) damage is found, supplement your TSARA TC case with additional information and pictures, and wait for response before proceeding further.

Replace the cylinder head cover oil separators as per Repair Instruction 11 15 140 " Replace oil separator"

If the turbocharger inspection is "not OK" then replace the turbochargers. Refer to repair instruction 11 65 025 "Removing and installing exhaust turbocharger, cylinders 1-4" and Repair Instruction 11 65 030 "Removing and installing exhaust turbocharger, cylinders 5-8"

Do not replace the turbo chargers if they are not leaking.



If engine oil is found under the turbos using a borescope then the oil return line cover (1) or the oil return line gaskets (2) are leaking engine oil.

(1) The oil return cover comes with all 3 O-rings. Use P/N 11 42 7 935 572.

Gasket asbestos free. Use P/N 11 42 8 624 158.

If the bell housing area shows a major oil leak, but engine valley area is dry (no oil puddle present), then also replace the rear main oil seal (find the correct PN in the ETK), with the rear engine cover (PN 11 14 2 446 298). Follow repair instructions from SI B11 09 16.

12. Complete the "B01\_21\_18\_N63\_Smoke\_Checklist".

All components or measurements that are found to be outside the specification need to be documented with pictures and submitted for authorization via a TSARA TeileClearing Hotline case and wait for a response. Weekend and holiday submissions must wait for a response on the following business day before starting any repairs.

Vehicles that are not smoking or do not require any repairs do not need authorization.

13. **Only continue if one of the 5 inspections above have failed in steps 3 – 8 and there is no engine oil found under the turbo chargers using the borescope.**

Inspect the turbochargers for engine oil leakage.



The turbocharger is OK.

No engine oil can be seen around the turbocharger impeller.





The turbocharger is OK.  
No engine oil can be seen around the turbocharger impeller.



The turbocharger is not OK.  
The turbocharger impeller seals are leaking engine oil.



The turbocharger is not OK.  
The turbocharger impeller seals are leaking engine oil.

If the turbocharger inspection is "OK", then go to step 14.

Or

If the turbocharger inspection is "NOT OK", then replace the turbochargers in conjunction with the recommendations in step 14. Go to step 14.

#### 14. Replace the engine.

If the turbocharger inspection is "not OK" then replace the turbochargers. Refer to repair instruction 11 65 025 "Removing and installing exhaust turbocharger, cylinders 1-4" and Repair Instruction 11 65 030 "Removing and installing exhaust turbocharger, cylinders 5-8"

Do not replace the turbo chargers if they are not leaking.

Complete the "B01\_21\_18\_N63\_Smoke\_Checklist"

All components or measurements that are found to be outside the specification need to be documented with pictures and submitted for authorization via a TSARA TeileClearing Hotline case and wait for a response. Weekend and holiday submissions must wait for a response on the following business day before starting any repairs.

Vehicles that are not smoking or do not require any repairs do not need authorization.

### **Engine Repairs and Replacements:**

Replacement engine assemblies are **NOT pre-filled** with engine oil.

**After replacing an engine with a new or remanufactured engine assembly, the engine oil level must be verified as outlined in the procedure below first, before starting the engine for the first time.**

If the replacement engine is started to determine electronically if the engine is filled with the appropriate amount of engine oil, damage to the replacement engine can occur immediately.

The engine may have some residual engine oil from assembly, but this is **not enough** engine oil to properly lubricate the engine to measure the engine oil level electronically when it is started for the first time.

Further, the electronic engine oil measurement is only operational when the engine is running at its full operating temperature. Checking the engine oil without the engine running at operating temperature will lead to an incorrect or incomplete measurement. After replacing the engine or making engine repairs that require the replacement or removal of the engine bearings, VANOS gears, camshafts, bed plate resealing, engine oil pump, engine oil filter housing, cylinder head, engine oil cooler or anything that interrupts the engine oil supply circuit of the engine requires a short oil pump and oil supply circuit priming procedure.

Refer to SI B11 09 15 for the detailed bleeding procedure.

**After engine repair or replacement, pay attention to a proper installation of all engine ground connections.** In particular, follow the recommendations from SI B12 24 14 (N63: Proper Ignition Harness Installation and Ground Connections) for the ignition harness grounding. Any consequential damage to DME, alternator, or QLT sensor resulted from a loose ground (causing BSD communication faults), is not covered under N63 Class Settlement.

**If the engine malfunction warning is illuminated and lean mixture faults are stored in the DME:** 

1. Double check all basic induction system connections, ensure no leaks are present.
2. Adaptation Procedure: Disconnect the tank ventilation valve (purge valve) electrical connector and allow the engine to idle for 15 minutes. This procedure will allow the DME to readapt. After 15 minutes of idling reconnect the tank ventilation valve (purge valve) electrical connector and clear the fault memory. Test drive the vehicle to ensure all faults do not reoccur.

**Workshop Cleanliness:** 

Always ensure the high pressure fuel system parts are properly stored in a clean location. Use caps or bags to keep contamination from occurring. It is good practice to immediately cap the high pressure pumps and store them in the upright position so that the plunger does not dry out. The appropriate caps can be found in the N63 Valve Seal Replacement Tool Kit P/N 83 30 2 408 268.