

40 Noises from the front end when steering

40 19 96 2053136/3 August 5, 2019. Supersedes Technical Service Bulletin Group 40 number 19-95 dated March 27, 2019 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
А3	2015 - 2019	All	Not Applicable	
А3	2020	000001 - 001882	Not Applicable	

Condition

REVISION HISTORY				
Revision Date Purpose				
3	-	Revised header (Added MY20 VIN break)		
2	03/27/2019	Revised Warranty (Updated Claim Types and added Labor Operation)		
1	11/30/2018	Initial publication		

Customer statement:

Noises from the left or right front end when steering.

Workshop findings:

- The customer statement can be reproduced. The noises can be clearly assigned to the suspension strut mounting.
- TSB 2044060: 40 Noises from front shock bellows when steering or when the front suspension is compressed has already been checked/completed.

Technical Background

The axial deep-groove ball bearing overlaps the suspension strut mounting. Over time the overlap can cause noises.

Production Solution

100% check when axial deep-groove ball bearing and suspension strut mounting are assembled.



Service

Tip: Axial deep-groove ball bearing and suspension strut mounting must always be replaced together. The two components must always be replaced on both sides (right and left).

1. Replace the axial deep-groove ball bearing (Figure 1, position 2) and the suspension strut mounting (Figure 1, position 4) according to the Elsa Repair Manual.




Figure 1. Suspension strut mounting and axial deep-groove ball bearing.



 Ensure the correct installation position when assembling the suspension strut mounting and the axial deep-groove ball bearing. The bar of the axial deepgroove ball bearing must be central in the groove of suspension strut mounting (Figure 2).



Figure 2. The correct installation position of suspension strut mounting and axial deep-groove ball bearing.

Warranty

Claim Type:	 110 up to 48 Months/50,000 Miles. If the vehicle is outside any warranty, this Technical Service Bulletin is informational only. 				
Service Number:	4088				
Damage Code:	0010				
Labor Operations:	Remove and install 2 deep groove ball thrust bearings	4093 2050	See SRT		
	Suspension struts remove + reinstall	4085 2002 Or 4085 2004	See SRT		
Diagnostic Time:	GFF	No allowance	0 TU		
	Road test prior to service procedure	0121 0002	10 TU		
	Road test after service procedure	0121 0004	10 TU		
Claim Comment:	As per TSB #2053136/3				



All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.						
Part Number	Part Description	Quantity				
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA				
See ETKA	Axial deep-groove ball bearing	02				
See ETKA	Suspension strut mounting	02				

Additional Information

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

• TSB 2044060, 40 Noises from front shock bellows when steering or when the front suspension is compressed.

All parts and service references provided in this TSB (2053136) are subject to change and/or removal.

©2019 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.