

**Adaptive Cruise Control Warning Along with ZFAS Faults**

**Vehicles Affected**

| Model   | Model Year | Model Type | VIN Range | Vehicle Specific Equipment |
|---------|------------|------------|-----------|----------------------------|
| Cayenne | 2019       | 9YA        | N/A       | N/A                        |

**Revision History**

| Revision | Release Date      | Changes  |
|----------|-------------------|--|
| 0        | November 30, 2018 | Original Document                              |
| 1        | August 6, 2019    | Added reference to WKC6 for corrective action. |

**Customer Concern**

The customer experiences a warning in the instrument cluster for Adaptive Cruise Control, Porsche Active Safe, and Headlight System.

**Technical Background**

The workshop confirms this behavior along with at least one of the following fault codes and fault sub-codes in the ZFAS driver assistance systems module.

|  |
|--|
| <p><b>ZFAS Fault code:</b> C12D5FA - Driver assistance systems control module, Image processing processor not reacting</p> <ul style="list-style-type: none"> <li><b>Sub-code:</b> 036061</li> </ul> <p>This fault code and sub-code combination is the result of a software bug and incorrect coding.</p> |
| <p><b>ZFAS Fault code:</b> B170AF1 - Coding, Step 2 not carried out</p> <ul style="list-style-type: none"> <li><b>Sub-code:</b> 205040</li> </ul> <p>This fault code and sub-code combination indicate the ECU is not completely coded.</p>  |

**Service Information**

Service campaign WKC6 fixes these issues. Please see the associated workshop literature for instructions.

**Search Items** (Tags, keywords, etc that can be used to search for this document)

Adaptive Cruise Control, ACC, ADC, driver assistance, ZFAS, Porsche Active Safe

---

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.