



# Technical Service Bulletin

## 94 Vehicle lights malfunction message in instrument cluster, DTC 03280, 01800 or B126AF0 stored in the vehicle module

94 19 13 2017806/12 September 17, 2019. Supersedes Technical Service Bulletin Group 94 number 15-64 dated March 4, 2015 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A5	2010 - 2020	All	Not Applicable
Q3	2015 - 2020	All	Not Applicable
Q7	2017 - 2020	All	Not Applicable
A4, Q5	2009 - 2020	All	Not Applicable
A8, TT	2011 - 2018	All	Not Applicable
A6, A7	2012 - 2018	All	Not Applicable

## Condition

REVISION HISTORY		
Revision	Date	Purpose
12	-	Revised header (Updated model years for (A3, A4, A5, A6, A7, A8 Q5, and Q7) Revised <i>Condition</i> (Updated faults for current models) Revised <i>Technical Background</i> (Added information)
11	03/05/2015	Revised header (Added Q3 and TT)
10	02/12/2015	Revised header (Added model year; added A3) Revised <i>Technical Background</i> (Added picture for clarity)

### Customer states:

- The light bulb warning light is displayed in the instrument cluster with the following message: "Vehicle lights: malfunction".

### Workshop findings:

- Exterior lights are functioning properly.

One of the following DTCs is stored in the vehicle electrical system control module, J519 (address word 0009):

- **DTC 03280** (Light switch position implausible signal).
- **DTC 01800** (Light switch E1, no signal/communication).



# Technical Service Bulletin

---

- **DTC B126AF0** (Light switch implausible switch position).

## Technical Background

If the headlight switch is moved to an intermediate position and remains there (Figure 1), the light bulb warning light and the error message appear after approximately ten seconds (Figure 2).



**Figure 1.** A headlight switch in an intermediate position.



**Figure 2.** The warning light and error message in the instrument cluster display.

Once displayed, the message turns off after approximately five seconds. The light bulb warning light turns off only after the headlight switch is turned to a defined position, and the status of **DTC 03280**, **DTC 01800** or **DTC B126AF0** are changed to sporadic.

After 40 driving cycles without an implausible signal detected, the DTCs are automatically cleared.



# Technical Service Bulletin

---

It is possible a faulty switch can cause the same faults and warning. For faults that are static or concerns able to be reproduced, use the MVBs within the 09 module to determine if the light switch position can be properly detected.

If the MVB does not match the physical position of the headlight switch, the switch is faulty.

In Figures 3 and 4 below, the intermediate position of the rotary knob is correctly detected in the MVBs of the 09 module. This is normal and does not indicate a faulty component. In this case, explain the operation to the customer.



**Figure 3.** Switch in an intermediate position (2018 A4).

Measured value name	ID	Value
Light switch	IDE08402	
Light switch position	IDE05742	Intermediate position park. light - low beam
Light switch position on CAN	MAS06887	Error

**Figure 4.** The corresponding MVB showing the implausible switch position (2018 A4).

## Production Solution

Not applicable.

## Service

Determine if the above situation applies to the vehicle, and explain the *Technical Background* to the customer. Replacing parts does not change the behavior.

## Warranty

This TSB is informational only and not applicable to any Audi Warranty.



# Technical Service Bulletin

---

## Additional Information

All part and service references provided in this TSB (2017806) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2019 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.