

## Solution K05913580 Friday, October 4, 2019 3:49:02 PM CEST

## \*\* SOLUTION \*\*

Title	13 Liter Engines ONLY - Engine Coolant Pump Housing Leak; Coolant Found Around The Oil Cooler Duct Cover Or In Between The Coolant Pump Housing And Oil Cooler Housing - Model Years 2019 And 2020
Mack Models	
Mack Model	TE - TerraPro, AN - Anthem, GR - Granite, PI - Pinnacle
Volvo Models	
Volvo Model	VN, VNL, VNR, VNX, VAH, VHD
Engine family	
Engine family	13L Engine, MP8
** SOLUTION **	
Cause	Vehicles built between 1 March 2018 and 28 May 2019 and equipped with a 13 liter engine may experience coolant leakage found on the front right side of the engine. It has been found that some coolant pump housings were manufactured out of specification.
Solution	Vehicles affected by this issue will show coolant runoff on the front rights side of the engine. The likely area coolant will be found is highlighted below:



The joint between the coolant pump housing and oil cooler duct cover should be checked:



If a vehicle presents with a coolant leak in the area shown and the source of the leak is traced to the surfaces between the oil cooler duct cover and the coolant pump housing:

- Replace the coolant pump cover.
- Replace the seal between the oil cooler duct cover and the coolant pump.

**Note:** Ensure the seal is properly seated when reconnecting the housing and duct cover. If the seal is improperly seated, leakage may persist after repairs are complete.

Solution visibility	Dealer distribution	
Function(s)/component(s) affected		
Function affected	Water Pump	
Function Group		
Function Group	262 coolant pump and thermostat	
Customer effect		
Main customer effect	fluid	
Fluid problem	leak	
Fluid implicated	Coolant	
Visual appearance	leaking	
Administration		
Author	A241298	
Dealer ID	A241298	
Last modified by	A241298	
Creation date	29-07-2019 20:07	
Date of last update	10-09-2019 21:09	
Status	Published	

UNCONTROLLED COPY. Printed document is for temporary use only and should not be retained.