

**** SOLUTION ****

Title	Vehicles With An Automated Manual Transmission (AMT) - Power Take-Off Diagnosis And Repair; PTO Air Leaks, Oil Leaks, Engagement, Noise
-------	---

Mack Models

Mack Model	AN - Anthem , CHU - Pinnacle, Axle back , CXU - Pinnacle, Axle front , GR - Granite , GU - Granite , PI - Pinnacle , TD - Titan
-------------------	---

Volvo Models

Volvo Model	VNL , VNM , VNR , VNX , VAH , VHD
--------------------	-----------------------------------

Emission Standard

Emission Standard	US07 , US10 , US10+OBD13 , US14+OBD13 , US14+OBD15 , US14+OBD16 , US17+OBD16 , US17+OBD18 , US17+OBD19
-------------------	--

Engine family

Engine family	11L Engine , 13L Engine , 16L Engine , MP7 , MP8 , MP10
---------------	---

Transmission

Transmission	AMT-F , AMT-F With Crawler Gears , AMT-F Without Crawler Gears , AMT-C , AMT-D , AMT-F , AMT-C , AMT-D , AMT-F , AMT-F With Crawler Gears , AMT-F Without Crawler Gears
--------------	---

**** SOLUTION ****

Cause	The service instructions for the gearbox mounted AMT PTO have not been readily available to the NA market when the PTO was made available for the AMT in NA. Although many of the parts have been available for the PTO in the NA parts system, not all parts are available because major components like gears and housing can quickly drive the cost of repair higher than the replacement cost. The parts that are available in NA parts system represent a reasonable repair option when internal inspection of the PTO and the failure mode show that a simple repair in the field is possible. See the failure mode and repair option information below for more information.
-------	---

Solution	<u>Where to find repair instructions</u>
----------	---

**WARNING**


Language settings **must be returned** to English (United States) after following the instructions below. CBR will not function correctly if the language is improperly set.

Note: Not all dealers or users are set up to be able to do this.


Service instructions are available in Europe for all of the PTOs currently available in NA. Changes

are ongoing to make this information available in the NA market. Until that happens please use the steps below to find the service instructions needed.


1. When looking for information in IMPACT click on the 'Menu' tab and select 'My Settings'.



2. Change your preferred language to English (Great Britain) and hit 'Save'



3. Under the service tab search for Model 'FH (4)' -- Select Function Group 48. Power Take-Off-All service information and hit search.




3.1. Here you will find Design and Function and service documentation.

Type	Title	Info type
41	Planetary main control function description	Description, Design and Location
41	PTO operation and shut down	Technical Service Bulletin
41	Powertrain PTO operation and identification methods	Technical Service Bulletin
402	Power shaft	Description, Design and Location
404	Power shaft and intermediate	Power
405	Power shaft input	Power
406	Power shaft control Removal	Power
407	Power shaft drive	Power
408	Control shaft power shaft input	Power
409	Power shaft lock release	Power
410	Power shaft input	Power
411	Power shaft output	Power
412	Power shaft input release	Power
413	Power shaft input release	Power
414	Power shaft input release	Power
415	Power shaft input release	Power
416	Power shaft input release	Power
417	Power shaft input release	Power
418	Power shaft input release	Power
419	Power shaft input release	Power

4. Select the PTO model you have from the list and then you can download or print the document for reference.

Note: The PTO model is stamped in the case of the PTO.



Note: DO NOT forget to change language settings back when finished!

Fail modes

Note: This list assumes the PTO was previously working as designed and has stopped working properly and is not limited to these descriptions.

- **Air leaking from gearbox vents when the PTO is engaged.**

Air leaking from the vents with PTO engaged is an air seal issue. The seals are available, as are the gaskets for the repair. The limiting factor is if the bore in the case that the piston is riding in is scored or worn.

1. Inspect the air piston for wear. Look for evidence of the piston making contact with the bore as shown in the picture below.



- **If wear is found**, the bore needs to be inspected.

2. Inspect the piston bore. Check for any wear or damage as shown in the example below.



- **If the bore is serviceable**, the unit should be repaired. Replace the air piston and seals.



- **If the bore is worn**, replace the PTO. The piston bore is not repairable.

3. Check the piston and bore for rust.

- **If Rust is found on the piston face**, then there has been water intrusion to the piston. An example is shown below.

Check the vehicle air system for moisture and correct the root cause of the water intrusion.



- **If rust damage is found in the bottom of the piston bore**, clean the bore and inspect the sealing surface for damage. Rust in the bottom of the bore will not affect operation.



- **If the vehicle air system is dry and properly serviced**, the solenoid should be checked for a good rubber cap on the top.

If the cap seal is damaged then replace the solenoid.



- The PTO drive shaft in the rear of the gearbox has a snap ring that contains the bearing to the shaft. If this snap ring breaks the pieces may end up in the PTO and get lodged under the shift fork and bind the fork.

- Depending on where the piece gets stuck will depend on how the failure is described.

- **If it is confirmed that the snap ring is the cause:**

Repair as needed.

Disassemble and inspect the PTO for repair or replacement.

Examples of snap ring failure can be found below:



Pieces of ring get into the PTO and cause operational issues.



Spline and sliding clutch: Damaged components should be replaced



PTO case damage from snap ring or other debris can be cleaned up and inspected. If the damage does not affect the operation of the PTO shifter and piston seals the PTO can be repaired.

- **Gearbox Low Lube, Mechanical or Contamination Failures**

A gearbox that fails for a low lube condition does not necessarily mean that the PTO is failed also. Contaminated oil may pass through the PTO, but may not necessarily cause damage. In several cases, PTOs replaced with a gearbox failure that have been inspected have been deemed acceptable for reuse. The PTO does not spin when not in use and so does not necessarily damage the internal parts due to low lube or contamination seen in the oil. The smaller single PTOs get lube all the time but the larger double PTOs do not. They only get oil from the gearbox when they are being used.

In cases of a gearbox failure of this nature, the PTO should be opened and inspected, cleaned, resealed and reused if the PTO is not failed.





Except for the dark oil in the housing, this PTO was perfect even though the gearbox failed for low lube.

Acceptable repairs and available parts

For all the fail modes listed above the repairs are typically straight-forward.

- Seals and gaskets for all PTOs are available in the parts system.
- The available parts include but may not be limited to common fasteners (nuts, bolts, washers and brackets), seals, gaskets, output flanges, sliding clutches and shift forks.
- Check parts availability for the repair.
- **When the repair starts to involve the replacement of the PTO case, gears or bearings the cost of parts and labor required to repair quickly exceeds the cost of replacement.**

Standard Repair Times

Operation	Description	SRT	
4811-03-02-02	PTO Replacement (Transmission), All Models	0.8 hr	
4811-04-04-01	Power Take-Off, Overhaul. Removed (Refer to appropriate PTO model to the right)	PTR-D	0.4 hr
		PTR-DH	1.8 hr
		PTR-DM	1.8 hr
		PTR-F	0.8 hr
		PTR-FH	1.6 hr
		PTR-FL	1.8 hr
		PTRD-D	1.4 hr
		PTRD-D1	1.4 hr
		PTRD-D2	1.4 hr
		PTRD-F	1.4 hr
4814-19-03-01	Power Take-off Shaft, Remove-Install, All Models	0.4 hr	

Solution visibility Dealer distribution

Function(s)/component(s) affected

Function affected Air System , Air Dryer , PTO

Function Group

Function Group 481 power-take off (gearbox) , 483 control power take-off

Customer effect

Main customer effect fluid , diagnostics/methodology

Noise	grinding , whine , hissing noise , blowing noise
Fluid problem	leak
Fluid implicated	Transmission Oil
Visual appearance	leaking

Conditions

Vehicle operating mode	with a PTO
Frequency of occurrence of problem	random
Location of problem	underneath cab

Administration

Author	UT9268H
Dealer ID	UT9268H
Last modified by	RU4469V
Creation date	29-08-2019 17:08
Date of last update	27-09-2019 19:09
Review date	31-12-2019 00:12
Status	<i>Draft copy</i>
NA_Reviewer	UT9268H
NA_Author_Group	GTT

Variantes Kola

5XX - PTO TRANSMISSION MOUNTED ADM.	PTOTRA-S - SINGLE PTO TRANSMISSION , PTOTRA-D - DOUBLE PTO TRANSMISSION
T4X - PTO TRANSM. MOUNTED	PTR-F - REAR PTO TRANS. FLANGE, 100% SPEDD , PTR-FL - PTO TRANS. MOUNTED REAR, FLANGE, LOW SPEED , PTRD-D1D - REAR PTO TRANS, DOUBLE,1 DIN-CONN.PUMP+1 FLANGE DIN 120 , PTR-D - REAR PTO TRANS., DIN-CONN.PUMP , PTR-DH - REAR PTO TRANS., DIN-CONN.PUMP, HIGH SPEED , PTR-DM - REAR PTO TRANS., DIN-CONN.PUMP,MEDIUM SPEED , PTRD-F - REAR PTO TRANS., DOUBLE, 1 SAE FLANGE , PTRD-D - REAR PTO TRANS., DOUBLE, 2 DIN-CONN.PUMP , PTRD-D2 - REAR PTO TRANS., DOUBLE, 1 DIN-CONN.PUMP + 2 FLANGES
RTX - AUTOMATIC GEARBOX	TRA-AMT

UNCONTROLLED COPY. Printed document is for temporary use only and should not be retained.