

QUALITY ACTION

CAMPAIGN BULLETIN

Inside Rearview Mirror Dealer Inventory

Reference: PM937

Date: February 1, 2020

Attention: Dealer Principal, Sales, Service & Parts Managers

Affected Affected Models/Years: Population:			SERVICE COMM Activation date:		
MY2020 Sentra (B18)	NA	336*	February 1, 2020	YES	

^{*13} VINs are assigned to Puerto Rico

*****Detailed Information****

Nissan is conducting a quality action on **336** MY2020 Sentra (B18) vehicles identified in Service Comm to inspect the adhesion of the inside rearview mirror attachment and, if necessary, replace the windshield if the mirror detaches.

Affected vehicles **are subject** to stop sale for temporary Quality Assurance (QA) Hold under PC732 and are either currently in dealer inventory or assigned and in transit to the dealer. Nissan is transitioning affected vehicles into this Quality Action campaign ID (PM937).

The Quality Hold under PC732 remains in effect for **346** MY2020 Sentra vehicles for a potential crack on the left side of the steering gear housing. Refer to PC732 for additional details.

*****What Dealers Should Do****

PLEASE FOLLOW THE ATTACHED REPAIR INSTRUCTIONS:

- 1. Verify if vehicles currently in new dealer inventory are affected by this quality action using Service Comm or DBS National Service History Open Campaign I.D. **PM937**
 - New vehicles in dealer inventory can also be identified using DBS (Sales-> Vehicle Inventory, and filter by Open Campaign).
 - Refer to NPSB 15-460 for additional information
 - <u>Please continue to check newly arriving inventory for campaign</u> applicability.
- 2. Use the attached procedure to inspect and, if necessary, remedy any vehicles affected by this quality action:
 - If the mirror and mounting plate does not detach from the windshield, no repair is needed.
 - If the inspection result is "NG" (inside rearview mirror and mounting plate detaches):
 - Replace the windshield and aim the front camera unit using the procedure outlined in the Electronic Service Manual (ESM).
 - Once vehicles have been inspected and, if necessary, remedied dealers may submit the applicable warranty claim for the action performed and the vehicle

can be r	released	for sale.	To a	avoid any	claim	suspension,	do not	submit
claims	prior to	Februar	y 4,	, 2020.				

***** Dealer Responsibility *****

It is the dealer's responsibility to check Service Comm or DBS National Service History – Open Campaign using the appropriate campaign I.D for the inspection status on each affected vehicle currently in new vehicle inventory.

NISSAN NORTH AMERICA, INC.

Aftersales DIVISION

***** Inspection procedure begins on next page *****



PM937 - 2020 SENTRA REAR VIEW MIRROR INSPECTION

SERVICE PROCEDURE:

1. Locate the rear view mirror mounted to the windshield. (Figure 1)



Figure 1

2. Confirm the rear view mirror is properly adhered to the windshield. (Figure 2)

NOTE: Do not use excessive force when performing this inspection procedure.

- a) Move the rear view mirror up until it reaches the stop.
- b) Move the rear view mirror down until it reaches the stop.
- c) Move the rear view mirror to the left until it reaches the stop.
- d) Move the rear view mirror to the right until it reaches the stop.
- e) Repeat the sub-steps a-d (10) additional times.



Figure 2

- 3. Did the rear view mirror and mounting plate become loose or detached from the windshield?
 - > NO Inspection is complete, no further action is required
 - ➤ YES Replace the windshield and aim the front camera unit using the procedure outlined in the ESM (CRUISE CONTROL & DRIVER ASSISTANCE DRIVER ASSISTANCE SYSTEM DRIVER ASSISTANCE SYSTEM BASIC INSPECTION ADDITIONAL SERVICE WHEN REPLACING FRONT CAMERA UNIT)

PARTS INFORMATION:			
Description	Part #	Quantity	
Glass-Windshield	72700-6LB0B	1	

EXPENSE CODES: FOR USE WITH WINDSHIELD REPLACMENT ONLY					
Code #	Description	Amount (MAX)			
515	Miscellaneous Glass Repair (Urethane/Primer)	\$150			

CLAIMS INFORMATION

Submit claim using the following claims coding:

Work Order Line Type: "CM" Campaign

Campaign: PM937

Claim Tyne:

CIM				
PM937		NI	SSAN	
ZZ				
99		Innovation that excites		
Op Codes	Flat Rate Time	Parts Required on claim	Expense Code Required	
PM9370	0.2 Hr	NO	NO	
	4 4 1 1	\/=0	NO	
	ZZ 99 Op Codes PM9370	PM937 ZZ 99 Op Flat Rate Time PM9370 0.2 Hr	PM937 ZZ 99 Op Codes Flat Rate Required on claim	

CM