3/2/2020 Print Case



Solution K44250068 Monday, March 2, 2020 7:36:51 PM CET

** SOLUTION **

SOLUTION	
Title	Volvo Chassis - SNV 14-026 P111C Compressor Discharge Temperature Sensor
Volvo Models	
Volvo Model	VN , VNL , VNM , VNR , VNX , VAH , VHD
Emission Standard	
Emission Standard	US10+OBD13 , US14+OBD13 , US14+OBD15 , US14+OBD16 , US17+OBD16 , US17+OBD18 , US17+OBD19
Engine family	
Engine family	11L Engine , 13L Engine , 16L Engine
** SOLUTION **	
Cause	Volvo Trucks has received reports of diagnostic trouble code (DTC) P111C Compressor Discharge Temperature Sensor.
Solution	In the event that this fault is logged no action is required . Refer to $\underline{SNV14}$ - $\underline{026}$ for further information.
Solution visibility	Dealer distribution
Function(s)/compoi	nent(s) affected
Function affected	Engine
Function Group	
Function Group	284 control system, fuel supply , 286 engine wires and mounting parts
Customer effect	
Main customer effect	diagnostics/methodology, efficiency/abnormal behavior
Administration	
Author	a175606
Last modified by	RU4469V
Creation date	16-12-2015 17:12
Date of last update	06-02-2020 21:02

3/2/2020 Print Case

Status	Published
Variantes Kola	
DPX - ENGINE TYPE	ENG-VE11 - 11 L. VOLVO ENGINE , ENG-VE13 - 13 L. VOLVO ENGINE , ENG-VE16 -16 L. VOLVO ENGINE
KTX - ENGINE EMMISION CONTROL	EM-USA14

UNCONTROLLED COPY. Printed document is for temporary use only and should not be retained.

SERVICE NEWS



To: U.S. and Canada Volvo Dealer Principals

U.S. and Canada Volvo General Managers
U.S. and Canada Volvo Service Managers

Bulletin: SNV14-026
Date: August 22, 2014
Valid to: Until Further Notice

Replaces: N/A

Action Required? Yes

From: Greg Holderfield – Director, Product Reliability

Subject: P111C Compressor Discharge Temperature Sensor

Volvo Trucks has received reports of diagnostic trouble code (DTC) P111C (Compressor Discharge Temperature Sensor). In the event that this fault is logged **no action is required**. The compressor discharge temperature sensor is used to monitor the temperature of the air coming from the compressor side of the turbocharger. The engine control module (ECM) will set a diagnostic trouble code (DTC) P111C and **could** de-rate the engine to avoid engine or turbocharger damage. This fault will normally be triggered under severe operating conditions, climbing up a large grades or heavy loads, etc. P111C is only viewable through Tech Tool and is not reported to the Instrument Cluster driver display.

Note: Replacement of components for (DTC) P111C may result in claim denial.