



# Technical Service Bulletin

## 43 Suspension control module malfunction, DTC B200FF is stored in the drivetrain or electronic damping control module

43 20 32 2051336/2 April 3, 2020. Supersedes Technical Service Bulletin Group 43 number 18-29 dated May 22, 2018 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A4 allroad, S4, A5, A5 Cabriolet, S5, and S5, Sportback	2017 - 2021	All	Suspension with electronic damper control

## Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised title Revised header (Added Model Year and DTCs) Revised <i>Warranty</i> (Updated TU)
1	05/28/2018	Initial publication

### Customer states:

- The warning lamp for the damper control in the instrument cluster is on.

### Workshop findings:

The following DTC may be stored in the drivetrain control module, J775 (address word 0074) or in the electronic damping control module, J250 (address word 0014):

- DTC B200FF0** (internal malfunction) with symptom code 4456587.

## Technical Background

Not applicable.

## Production Solution

Not applicable.



# Technical Service Bulletin

---

## Service

The DTC does not affect the handling characteristics of the vehicle. Delete the DTC and perform suspension basic settings.

Perform GFF to ensure there are no other DTCs stored in the control module.



### Note:

Parts replacement does not solve this issue. Claims for replaced parts will be subject to review.

## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"><li>• 110 up to 48 Months/50,000 Miles.</li><li>• G10 for CPO Covered Vehicles – Verify Owner.</li><li>• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li></ul>		
<b>Service Number:</b>	4316		
<b>Damage Code:</b>	0040		
<b>Diagnostic Time:</b>	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
<b>Claim Comment:</b>	As per TSB #2051336/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

All parts and service references provided in this TSB (2051336) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any



# Technical Service Bulletin

---

time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.