

Service

153/19 ENU 2796

2

Symptom - Body Exterior - Hybrid Vehicle Cannot be Charged Using 208 V Main Power Supply. Install New Software on Porsche Mobile Charger (2nd generation). (SY 153/19)

Revision: This bulletin replaces bulletin Group 2, 153/19, dated March 18, 2020.

Model Year: As of 2017 up to 2020

Vehicle Type: Panamera Hybrid (971)

Cayenne Hybrid (9YA/9YB)

Equipment: Charging socket AC type 1 mode 2-3 (NAR/Japan) (I-no. ES1)

Subject: Porsche mobile charger (2nd generation charging cable)

Information: Hybrid vehicles with a Porsche mobile charger cannot be charged using the 208 V mains

power supply.

Affected part numbers:

Part No.	SW (old)	SW (new)
7PP971675AA/AB	0612 or 0613	0614
9Y0971675BA/BB	0126 or 0127	0128

Remedial Action:

Install new software on the Porsche mobile charger (2nd generation).

Tools:

- 9900 PIWIS Tester 3 with PIWIS test software version 39.100.035 (or higher) installed
- · VAS 611 009 Diagnostic adapter for high-voltage charging system

General information



Working on electric components

- Risk of burns
- · Risk of short circuit or fire.
- ⇒ Before replacing the power cable or vehicle cable, always disconnect the power cable from the electrical socket.
- ⇒ Only replace cables in a dry environment.

⇒ Porsche mobile charger may only be used as a unit comprising power cable, control unit and vehicle cable.




Information

Risk of damage to charging equipment.

Charging equipment can be operated in a temperature range from -13 °F to +95 °F /-25 °C to +35 °C.

Control unit must not be submerged in water or covered with snow or ice.

Do not expose Porsche mobile charger to direct sunlight over long periods to prevent it from overheating during operation.



Individual parts of Porsche mobile charger

- **A** Power cable
- **B** Power plug (connector for connecting to mains power supply)
- C Operator control unit
- D Vehicle plug (plug connection for the vehicle)
- Vehicle cable

Procedure:



Use of a PIWIS Tester software version that is older than the prescribed version

- Measure is ineffective
- ⇒ Always use the prescribed version or a higher version of the PIWIS Tester software for programming.



Information

The procedure described here is based on the PIWIS Tester 3 software version **39.100.035**.

The PIWIS Tester instructions take precedence and in the event of a discrepancy, these are the instructions that must be followed.

A discrepancy may arise with later software versions for example.

- 1 Disconnect Porsche mobile charger from the power supply.
- 2 Unplug the vehicle plug from the vehicle charge port.
- 3 Connect diagnostic adapter for high-voltage charging system to the Porsche mobile charger and 9900 - PIWIS Tester 3.
- 4 Connect diagnostic adapter for high-voltage charging system, Porsche mobile charger and 9900 - PIWIS Tester 3 to the power supply.



Connecting adapter

5 Switch on Porsche mobile charger ⇒ Porsche mobile charger - "arrow" -.



Information

If there is no data exchange between the PIWIS Tester and Porsche mobile charger, the Porsche mobile charger will switch off automatically after a while. To re-activate it, briefly press the On/Off switch on the Porsche mobile charger.



- 6 Start the PIWIS Tester.
- 7 Select **Diagnostics**.

Porsche mobile charger

- 8 Select the model line **external components** in the **manual model line selection** screen. ⇒ Continue ⇒ *Manual model line selection*.
- 9 Re-program Porsche mobile charger charging cable.

For specific information on control unit programming during this campaign, see the table below:



Manual model line selection

Required PIWIS Tester software version:	39.100.035 (or higher)
Type of control unit programming:	Charging cable programming using the 'Campaign' function in the Additional menu on the PIWIS Tester by entering a programming code.
Programming code:	X5X5J
Programming sequence:	Read and follow the information and instructions on the PIWIS Tester during the guided programming sequence. During the programming sequence, the Porsche mobile charger charging cable is re-programmed and then re-codedautomatically.
	Do not interrupt programming and coding.
Programming time (approx.):	20 minutes
Frogramming time (approx.).	20 minutes
Software version programmed during this campaign:	0614* or 0128*
Software version programmed during this	0614 * or

Service

153/19 ENU 2796

2

- * The software version programmed on the Porsche mobile charger depends on the software that was originally installed on the charger.
- 10 Once programming has been completed successfully, delete the fault memory. See *⇒ Workshop Manual '094095 Reading out Porsche universal charger (AC) high-voltage fault codes'*.
- 11 Switch off Porsche mobile charger.
- 12 Disconnect **diagnostic adapter for high-voltage charging system** and **9900 PIWIS Tester 3** from the Porsche mobile charger.

Invoicing

Invoicing:

For documentation and warranty invoicing, enter the labor operation and PQIS coding specified below in the warranty claim:

APOS	Labour operation	I No.
09062550	Programming battery charger	

PQIS coding:

Location (FES5)	0940	High-voltage charging cable
Damage type (SA4)	9735	Repair in accordance with PAG instructions

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2020 Porsche Cars North America, Inc.