



Subject: MAZDA CONNECT REBOOTS OR SCREEN TURNS BLACK DURING COLD TEMPERATURES	Bulletin No.: 09-015/20
	Last Issued: 06/03/2020

BULLETIN NOTES

This bulletin supersedes the previously issued bulletin(s) listed below. The changes are noted in Red.

Previously issued TSBs:	Date issued:
09-015/20	04/20/20 and 04/17/20
09-001/18	02/22/18 and 01/08/18

APPLICABLE MODEL(S)/VINS

- 2014-2016 Mazda3 (Japan built/Mexico built)
- 2017-2018 Mazda3 (Japan built) with VINs lower than JM1BN*****169265 (produced before September 12, 2017)
- 2017-2018 Mazda3 (Mexico built) with VINs lower than 3MZBN*****195058 (produced before December 19, 2017)
- 2016 Mazda6
- 2017 Mazda6 with VINs lower than JM1GL*****146174 (produced before September 12, 2017)
- 2016-2018 CX-3 with VINs lower than JM1DK*****313641 (produced before September 12, 2017)
- 2016 CX-5
- 2017 CX-5 with VINs lower than JM3KF*****214325 (produced before September 12, 2017)
- 2016-2018 CX-9 with VINs lower than JM3TC*****207204 (produced before September 12, 2017)
- 2016-2017 MX-5 (soft top) with VINs lower than JM1ND*****125203 (produced before September 12, 2017)
- 2017 MX-5 (RF) with VINs lower than JM1ND*****109425 (produced before September 12, 2017)

DESCRIPTION

Some customers may experience the MAZDA CONNECT rebooting or the screen turning black during cold temperatures. The concern occurs when the interior of the vehicle is cold and disappears when the interior warms up. This is caused by some SD cards for the MAZDA CONNECT navigation system being manufactured with improper hardware, resulting in a data reading error during cold temperatures. To correct the concern, the SD card hardware has been changed.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify customer concern.
2. Remove the SD card and check the last 6 digits of the lot number on the SD card.



- If the SD card has any of the following 6 digit lot numbers, replace it with a new SD card.

50424D	50631D	50635G	50881G	50955G
50428G	50632G	50877D	50913D	50995G

NOTE: The new SD card has a capacity of 16 GB, not 8 GB, like the original.

- If the SD card does not have any of these 6 digit lot numbers, this TSB is not applicable. Follow the instructions on MGSS for further diagnosis.

3. Verify repair.

PARTS INFORMATION

Parts Number	Description	Qty.	Notes
BHP1-66-EZ1M	SD Card Kit	1	Kit includes Navigation Owner's Manual

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	64
Damage Code	9W
Part Number Main Cause	BHP1-66-EZ1M
Quantity	1
Operation Number / Labor Hours:	XXN8DXRX / 0.2 Hrs.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.