

Technical Service Bulletin

GROUP	NUMBER	
CAMPAIGN	20-01-022H-1	
DATE	MODEL(S)	
JUNE, 2020	NEXO (FE) PALISADE (LX2) SANTA FE (TM)	

# SUBJECT: POWER TAILGATE SPINDLE WIRE HARNESS INSPECTION/REVISION (SERVICE CAMPAIGN T4X)

This TSB supersedes TSB# 20-01-022H to include the Santa Fe (TM).

### **\*** IMPORTANT

#### \*\*\* Dealer Stock and Retail Vehicles \*\*\*

Dealers must perform this Service Campaign on all affected vehicles prior to customer retail delivery and whenever an affected vehicle is in the shop for any maintenance or repair.

When a vehicle arrives at the Service Department, access Hyundai Motor America's "Vehicle Information Screen" via WEBDCS to identify open Campaigns.

**Description:** Some 2019 - 2020 Nexo (FE), 2020 Palisade (LX2), and 2019 - 2020 Santa Fe (TM) vehicles equipped with the power tailgate may not operate. This bulletin provides the service procedure to inspect and when necessary perform the power tailgate spindle wire harness revision.



**Applicable Vehicles:** Certain 2019 - 2020 Nexo (FE), 2020 Palisade (LX2), and 2019 - 2020 Santa Fe (TM) equipped with power tailgate.

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair

SUBJECT:	POWER TAILGATE SPINDLE WIRE HARNESS INSPECTION/REVISION
	(SERVICE CAMPAIGN T4X)

#### Parts Information:

PART NAME	PART NUMBER PART IMAGE		QTY.
LOCTITE 401	81831-S1101QQH		1 per vehicle
SYRINGE	81831-S1102QQH		1 per vehicle

#### Warranty Information:

MODEL	OP. CODE	OPERATION	OP. TIME	CAUSAL PART	NATURE	CAUSE
Nexo (FE) Palisade (LX2) Santa Fe (TM)	00D017R2	POWER TAILGATE	0.3 M/H	81831-S1101QQH	121	ZZ3
	00D017R3	POWER TAILGATE INSPECTION AND SPINDLE WIRE REVISION	0.3 M/H			

NOTE 1: Submit Claim on Campaign Claim Entry Screen NOTE 2: If a part is found in need of replacement while performing Service Campaign T4X and the affected part is still under warranty, submit a separate warranty claim using the same Repair Order. If the affected part is out of warranty, submit a Prior Approval Request for goodwill consideration prior to performing the work.

#### SUBJECT:

#### POWER TAILGATE SPINDLE WIRE HARNESS INSPECTION/REVISION (SERVICE CAMPAIGN T4X)

#### Service Procedure:

#### POWER TAILGATE SPINDLE WIRE HARNESS INSPECTION

1. Open the tailgate to inspect the LH/RH power tailgate spindle wiring harness (A).

2. Remove the rubber grommet (B) of the tailgate spindle wiring harness and inspect the material.

If the wire harness has a metallic shield (C), <u>no</u> <u>further action is required</u>.

If the wire harness shield does not have the metallic shield, perform the power tailgate spindle wire harness revision on page 4.



3.

#### POWER TAILGATE SPINDLE WIRE HARNESS INSPECTION/REVISION (SERVICE CAMPAIGN T4X)

## NOTICE

After inspecting the power tailgate spindle wire harness, reinstall and ensure the wire harness is not twisted (D) as shown in the picture to the right.




#### POWER TAILGATE SPINDLE WIRE HARNESS REVISION

## NOTICE

The tailgate spindle wire harness revision requires an injection of 0.2ml of Loctite 401 into the left side spindle wire harness sleeve and 0.2ml into the right side spindle wire harness sleeve.


- 1. Remove the Loctite 401 outer cap by performing the following procedure:
  - **1.** Align the top / bottom (A) of the cap as shown in the picture (B).
  - 2. Remove the cap by pulling upward.




#### SUBJECT:

#### POWER TAILGATE SPINDLE WIRE HARNESS INSPECTION/REVISION (SERVICE CAMPAIGN T4X)

- 2. Remove the Loctite 401 inner cap (C) by turning it counterclockwise.





3. Fill the syringe with 0.4ml (D) of Loctite.

4. Slowly press the plunger (E) inward, to remove any air from the syringe.

#### SUBJECT:

#### POWER TAILGATE SPINDLE WIRE HARNESS INSPECTION/REVISION (SERVICE CAMPAIGN T4X)


5. Carefully insert the syringe into the spindle wire harness sleeve approximately .5 inches away from the spindle (F). Inject 0.2ml of Loctite 401 into one side of the spindle wire harness, and the remaining 0.2ml into the other side.

## 

Be careful not to pierce the wire. Inject the Loctite 401 into the wire harness sleeve only.

Be careful to not spill the Loctite 401 liquid onto the vehicle's paint surface.





- Close the tailgate after injecting the Loctite 401 into both the left and right side spindle wire harness sleeves.
- 7. Properly dispose the syringe by placing it in the appropriate disposal container.

