Air recirculation flap malfunctions with fault code B105C07 and / or B113600 in ACC control units

Topic number
Version
Function group
Date
Validity
Reason for change
Reason for block

LI83.10-N-071291 1 83.10 Ventilation 06-02-2020 Model 907

Complaint:

Fault Code B105C07 the actuator motor for the air recirculation flap has a malfunction.

There is a mechanical fault current and stored in the AAC.

and / or

B113600 the measurement run for actuator motors for air flaps has a malfunction.

Cause: Under analysis

Normalization lost for the air conditioning flap actuators

Remedy:

Remedy 1

1. Connect XENTRY diagnosis and attempt normalization of the flap actuator motors. If normalization is successful procedure is complete, if not proceed to step 2

2. If normalization is unsuccessful, continue to Remedy 2.

Remedy 2

1. Switch off ignition

2. Remove passenger foot well cover and tool kit to access the recirculation flap actuator motor (see: remedy 2 motor location.jpg)

3. Remove the flap actuator motor from heater case with suitable tool (AR83.10-D-2041TS) (see: remedy 2 motor removal.jpg)

4. Check flap linkage for blockage by hand. If unimpeded movement is noted, reinstall the recirculation flap actuator motor with the linkage in horizontal orientation (middle of sweep) (see: remedy 2 linkage orientation)

5. Repeat normalization of the flap actuators via XENTRY diagnosis

6. Erase stored faults

Note: If remedy 2 is unsuccessful please open a PTSS case for processing.

Attachments			
File	Description		
remedy 2 motor location.jpg	Air recirculation flap actuator motor		
remedy 2 motor removal.jpg	Air recirculation flap actuator motor removal		
remedy 2 linkage orientation.jpg	Linkage orientation		

Symptoms
Body / Air conditioning / Heater / Malfunction, air distribution

Control unit/fault code		
Control unit	Fault code	Fault text
N22/1 - Air conditioning (AAC) (HVAC177)	B105C07	The actuator motor for the air recirculation flap has a malfunction. There is a mechanical fault. (HVAC_F907)
N22/1 - Air conditioning (AAC) (HVAC177)	B113600	The measurement run for actuator motors for air flaps has a mal- function (HVAC_F907)


Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
54-0650	ON-BOARD POWER SUPPLY VOLTA- GE MAINTAIN (WHEN CHECKING/TE- STING AND TROUBLESHOOTING)	0.1		
54-1011	PERFORM QUICKTEST	0.2		
83-3117	PERFROM NORMALIZATION OF AC- TUATOR MOTORS ON HEATING/VEN- TILATION/AC HOUSING	0.2	80460 73	
83-3139	FRESH AIR/RECIRCULATED AIR FLAP ACTUATOR MOTOR REMO- VE AND REINSTALL WITH LINKAGE CORRECTION	0.2		Only claim when performing remedy 2

WIS-References			
Document number	Title	Note	Allocation
AR83.10-D-2041TS	Remove/install fresh air/re- circulated air flap actuator motor		Remedy


Validity		
Vehicle	Engine	Transmission
Sprinter 907	*	*

Attachments

remedy 2 motor location. jpg:



remedy 2 motor removal. jpg:



XENTRY TIPS

remedy 2 linkage orientation.jpg:

