

45-09-05TT - Fault Code 01486 System Function Test Activated

Release date:

**Transaction No:** 

07/31/2020

## Condition

#### **ATTENTION:**

THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.

TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

## Applicable Vehicles

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All	1997- 2018	All	All	All	All

Revision Table						
Instance Number	Published Date	Version Number	Reason For Update			
2031562/4	7/31/20	45-09-05TT	To include additional models and model year applicability.			
2031562/3	9/27/17	TT 45-09-05	Update to latest standard.			
2031562/1	9/18/09	TT 45-09-05	Original publication			

# **Technical Background**

In some cases, the Electronic Stabilization Program (ESP) function test may not end on its own creating a 01486 fault code in the Antilock Brake System (ABS) -J104-.

### **Service**

The only way to end the test is to enter basic settings group 103 under address 03 – ABS. As soon as 103 is entered, the display should read "function test inactive" indicating it has been turned OFF. The "Activate" button **should not** be used.

Check ABS fault codes to see if the test was completed fully. If not, repeat using basic settings 93 or the test plan under Guided Functions.

#### **Additional Information**

© 2020 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.