



# Service Bulletin

Bulletin No.: 20-NA-130

Date: July, 2020


## INFORMATION

**Subject:** Information on Message Illuminated in DIC, DTC B094C (39) Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Bolt EV	2019	2020	—	—	All	All


<b>Involved Region or Country</b>	North America, Europe, Middle East, GM Korea Company
<b>Condition</b>	Some customers may comment on a message illuminated in the DIC. A technician may find DTC B094C (39) - Right Side Driver Assistance Systems set.
<b>Cause</b>	The cause of the condition may be corrosion in the LED wiring harness connection in the right outside rearview mirror.
<b>Correction</b>	Upon verifying the condition, follow the appropriate direction and steps in the Service Procedure below.

### Service Procedure



4533897

1. Remove the right outside rearview mirror housing bezel (2). Refer to *Outside Rearview Mirror Housing Bezel Replacement* in SI.



4811651

2. Inspect the LED circuit in the mirror for corrosion. Refer to Rear Cross Traffic Alert (UFG) and Side Object Detection (UKC) (Document ID #4817118) in SI.
  - If any corrosion IS found, it will be necessary to replace the mirror assembly. Refer to *Outside Rearview Mirror Replacement* in SI.
  - If NO corrosion is found, reinstall the mirror and follow the DTC B094C diagnostics referenced in SI.

### Parts Information

Use the VIN and refer to the GM Electronic Parts Catalog (EPC) to determine the proper part to order.

Causal Part	Description	Part Number	Qty
X	MIRROR ASM-O/ S RR VIEW	42553500	1
		42736385	
		42690694	
		42736379	
		42690697	
		42690696	

## Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2050220	Outside Rearview Mirror Replacement	Use Published Labor Operation Time

Version	1
Modified	Released July 15, 2020

