

Federal Recall Information

20PBE

Supplier

Watson and Chalin

Description

Watson Chalin Lift Axle Pivot Bolts - NHTSA: 20V506 / TC: 2020-399

Release Date

9/16/2020

Introduction

Peterbilt has decided that a condition could exist in certain model 348, 365, 367, 389, 520, and 567 vehicles built between 11/19/2019 and 4/09/2020. Vehicles equipped with Watson & Chalin SL2065 lift axles may have lower rear pivot bolts that are not long enough to sufficiently engage the locking feature of the corresponding nuts. In some cases, this condition may cause a loss of clamp load of the pivot joint (arm to axle). Extended use of the lift axle in this condition can result in foreign object debris on the roadway, increasing the risk of a crash and/or injury.

Resolution

Safety Recall

Service all affected chassis that enter your dealership, even if the customer has no issue with the chassis.

- 1. Review the attached chassis list for your dealer code and schedule your customer(s) for service if their chassis is on the list.
- If you are not using Service Management to start repair orders, review SIR for "Complete" or "In Process" next to the "20PBE" campaign code prior to performing this repair.
- 3. Follow the procedures below to inspect the lower rear pivot bolt and replace with longer bolts if necessary.

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Warranty

There is no time or mileage limit for this recall. Peterbilt will pay for parts at dealer net plus applicable mark up and labor:

- 1.0 hour to inspect the thread engagement of the Pivot Bolts.
- This labor is for inspection only. It is not applicable for trucks that require Pivot Bolt replacement.
- 1.5 hours to inspect the thread engagement of the Pivot Bolts and replace with the hardware kit that includes longer bolts.
- File a long form claim.

For Field	Enter
Failure Location	016-014-000

Failure Type	705
Claim Type	С
Campaign Number	20PBE
Labor	 016-358 1.0 hour to inspect both lift axle pivot bolts for thread engagement. 016-359 0.5 hours to replace both lift axle pivot bolts using the hardware kit.

Take off parts disposition: Destroy parts 30 days after the claim has been paid.

<u>Parts</u>

Parts are available from PACCAR Parts through DSP.


Place DSP orders for this campaign on an individual PO for freight pre-paid. Freight cannot be submitted in your warranty claim.

Quantity	Part Number	Description
1	SRK2065WAR-001	Hardware kit – Bolts, Washers, Locknuts required for both sides of the lift axle.

Procedure

- 1. Review the attached Pivot Bolt Inspection Procedure.
- 2. If the thread engagement of the pivot bolts does not meet the requirements as described in the Pivot Bolt Inspection Procedure, follow the procedure in the attached Pivot Bolt Replacement Procedure.
- 3. It is required that the following are attached to the claim:
 - A clear photo showing the bolt and the nut with insufficient thread engagement.
 - The model of the truck.
 - The serial number for the axle see serial number location in Figure 1.

Figure 1



Attachments

<u>Pivot Bolt Inspection Procedure</u> <u>Pivot Bolt Replacement Procedure</u> <u>Chassis List</u> <u>US Customer Letter</u> <u>Canada Customer Letter – English</u> <u>Canada Customer Letter – French</u>

Revision History

10/01/2020 - Added details to the Parts section involving freight.

09/18/2020 - Updated the procedure links to link directly to the Watson and Chalin website.

Authored by: PR

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2020 PACCAR Inc. All rights reserved. We welcome your <u>feedback</u> on this page. For technical questions or concerns about this page, please contact the <u>DealerNet Webmaster</u>.

Select the date.

IMPORTANT SAFETY RECALL

This notice applies to your vehicle. Your VIN(s) can be found on the bottom or back of this page.

Subject: Safety Recall: 20PBE - Watson & Chalin Lift Axle Pivot Bolt NHTSA: 20V506 EXPIRATION DATE: NONE

Dear Peterbilt Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Peterbilt has decided that a defect which relates to motor vehicle safety may exist in certain Model 348, 365, 367, 389, 520 and 567 vehicles manufactured between November 19, 2019 and April 9, 2020. Vehicles equipped with Watson & Chalin SL2065 lift axles may have lower rear pivot bolts that are not long enough to sufficiently engage the locking feature of the corresponding nuts. In some cases, this condition may cause a loss of clamp load of the pivot joint (arm to axle). Extended use of the lift axle in this condition can result in foreign object debris on the roadway and increase the risk of a crash or injury.

What is the problem?	The lower rear pivot bolts on the lift axle could lose clamp load.
What will your dealer do?	Your dealer will inspect the bolts for proper thread engagement and, if necessary, replace the hardware with longer bolts.
What should you do?	Contact your dealer immediately to schedule an appointment.

Peterbilt Motors Company has initiated this recall to remedy the issue at no charge to you. Please contact your Peterbilt dealer to schedule an appointment for these services. To find your Peterbilt dealer, please visit the Dealer Locator at www.Peterbilt.com or scan the QR code. When contacting your Peterbilt dealer, reference the Safety Recall number and the NHTSA number. This repair may take up to 2 hours of labor depending on dealer scheduling.

If you had this repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. Receipts for parts or labor are required for consideration of reimbursement. Contact your local Peterbilt dealership for details.

If you require further information about this recall, or experience any difficulty in making arrangements for this repair, please contact: Peterbilt Motors Company, 1700 Woodbrook St, Denton, TX 76205, Attn: Customer Services Department, phone 940-591-4220.

If you conclude that Peterbilt has not enabled you to remedy this defect in a reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to http://www.safercar.gov.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate you advising us of the new owner's name.

We apologize for any inconvenience this preventive procedure may cause and thank you for your participation in helping Peterbilt provide the highest levels of customer satisfaction and service expertise. We value your business and appreciate your ongoing loyalty to Peterbilt and its dealer network. Industry-leading quality, performance and reliability are hallmarks of Peterbilt products, and we thank you for making Peterbilt your truck of choice. Sincerely,

M. du For

Michelle Ponsonby Director of Customer Service Peterbilt Motors Company

Scan this QR code to open the Peterbilt Dealer Locator.

