



No.: 17TS-05Rev2
October 2020

TO: Service Locations

FROM: Service Systems Development


SUBJECT: **Detroit™ DT12™ TCM GHG17 Only; Bootloader Update**

ISSUE

On Detroit™ DT12™ equipped vehicles, it may be necessary to complete an additional step in the programming process when updating the TCM software.

REQUIRED ACTION

1. To improve the programming success rate, a hard-wired connection from DiagnosticLink® to the vehicle is preferred. Connect DiagnosticLink version 8.12 with Service Pack 2 (or higher versions) on the Identification Tab and check the TCM01T Hardware Part Number. Is the TCM Hardware Part Number listed as A0504463109 ZGS **901** or A0504463409 ZGS **901**?
 - a. Yes; special programing steps are **NOT** necessary and you may continue to program the powertrain modules as usual with Model Year 2020 package.
 - b. No; the TCM Hardware Part Number level is either A0504463109 ZGS **001** or A0504463409 ZGs **001**. Continue to step 2.



- 2. Connect DiagnosticLink® version 8.12 with Service Pack 2 (or higher). Download Unit Data from server and note the TCM01T Hardware Part Number (last 3 digits are **001**).

Request Equipment Data Download

Enter the identity of the equipment you wish to program.

Vehicle Identification (VIN/PIN)
1FUJGLDR0GLZZ3415

Engine Serial Number (Unit Number)
472910S0356782


Device controllers for this equipment

+ Add - Remove


Device	Hardware Part Number
CPC04T	A0034461102-002
MCM21T	A0014465835-002
TCM01T	A0504463109-001
IPPC01T	A0004460675-001
ICU4ME	06-84378-001
SAMCAB_P3	06-74862-000
CGW03T	06-93359-001
RDF01T	A0004461649-001
MSF_P3	06-66446-002

Clear All OK Cancel


3. After download, select "Next".




4. Select TCM01T, then "Update Device Software". Select bootloader software NAMT154601, and then select "Next".




5. Make sure software NAMT154601 is correct and then select "Start".




6. Programming will fail at the step highlighted below -- "Data Implausible – reconnected in boot mode". This is an expected error.




7. Navigate back to the “Identification” screen and you will see TCM01T is “Running in Boot”. Again, this is an expected result.



8. Reselect “Program Device” tab, and select the “Back” button.



9. Highlight the VIN, select “Remove” and then select “Add” to reload the VIN.



10. After the VIN has been re-added, notice TCM01T Hardware Part Number has changed (last 3 digits are now 901). Select "OK" and connect to the server. **Note: You may have to manually connect to the TCM prior to downloading server data; see steps 11 and 12 for manual connection details.** If a manual connection is not necessary, go to Step 14.

Request Equipment Data Download

Enter the identity of the equipment you wish to program.

Vehicle Identification (VIN/PIN)
1FUJGLDR0GLZZ3415

Engine Serial Number (Unit Number)
472910S0356782



Device controllers for this equipment

+ Add - Remove


	Device	Hardware Part Number
	CPC04T	A0034461102-002
	MCM21T	A0014465835-002
▶	TCM01T	A0504463109-901
	ICU4ME	06-84378-001
	SAMCAB_P3	06-74862-000
	CGW03T	06-93359-001
	RDF01T	A0004461649-001
	MSF_P3	06-66446-002
	ACM21T	A0004464654-003

Clear All OK Cancel


11. This step and step 12 show how to manually connect to the TCM.




12. Connect to server, and download unit data.




13. If not connected after download, make a manual connection to the TCM. (Refer back to Steps 11 & 12 for manual connection instructions.) After a connection is made, continue to Step 14.






14. Verify TCM software NAMT191402 and select "Start" to complete programming.



15. Verify programming was successful.



16. After programming is complete, navigate to Identification tab and verify TCM software, NAMT191402. Continue to program the powertrain modules with Model Year 2020 applicable software versions as usual. Refer to DTNA Connect → Detroit Service Information → Service Info Page → Software Versions.

NOTE: DO NOT PERFORM A TRANSMISSION LEARN. DO NOT PERFORM A CLUTCH LEARN. LEARNED VALUES ARE RETAINED DURING THE PROGRAMMING EVENT.

CONTACT INFORMATION

Please contact the Detroit® Customer Support Center at 800-445-1980 or email csc@daimler.com if you have any questions.