

Double Check Vehicle Application When Ordering Hybrid E-Machines

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Panamera (Hybrid)	2012 - 2017	970	N/A	N/A
Cayenne (Hybrid)	2012 - 2017	92A	N/A	N/A

Revision History

Revision	Release Date	Changes
0	October 28, 2020	Original document

Condition

Hybrid and Plug-In Hybrid models use different e-machines. Some dealers have ordered **and installed** the incorrect e-machine because they did not observe the production breaks shown in PET. (See figure 1.)

POS	PART NUMBER	NAME	REMARK	QTY	MODEL
(1)	958 624 152 02	electric motor F 97-CL041 052>> F A7-CL045 410>> See technical information	106/19	1	
(1)	958 624 152 CX	electric motor F 97-CL041 052>> F A7-CL045 410>> See technical information	106/19	1	
(1)	970 117 010 13	electric motor D - MJ 2014>> See technical information	106/19	1	
(1)	970 117 010 FX	electric motor D - MJ 2014>> See technical information	106/19	1	

Figure 1

Technical Background

An incorrect part will always cause problems for the customer, such as ineffective repairs and unnecessary delays. In this case, installing the incorrect part may also generate fault code POBFF00.

Service Information

Be sure to order a part that is consistent with the production breaks shown in PET. In figure 1, there is a production break defined by VIN (marked with an "A") and a production break defined by model year (marked with a "B"). In this case, the dealer should order one of the parts marked with "A" if the vehicle's **VIN** falls within the range given. On the other hand, the dealer should order one of the parts marked with "B" if the vehicle's **model year** is at or above the year shown.

Search Items

E-machine, electric motor, PHEV, SE

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.
