

**HARD START/NO START/LOSS OF ENGINE RPM AFTER REFUELING -
BUILT ON OR BEFORE 11/9/2013****TSB 16-0075****FORD:**

2013 Escape

2013-2014 Fusion

LINCOLN:

2013-2014 MKZ

ISSUE

Some 2013 Escape, 2013-2014 Fusion and MKZ vehicles built on or before 11/9/2013 may exhibit a hard start, no start and/or a loss of engine RPM after refueling. Some vehicles may also exhibit an illuminated malfunction indicator lamp (MIL) with diagnostic trouble code (DTC) P1450 and/or P0456 stored in powertrain control module (PCM) memory.

ACTION

Follow the Service Procedure steps to correct the condition.

SERVICE PROCEDURE

Replace the evaporative emission canister purge valve. Refer to Workshop Manual (WSM), Section 303-13.

PART NUMBER	PART NAME
GG9Z-9D289-C	Evaporative Emission Canister Purge Valve - Fusion/MKZ 1.5L
DG9Z-9D289-G	Evaporative Emission Canister Purge Valve - Fusion/MKZ 1.6L
DG9Z-9D289-D	Evaporative Emission Canister Purge Valve - Fusion/MKZ 2.0L
CV6Z-9D289-B	Evaporative Emission Canister Purge Valve - Escape 1.6L
CV6Z-9D289-R	Evaporative Emission Canister Purge Valve - Escape 2.0L

OPERATION	DESCRIPTION	TIME
160075A	2014 Fusion 1.5 GTDI, 2013-2014 Fusion 1.6L: Retrieve DTCs And Replace The Evaporative Emission Canister Purge Valve (Do Not Use With Any Other Labor Operations)	0.5 Hr.
160075A	2013 Escape 1.6L GTDI: Retrieve DTCs And Replace The Evaporative Emission Canister Purge Valve (Do Not Use With Any Other Labor Operations)	0.8 Hr.
160075A	2013 Escape 2.0L GTDI: Retrieve DTCs And Replace The Evaporative Emission Canister Purge Valve (Do Not Use With Any Other Labor Operations)	0.7 Hr.
160075A	2013-2014 Fusion/MKZ 2.0L GTDI: Retrieve DTCs And Replace The Evaporative Emission Canister Purge Valve (Do Not Use With Any Other Labor Operations)	1.0 Hr.

WARRANTY STATUS:

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage And Emissions Warranty Coverage
Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.

DEALER CODING

BASIC PART NO.	CONDITION CODE
9D289	42