

H295NAS1 UPS5420-1B

TECHNICAL BULLETIN

12 NOV 2020



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

SECTION:

100-00

SUBJECT/CONCERN:

Update Prior to Sale: Battery Charge Control Module (BCCM) Software Update

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:
I-PACE (X590)	2019	F60174-F76735
I-PACE (X590)	2020	F76973-F90426
I-PACE (X590)	2020	600001-605261

MARKETS:

CANADA, USA

CONDITION SUMMARY:

This bulletin does not apply to any vehicles already registered and in use, either with the retailer or customer. Any vehicle already in use may continue to be driven and any repair instructions will be communicated through a separate bulletin.

SITUATION:

A potential issue has been identified on certain Jaguar vehicles within the listed Affected Vehicle Range which may experience a loss of Alternating Current (AC) and Direct Current (DC) charging functionality.

ACTION:

Retailers are required to HOLD affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the procedure(s) detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but must have it completed prior to vehicle handover to the customer.

WARRANTY INFORMATION:**NOTE:**

Use the Jaguar Land Rover claims submission system to make sure that a vehicle is eligible for this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, make sure that all open Recall and Service Actions are identified to make sure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code and the relevant Option Code; this will result in payment of the stated time. The SRO and parts information is included for information only. The Option Code(s) that allows for the drive in/drive out allowance may only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times/prices are subject to change; those quoted here must be taken as guidance only. Use TOPIx to obtain the latest repair time.

This program is valid for a limited time only. Warranty claims with a repair date prior to the November 30, 2021 closure date must be submitted or payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)
H295	A	Battery Charger Control Module (BCCM) - Update - Replace ECU	85.86.18	0.2
H295	B	BCCM - Update - Replace ECU Drive in/drive out	85.86.18 10.10.10	0.2 0.2

Normal Warranty policies and procedures apply.

DIAGNOSTIC INSTRUCTION:

CAUTION:

All ignition ON/OFF requests **MUST** be performed; failure to do so may cause damage to vehicle control modules.

1.

CAUTION:

A Jaguar Land Rover-approved battery support unit must be connected to the vehicle startup battery during diagnosis / module programming.

Connect the Jaguar Land Rover-approved battery support unit to the vehicle startup battery.

2.

NOTE:

The Jaguar Land Rover-approved diagnostic equipment must be loaded with PATHFINDER version 305 (or later).

Connect the Jaguar Land Rover-approved diagnostic equipment to the vehicle and begin a new session.

3. Follow all on-screen instructions.

- 1. Select 'ECU Diagnostics'.
- 2. Select 'Battery Charger Control Module [BCCM]'.
- 3. Select 'Update ECU'.
- 4. Follow the on-screen instructions until the application finishes successfully.

4. **Only if required:** set the vehicle to Transit mode.

- 1. Follow the on-screen instructions until the application finishes successfully.

5. Exit the current session.

6. Disconnect the diagnostic equipment and battery support unit from the vehicle.