

H299NAS1

TECHNICAL BULLETIN

02 NOV 2020



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

SECTION:

303-14

SUBJECT/CONCERN:

Service Action: Variable Camshaft Timing (VCT) Solenoids

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	APPLICABILITY:
E-PACE (X540)	2018-2020	Z00291-Z74881	INGENIUM I4 2.0L Petrol
F-PACE (X761)	2018-2019	201651-399997	INGENIUM I4 2.0L Petrol
F-PACE (X761)	2019-2020	600006-625494	INGENIUM I4 2.0L Petrol
F-TYPE (X152)	2018-2020	K51500-K66534	INGENIUM I4 2.0L Petrol
XE (X760)	2018-2020	P26716-P60039	INGENIUM I4 2.0L Petrol

MODEL:	MODEL YEAR:	VIN:	APPLICABILITY:
XF (X260)	2018-2020	Y58519-Y85156	INGENIUM I4 2.0L Petrol

MARKETS:

CANADA; USA

CONDITION SUMMARY:

SITUATION:

A potential issue has been identified on certain Jaguar vehicles with the INGENIUM I4 2.0L Petrol engine within the listed Affected Vehicle Range which may exhibit one or more of the following:

- Driveability flat spots;
- Malfunction Indicator Lamp (MIL) illuminated with Variable Camshaft Timing (VCT) Diagnostic Trouble Code(s) (DTC) stored in the Powertrain Control Module (PCM);
- Increased induction noise while driving; and/or
- A small reduction in performance.

ACTION:

Retailers are required to HOLD affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the procedure(s) detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but must have it completed prior to vehicle handover to the customer.

Affected vehicles already in the hands of customers should be updated at the next available opportunity.

PARTS INFORMATION:**NOTE:**

Use the Vehicle Identification Number (VIN) and the Electronic Parts Catalogue (EPC) to confirm part number(s) necessary to perform repairs.

DESCRIPTION	PART NUMBER	QUANTITY
VCT solenoid	T4N32636	2

WARRANTY INFORMATION:**NOTE:**

Use the Jaguar Land Rover claims submission system to make sure that a vehicle is eligible for this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, make sure that all open Recall and Service Actions are identified to make sure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code and the relevant Option Code; this will result in payment of the stated time. The SRO and parts information is included for information only. The Option Code(s) that allows for the drive in/drive out allowance may only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times/prices are subject to change; those quoted here must be taken as guidance only. Use TOPIx to obtain the latest repair time.

This program is valid for a limited time only. Warranty claims with a repair date prior to the October 31, 2022 closure date must be submitted or payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART NUMBER	QUANTITY
H299	A	Variable Camshaft Timing Solenoid - Engine Set - Renew	18.31.51	E-PACE: 0.3 F-PACE, XE, XF: 0.6 F-TYPE: 0.2	T4N32636	2
H299	B	Variable Camshaft Timing Solenoid - Engine Set - Renew	18.31.51	E-PACE: 0.3 F-PACE, XE, XF: 0.6 F-TYPE: 0.2	T4N32636	2
		Drive in/drive out	10.10.10	All: 0.2	-	-

Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

1. Renew both VCT solenoids (see TOPIx Workshop Manual section 303-14: Electronic Engine Controls - INGENIUM I4 2.0L Petrol - Remove and Installation - Variable Camshaft Timing Solenoid).