# Polestar

# Service and Parts Business

# **Technical Journal**

## TITLE:

# Diagnose of HV system after HVCH malfunction

REF NO: TJ 35721.3.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada		
	PARTNER: 3 US 7515	ISSUE DATE: 2020-11-03	STATUS DATE: 2020-11-06	
FUNC GROUP: 8760	FUNC DESC: Auxiliary heater, electrically operated	Page	1 of 3	

#### **Attachment**

File Name	File Size
TJ 35721.jpg	0.1643 MB

# **Vehicle Type**

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
534							2021-2021	19	0000001-9999999	202007-999952

## **CSC** Customer Symptom Codes

Code	Description
BE	Starting/Engine does not start/Engine does not turn/Unsure when/at all times
BJ	Starting/Engine does not start/Unsure when/at all times

# **VST** Operation Number

VST Operation Number	Description			
36050-2	Calibrating/Identifying with VIDA			
31130-2	High Voltage Battery, disconnecting and connecting			

## **DTC** Diagnostic Trouble Codes

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

# Technical Journal 35721.3.0

#### **DESCRIPTION:**

\* This TJ is rewritten in its entirety

If confirmed HVCH malfunction, please follow advice under service.

#### SERVICE:

If a defect is found with the HVCH causing an isolation warning, before replacement of the HVCH perform a test of high voltage battery pre-charge contactor. This is to determine if the pre-charge resistor has been damaged. If the result confirms the pre-charge resistor is damaged, also replace the complete BDU.

High voltage battery contactor test found in Vida as follow: Planning & Diagnostics->Components->ECUs->Battery Energy Control Module->Diagnostic Sequences
If high voltage battery contactor test result is ok, please remove the MSD to prevent further stress on pre-charge resistor.

After HVCH replacement please test the 3-phase AC Charging circuit to determine if the OBC has been damaged. This has to be done on an 11kW and above power charge station to utilize 3-phase charging. If a red indication is present in the EVI Charging Inlet, please follow fault tracing according to VIDA.

HVCH = High Voltage Coolant Heater BDU = Battery Disconnect Unit MSD = Manual Service Disconnector OBC = On Board Charger EVI = Electrical Vehicle Inlet

#### Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data: VST OP number: 36050-2 VST OP number: 31130-2 36050-2 Calibrating/Identifying with VIDA 31130-2 High Voltage Battery, disconnecting and connecting


#### **VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report Polestar" and sub concern area "Support needed Polestar", use function group 3113.

o view TJ attachment continue to next page. This TJ has one attachment.

Page 2 of 3 2020-11-06

# **Technical Journal 35721.3.0**



2020-11-06 Page 3 of 3