

Technical Information

Service

119/20 ENU 7413

Complaint - Creases on Seat Surface/Side Bolster of Front Seat and Ridge Formation on Seat Surface of Rear Seat: Replacing Cover and Padding (119/20)

Change overview

Version	Date	Change
0	August 14, 2020	First publication
1	September 3, 2020	"Ridge formation on seat surface of rear seat" added
2	December 16, 2020	 Parts added "Heating element for seat cushion", front/rear Reference to Workshop Manual "Replacing heating element" added under "Remedial action"

Model Line: Cayenne (9YA/9YB)

Model Year: As of 2018 up to 2020


Subject: Front and rear seat

Information: Leather stretching and compression in conjunction with an entry height typical for SUVs results in

permanent creases in the seat covers and side bolsters of the front seats \Rightarrow Wrinkling on front seat

-Arrows-.

This also causes ridge formation on the seat surfaces of the rear seats \Rightarrow *Ridge formation on rear seat* -**Arrows**-.



Wrinkling on front seat



Ridge formation on rear seat

Remedial Action:

In the event of a customer complaint and on vehicles produced before the date of introduction specified below, replace padding and seat cover, see

- ⇒ Workshop Manual '741319 Removing and installing cover for front seat'
- ⇒ Workshop Manual '741055 Replacing padding for front seat'
- ⇒ Workshop Manual '742855 Replacing heating element for front seat'
- ⇒ Workshop Manual '74501901 Removing and installing cover for rear seat (2/3-split folding rear seat)'
- ⇒ Workshop Manual '74495501 Replacing padding for rear seat surface (2/3-split folding rear seat)'
- ⇒ Workshop Manual '74501902 Removing and installing cover for rear seat (1/3-split folding rear seat)'
- ⇒ Workshop Manual '74495502 Replacing padding for rear seat surface (1/3-split folding rear seat)'
- ⇒ Workshop Manual '743055 Replacing heating element for rear seat cushion'

The relevant date of introduction of the seat can be found in the table under \Rightarrow *Technical Information '743055 Date of introduction'*.



Information

In an effort to minimize the normal effect of leather stretching, Porsche has made a change to the seat cover. Based on the introduction dates below, optimized padding and seat covers, now also available for customer service, have been installed during production. This will provide additional support to the leather and should help the new look last for a much longer time.

Dates of introduction of new seat covers in production

Front seat

Seat	I-No. of seat	Date of introduction
Standard seat	Q1A	06/01/2020
Comfort seat	Q2J	06/15/2020
Sports seat	Q1D and Q1J	06/15/2020

Service

119/20 ENU 7413

Rear seat

Seat	I-No. of seat	Leather	I-No. of leather	Date of introduction
Standard seat	Q1A	Partial leather, embossed	N1X and 4D0	02/26/.2020
		Plain leather	NSU and 4D0	05/06/2020
		Plain leather	N5U or NOQ and 4D0 or 4D3 or 4D5	02/25/2020
	Q2J		With NOQ and 4D1 or 4D9	05/20/2020
Comfort seat		Club leather	N1W or N1V and 4D0 or 4D3 or 4D5	03/02/2020
	3NS	Plain leather	K5A and NOQ or N1T or N5T or N5U	02/24/2020
		Club leather	K5A and N1W and N1V	03/03/2020
			NOQ or N1T and 4D1	06/12/2020
			N5U or NOQ and 4D0 or 4D3	03/09/2020
	Q1J	Plain leather	N5T and 3J4 or 3J7 or 5ZF	03/09/2020
Sports seat			N1T and 4D0 or 4D3	05/28/2020
			N5T and 5ZJ	05/28/2020
		Club leather	N1W or N1V and 4D0 or 4D3	05/07/2020
	2NE	Diain loather	K5A and N5U or NOQ	03/13/2020
	3NE	Plain leather	N5T and 3J7 or 5ZF	03/13/2020

Technical Information

Parts required if necessary

Parts Info for front seat:	Part No.	Designation - Use	Qty.
	N 91205201	\Rightarrow Cheese head bolt with multiple-tooth head	4 ea.
	9Y0881405*	⇒ Seat cover – front left seat	1 ea.
	9Y0881406*	⇒ Seat cover – front right seat	1 ea.
	9Y0881375*	⇒ Foam part of seat cushion – front left seat	1 ea.
	9Y0881376*	⇒ Foam part of seat cushion– front right seat	1 ea.
	9Y0963555*	⇒ Heating element for seat cushion– Front seat (left/right)	1 ea.
	9Y0881256*	⇒ Repair kit ¹⁾	1 ea.

^{*} Part number varies depending on equipment.

¹⁾ only for NAR vehicles with seat occupancy detection (I-no. 9P7).

Parts Info for	Part No.	Designation	Qty.
rear seat:		- Use	
	PAB88637300	⇒ Fixing clip for seat cushion	5 ea.
		- rear left seat (2/3-split folding rear seat) and rear	
		right seat (1/3-split folding rear seat)	
	9Y0885405*	⇒ Seat cover	1 ea.
		- rear left seat (2/3-split folding rear seat) with I-No.	
		Q1A, Q2J and Q1J	
	9Y0885406*	⇒ Seat cover	1 ea.
		- rear right seat (1/3-split folding rear seat) with I-No.	
		Q1A, Q2J or Q1J	
	9Y3885405*	⇒ Seat cover	1 ea.
		- rear left seat (2/3-split folding rear seat) with I-No.	
		3NS or 3NE	
	9Y3885406*	⇒ Seat cover	1 ea.
		- rear right seat (1/3-split folding rear seat) with I-No.	
		3NS or 3NE	
	9Y0885375*	⇒ Foam part of seat cushion	1 ea.
		- rear left seat (2/3-split folding rear seat) with I-No.	
		Q1A, Q2J and Q1J	

Technical Information	Service		7
	119/20 _E	NU 7413	/

9Y0885376*	 ⇒ Foam part of seat cushion – rear right seat (1/3-split folding rear seat) with I-No. Q1A, Q2J or Q1J 	1 ea.
9Y3885375*	 ⇒ Foam part of seat cushion – rear left seat (2/3-split folding rear seat) with I-No. 3NS or 3NE 	1 ea.
9Y3885376*	 ⇒ Foam part of seat cushion – rear right seat (1/3-split folding rear seat) with I-No. 3NS or 3NE 	1 ea.
9Y0963561*	⇒ Seat heating element for seat cushionRear seat, left (2/3-split folding rear seat)	1 ea.
9Y0963562*	⇒ Seat heating element for seat cushionRear seat, right (1/3-split folding rear seat)	1 ea.

^{*} Part number varies depending on equipment.

Invoicing for front seat

Invoicing:

For documentation and warranty invoicing for enter the appropriate labor operations, PQIS coding and part numbers specified below in the warranty claim:

APOS	Labour operation	I No.
74105501	Replacing front left padding (basic seat)	
74105502	Replacing front right padding (basic seat)	
74105503	Replacing front left padding (comfort or sports seat)	
74105504	Replacing front left padding (comfort or sports seat)	

APOS	Labour operation	I No.
74131901	Replacing and installing front left cover (basic seat)	
74131902	Replacing and installing front right cover (basic seat)	
74131903	Replacing and installing front left cover (comfort or sports seat)	
74131904	Replacing and installing front right cover (comfort or sports seat)	

PQIS coding:

Location (FES5)	74130	Front seat cover
Damage type (SA4)	3042	wrinkling

Parts Info for front seat:	Part No.	Designation - Use	Qty.
	N 91205201	Cheese head bolt with multiple-tooth head	4 ea.
	9Y0881405*	Seat cover – Front seat, left	1 ea.
	9Y0881406*	Seat cover – Front seat, right	1 ea.
	9Y0881375*	Foam part of seat cushion – Front seat, left	1 ea.
	9Y0881376*	Foam part of seat cushion – Front seat, right	1 ea.
	9Y0963555*	Heating element for seat cushion – Front seat (left/right)	1 ea.
	9Y0881256*	Repair kit ¹⁾	1 ea.

^{*} Part number varies depending on equipment.

References:

⇒ Workshop Manual '741319 Removing and installing cover for front seat'

⇒ Workshop Manual '741055 Replacing padding for front seat'

Invoicing for rear seat

Invoicing:

For documentation and warranty invoicing, enter the appropriate labor operations, PQIS coding and part numbers specified below in the warranty claim:

APOS	Labour operation	I No.
74495501	Replacing padding for rear left seat surface (2/3-split folding rear seat) (includes removing and installing cover for rear left seat (2/3-split folding rear seat))	
74495502	Replacing padding for rear right seat surface (1/3-split folding rear seat) (includes removing and installing cover for rear right seat (1/3-split folding rear seat	

¹⁾ only for NAR vehicles with seat occupancy detection (I-no. 9P7).

Technical Information

Service

119/20 ENU 7413

7

PQIS coding:

Location (FES5)	74500	Rear seat cover
Damage type (SA4)	3042	ridge formation, wrinkled

Parts Info for rear seat:	Part No.	Designation - Use	Qty.
	PAB88637300	Fixing clip for seat cushion - Rear seat, left (2/3-split folding rear seat) and rear seat, right (1/3-split folding rear seat)	5 ea.
	9Y0885405*	Seat cover - Rear seat, left (2/3-split folding rear seat) with I-no. Q1A, Q2J and Q1J	1 ea.
	9Y0885406*	Seat cover - Rear seat, right (1/3-split folding rear seat) with I-no. Q1A, Q2J or Q1J	1 ea.
	9Y3885405*	Seat cover - Rear seat, left (2/3-split folding rear seat) with I-no. 3NS or 3NE	1 ea.
	9Y3885406*	Seat cover - Rear seat, right (1/3-split folding rear seat) with I-no. 3NS or 3NE	1 ea.
	9Y0885375*	Foam part of seat cushion Rear seat, left (2/3-split folding rear seat) with I-no. Q1A, Q2J and Q1J	1 ea.
	9Y0885376*	Foam part of seat cushion - Rear seat, right (1/3-split folding rear seat) with I-no. Q1A, Q2J or Q1J	1 ea.
	9Y3885375*	Foam part of seat cushion – Rear seat, left (2/3-split folding rear seat) with I-no. 3NS or 3NE	1 ea.
	9Y3885376*	Foam part of seat cushion - Rear seat, right (1/3-split folding rear seat) with I-no. 3NS or 3NE	1 ea.
	9Y0963561*	Seat heating element for seat cushion - Rear seat, left (2/3-split folding rear seat)	1 ea.
	9Y0963562*	Seat heating element for seat cushion - Rear seat, right (1/3-split folding rear seat)	1 ea.

^{*} Part number varies depending on equipment.

References:

- ⇒ Workshop Manual '74501901 Removing and installing cover for rear seat (2/3-split folding rear seat)'
- ⇒ Workshop Manual '74495501 Replacing padding for rear seat surface (2/3-split folding rear seat)'
- ⇒ Workshop Manual '74501902 Removing and installing rear seat cover (1/3-split folding rear seat)'
- ⇒ Workshop Manual '74495502 Replacing padding for rear seat surface (1/3-split folding rear seat)'

Service
7413 ENU 119/20

Technical Information

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2020 Porsche Cars North America, Inc.

Dec 16, 2020 Page 8 of 8