



69-20-02 - Update Programming, DTC B101612 Stored

Release date: 1/25/2021

Condition

| Applicable Vehicles | | | | | |
|---------------------|-----------|-----------|-------------|----------------|--------------|
| Model(s) | Year | Eng. Code | Trans. Code | VIN Range From | VIN Range To |
| Atlas | 2019-2021 | All | All | CA_KC530794 | CA_MC521445 |
| Atlas Cross Sport | 2020 | All | All | CA_LC200001 | CA_LC225415 |

| Revision Table | | | |
|-----------------|----------------|----------------|---|
| Instance Number | Published Date | Version Number | Reason For Update |
| 2061220/4 | 1/25/21 | 69-20-02 | To update service number in warranty table. |
| 2061220/2 | 11/11/20 | 69-20-02 | Administrative. |
| 2061220/1 | 10/29/20 | 69-20-02 | Original publication. |

One or more of the following fault codes may be stored in the Airbag Control Module (0015) -~~J234~~- Fault Memory:

| DTC | Description |
|---------|--|
| B101612 | Passenger airbag disabled light short to Vbat. |



Note:

DO NOT diagnose or replace components due to DTC B101612 faults **before** performing the update function as explained in this bulletin.



69-20-02 - Update Programming, DTC B101612 Stored

Release date: 1/25/2021

Technical Background

Airbag icon illuminated in Instrument Cluster -~~KX2~~-.

Updated programming of the Airbag Control Module (0015) -~~J234~~- software is based on most recent engineering experiences and makes this knowledge available for the monitoring strategies.

Production Solution

Improved software in production since August 13, 2020.

Service

Update-Programming Procedure:

Critical Warning: : The Midtronics battery charger **must** be connected to the vehicle battery for the duration of the programming, to ensure the battery state of charge remains above 12.5 volts during the update process. If the battery drops below 12.5 volts, the programming could fail which may result in damage to the control module. Control modules damaged by inadequate voltage will not be covered under the warranty policy. The technician should verify the vehicle voltage prior to starting the update process, and should monitor the voltage for the duration of the update.

The procedure may cancel itself if the hazard warning lights are not switched ON. The hazard warning lights prevent the system from switching to bus sleep mode during the update.

ODIS-Service tester should be updated to the latest GFF technical version 2.40.15 or higher and SW version 6.2.0. or higher.



Note:

Prior to launching the ODIS Service diagnostic applications and starting control module update process, confirm tester screen saver and power settings in accordance with Diagnostic Device Hardware & Windows® - VHW-20-02 Change Power Options After Windows®10 Upgrade. Failure to do so may result in the tester entering power save mode during data transfer, and subsequent control module failure. When using a VAS 6150/X or 6160/X tester in conjunction with a VAS 6154 wireless transmitter head for a flash procedure, connect a USB cable between the transmitter head and the tester. Failure to do so may lead to errors during the flash procedure.

VAS tools must only be used with their power adapters plugged in. Under no circumstances should they be used on battery power alone during the programming procedure.



Tip:

To Update-Programming using Software Version Management (SVM), **review and follow** instructions in **Technical Bulletin Instance 2014603** "Software Version Management".

The SVM process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim or action is carried out that is not explicitly stated in the Technical Bulletin.

- Update the Airbag Control Module (0015) -~~J234~~- using the SVM Unit code as listed in the table below:
- Go to diagnostic address 0015 – airbag: Perform GFF replacement control module test plan.



| Model | Engine | Old Software Part No. | Old Software Version | New Software Part No. | New Software Version (or higher) | SVM Unit Code |
|------------------|--------|-----------------------|----------------------|-----------------------|----------------------------------|---------------|
| Atlas | All | 3Q0959655DB | 720 | 3Q0959655DB | 721 | 4488 |
| Atlas CrossSport | All | 3Q0959655DB | 720 | 3Q0959655DB | 721 | 4488 |



Note:

If you have a "FAZIT" error perform component protection test plan for address word 0015.



Tip:

The procedure can be found in GFF under Functions/ Component Selection, Software Version Management, Adapting Software (0015).

Warranty

| To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual ¹⁾ | | | | | |
|---|---|--------------|--|---|-------------------|
| Model(s) | Year(s) | Eng. Code(s) | Trans. Code(s) | VIN Range From | VIN Range To |
| Atlas | 2019-2021 | All | All | CA_KC530794 | CA_MC521445 |
| Atlas CrossSport | 2020 | All | All | CA_LC200001 | CA_LC225415 |
| SAGA Coding | | | | | |
| Claim Type: | Use applicable Claim Type ¹⁾ | | | | |
| Service Number: | Damage Code | HST | | Damage Location (Depends on Service No.) | |
| 6953 | 0039 | -- | | -- | |
| Parts Manufacturer | Atlas, Atlas CrossSport | | | | WVO ²⁾ |
| Labor Operation ³⁾: Charge Battery | | | 27068950 = See Elsa for latest time units. | | |
| Labor Operation ³⁾: Update Programming Airbag | | | 69531999 = 65TU | | |



69-20-02 - Update Programming, DTC B101612 Stored

Release date: 1/25/2021

| | | |
|--|-----------------------|----------|
| Control Module | | |
| Causal Part: Select Labor Operation | | 69531999 |
| Diagnostic Time ⁴⁾ | | |
| GFF Time expenditure | 01500000 = 00 TU | NO |
| Road Test | 01210004 = 10 TU | YES |
| Technical Diagnosis | 01320000 = 00 TU max. | NO |
| Claim Comment: Input "As per Technical Bulletin 2061220" in comment section of Warranty Claim. | | |
| <p>¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only.</p> <p>²⁾ Code per warranty vendor code policy.</p> <p>³⁾ Labor Time Units (TUs) are subject to change with ELSA updates.</p> <p>⁴⁾ Documentation required per Warranty Policies and Procedures Manual.</p> | | |

Required Parts and Tools

No Special Parts required.

| Tool Description | Tool No: |
|-----------------------------------|---|
| Midtronics Battery Tester/Charger | GRX3000VAS or MTRMSP0702 battery maintainer/charger |
| VAS Diagnostic Tool | VAS 6150/X & VAS 6160/X and ODIS Service with current online updates |

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.