

Technical Information	911 (991)		$\overline{O}$
rechilical initormation	121/14 ENU	9025	9

## 911 Carrera (4) GTS Cabriolet: Instrument cluster coding

Vehicle Type: 911 Carrera GTS Cabriolet/911 Carrera 4 GTS Cabriolet

Model Year: 2015

Concerns: Display of the vehicle designation in the multi-function display in the instrument cluster

Information: During the production process, we have discovered that no convertible top status messages are displayed in the instrument cluster for 911 Carrera (4) GTS Cabriolet vehicles due to an incorrect coding table.

To ensure that the **convertible top status messages are displayed in the instrument cluster**, the instrument cluster on these vehicles has been coded using a corresponding coding table for 911 Carrera (4)S Cabriolet vehicles **at the factory** as an **interim solution**.

As a result, the "Carrera (4)S" logo is currently displayed in the multi-function display in the instrument cluster instead of the "Carrera (4) GTS" logo for 911 Carrera (4) GTS Cabriolet vehicles.

This means that there is currently a **difference between the Coupé and Cabriolet** version of the **911 Carrera (4) GTS** in terms of **the logo that is displayed in the multi-function display**:

Vehicle type	Logo displayed in multi-function display
911 Carrera GTS (Coupé) 911 Carrera 4 GTS (Coupé)	Carrera GTS Carrera 4 GTS
911 Carrera GTS (Cabriolet) 911 Carrera 4 GTS (Cabriolet)	Carrera S Carrera 4S

Work Procedure:

Please note that if a complaint about this is received, the instrument cluster **must not be re-coded** at present using the PIWIS Tester in order to correct the fault or for standardisation purposes because if it is, the **convertible top status messages** will **no longer be displayed** in the instrument cluster.

Please inform your customers about this if necessary and please note that the instrument cluster **must not be re-coded** on these vehicles **even in the course of further work or during fault finding**.

Dates of Introduction:

PIWIS Tester software version 14.900 (should be available from 18.12.2014):

With this PIWIS Tester software version, the coding table that is already used in production will be available on the PIWIS Tester as an **interim solution**.

The instrument cluster can be coded again in the dealer organisation using this software version.

Once coding is complete, the **convertible top status messages will be displayed correctly**, but the "**Carrera (4)S**" logo will **still** be displayed instead of the "**Carrera (4) GTS**" logo in the multi-function display.

911 (991)

9025 ENU 121/14

## **Technical Information**

PIWIS Tester software version 15.200 (should be available from February 20, 2015):

With this PIWIS Tester software version, a **corrected coding table** will be available on the PIWIS Tester. This can be used to code the instrument cluster correctly so that **both the convertible top status messages and the "Carrera (4) GTS" logo will be displayed**.

To standardize the affected vehicles, they will then be assigned to a workshop campaign during which the instrument cluster must be re-coded.

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.