

72-21-01 - Seat Memory Inoperative, Loss Of Basic Settings

Release date:

4/1/2021

Condition

Applicable Vehicles					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Atlas	2019-2021	All	All	CA_KC602912	CA_MC561902
Atlas CrossSport	2020-2021	All	All	CA_LC200225	CA_MC214615

Revision Table					
Instance Number	Published Date	Version Number	Reason For Update		
2062852/1	4/1/21	72-21-01	Original publication.		

Memory Seats Inoperative, Loss of Basic Settings.

One or more of the following may be stored in the Driver Seat Adjustment Control Module (0036) - **J810**-.

DTC	Description
B135454	Seat height adjustment motor no basic setting
B201000	No basic setting



DO NOT diagnose or replace components due to DTC B135454, B201000 faults before performing the update function as explained in this bulletin.

Technical Background

The memory seat function may become inoperative due to seat memory parameterization

Production Solution

Update to Driver Seat Adjustment Control Module - J810- parameters as of 1/27/2021.

Technical Service Bulletin

Transaction No:

2062852/1



72-21-01 - Seat Memory Inoperative, Loss Of Basic Settings

Release date:

4/1/2021

Service


Software Configuration Procedure.

Under OBD diagnostic in 0036:

- · Select identification
- Select show complete identification
- Select Identification of parameterization
- Review the [LO] Basic Structure version top number. Numbers below 5 needs to be updated.



If the version number is already at 5 this bulletin does not apply and further diagnosis is required.






72-21-01 - Seat Memory Inoperative, Loss Of Basic Settings

Release date:

4/1/2021

 In address word 0036 enter Guided Functions, select and perform Software Configuration.



- After the update go back to Identification of parameterization and verify the version has updated to 5.
- Re-enter Guided Functions and perform test plan for Basic Settings.





72-21-01 - Seat Memory Inoperative, Loss Of Basic Settings

Release date:

4/1/2021

Warranty

Model(s)	Year(s)		Eng. Code(s)	Trans. Code(s)	VIN R Fro	ange om	VIN Range To
Atlas	2019-2021		All	All	CA_KC602912		CA_MC561902
Atlas CrossSport	2020-2021		All	All	CA_LC200225		CA_MC214615
			SAGA	Coding			
Claim Type: Use applicable Claim Type 1)							
Service Number:		Damage Code	нѕт		Damage Location (Depends on Service No.)		
7293			0039				
Parts Manufacturer		Atlas, Atlas	Cross Sport		WW	WWO ²⁾	
Labor Operation 3): Charge Battery			27068950 = See Elsa for latest time units.				
Labor Operation ³⁾ : Update Programming Memory Seat Module			72931999 = 50TU				
Causal Part: Select Labor Operation			72931999				
			Diagnost	ic Time ⁴⁾			
GFF Time expenditure		01500000 = 00 TU		NO			
Road Test		01210004 = 10 TU		NO			
Technical Diagnosis 01320000 =		01320000 = 00 T	TU max. NO		0		
Claim Comment:	: Input "A	As per Te	echnical Bulletin 20	62852" in comme	nt sectior	n of Warr	anty Claim.
1) Vehicle may be	outside	any War	ranty in which case	e this Technical Bu	ılletin is i	nformatio	anal only

²⁾ Code per warranty vendor code policy.

Technical Service Bulletin

Transaction No:

2062852/1



72-21-01 - Seat Memory Inoperative, Loss Of Basic Settings

Release date:

4/1/2021

- 3) Labor Time Units (TUs) are subject to change with ELSA updates.
- ⁴⁾ Documentation required per Warranty Policies and Procedures Manual.

Required Parts and Tools

No Special Parts required.

Tool Description	Tool No:		
Midtronics Battery Tester/Charger	GRX3000VAS		
	or		
	MTRMSP0702 battery maintainer/charger		
VAS Diagnostic Tool	VAS 6150/X & VAS 6160/X and		
	ODIS Service with current online updates		

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.