

# **Technical Service Bulletin**

#### PSS 01 3.0TFSI Bank 2 engine misfires - Q8/Q7 (DCBD engine)

01 21 03 2054182/5 April 7, 2021. Supersedes Technical Service Bulletin Group 01 number 20-85 dated September 3, 2020 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7, Q8	2019 - 2022	All	3.0TFSI

### **Condition**

REVISION HISTORY					
Revision	Date	Purpose			
5	-	Revised title			
		Revised header (Added MY21-22)			
		Revised Production Solution (Updated estimate)			
4	09/03/2020	Revised Production Solution (Updated estimate)			
		Revised Service (Adjusted Steps and updated with software release)			
3	12/13/2019	Revised title (Changed format)			
		Revised header (Added MY20)			
		Revised Service (Updated estimate added to Production Solution)			

This PSS only applies if all of the following conditions are met, see Figure 1 for an example:

- MIL on, MIL flashing, or misfires reported by customer.
- Misfire DTCs are stored for more than one cylinder on Bank 2.
- DTC ambient conditions show misfires occurring at or near the same timestamp.
- DTC ambient conditions show misfires occur while engine operating condition is "Leerlauf" (idle in German).
- DTC ambient conditions show misfires occur when the vehicle is at or near 0 km/h speed.
- The vehicle is NOT currently misfiring when examined in the workshop.

If all of the above criteria are not met, this PSS does not apply and the vehicle should be diagnosed using the normal GFF process.



# Technical Service Bulletin

DTC memory entry	DOZDEGO: Out E Minter	S.	
Number:	P030500: Cyl.5 Misfire Detected		
Error type 2:	passive/sporadic		
Symptom:	10595		
Status:	01100000		
Standard ambient conditions:			
Date:	12/2/18		
Time:	2:42:42 PM		
Mileage (DTC):	1771		
Priority:	2		
Frequency counter.	2		
Elimination counter / driving cycle:	255		
Expanded ambient conditions:			
Engine speed	626.5	1/mln	
Normed load value	7.8431373	%	
Vehicle speed	0	km/h	
Coolant temperature	101	·C	
Intake air temperature	23	·C	
Ambient air pressure	970	mbar	
Voltage terminal 30	13.1	٧	
	20 96 27 10 7A 03 11 BD 0	E 77	
Dynamic environmental data	3E FC 05 12 16 03 1F 15 14 04 1B 60 00 02 10 10 01 6A		
Unlearning counter according	39		
OBD	1973		
Engine status	COENG_RUNNING		
Param_TestProgrCoEngStCOMPUVERBUB		623	
Engine oil temperature	97.16	.c	
Engine operating condition	Leerlauf 5		
Param_TestProgrChann87 Relative load value	18.726562	%	
Current system status	SYC_DRIVE	76	
Param_TestProgrExeConState02UBYTE	4		
Virtual_SigXSet_TIOff_tiStrtEnd_Off	2	5	
Engine torque	36.2	Nm	
DTC memory entry			
	P030600: Cyl.6 Misfire	8	
Number:	Detected		
Error type 2:	passive/sporadic		
Symptom:	10596		
Status:	01100000		
Standard ambient conditions:			
Date:	12/2/18		
Time:	2:42:42 PM		
Mileage (DTC):	1771		
Priority:	2		
Frequency counter.	2		
Elimination counter / driving cycle:	255		
Expanded ambient conditions:			
Engine speed	626.5	1/min	
Normed load value	7.8431373	%	
Vehicle speed	0	km/h	
	4.00.2	.c	
Coolant temperature Intake air temperature	101 23	·c	

Figure 1. Example of applicable DTC.

## **Technical Background**

Software calibration causing misfire under certain running conditions using winter blend fuel (higher vapor pressure). This condition would occur mostly during winter months.



# Technical Service Bulletin

### **Production Solution**

Improved software in development pending 4th quarter of 2021 release.

#### **Service**

- 1. If customer's vehicle condition matches the conditions listed in this PSS TSB clear DTC's and test drive vehicle.
- If no faults return after the test drive, explain to the customer that a solution is forthcoming for the 4th quarter of 2021 and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
- 3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links* >> *Service*), or through the Technical Assistance Page in Elsa.

### **Warranty**

This TSB is informational only and not applicable to any Audi Warranty.

### **Additional Information**

All parts and service references provided in this TSB (2054182) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.