



## SIB 51 02 21

2021-03-17

### AIR DUCT COVER LOOSE OR MISSING

This Service Information Bulletin (Revision 1) replaces SI B51 02 21 **dated February 2021**.

#### What's New (Specific text highlighted):

- Procedure

### MODEL

| E-Series | Model Description |
|----------|-------------------|
| F90      | M5 Sedan          |

### SITUATION

The air duct cover (fender mounted) may be loose or missing.

### CAUSE

Prolonged high-speed driving can cause movements of the fender, causing the air duct to become loose.

### CORRECTION


Replace the air duct cover along with air duct. Apply additional adhesive.

### PROCEDURE

Note: The repair procedure listed below is available for guided step by step instructions using the TSARA Vision Ubimax glasses. Scanning the QR code below with the glasses will load the available repair instructions into the glasses for use at the vehicle. For general reference on the TSARA Vision glasses, refer to [B04 03 19](#).

**Once the device (glasses) is powered on, you will see Scan Task. Say “scan task”, then scan the QR Code below:**

# B51 02 21



TSARA Vision Ubimax glasses for repair instructions are in addition to, and secondary to the repair instructions contained in this bulletin.


TSARA Vision repair instructions are currently being piloted. Feedback on the guided repair instructions via TSARA glasses can be sent through the technical inquiries feedback option at the top of this bulletin.

**For those not wishing to utilize smart glasses for repair instructions, see below:**

1. Clean the fender in the area of the air duct mounting using a lint free cloth and cleaner R2 P/N 83 19 0 417 324. Allow at least 2 minutes for the cleaner to dry.
2. Using adhesive tape, secure the new air duct and air duct cover as shown below.




3. Apply window glass adhesive P/N 83 19 2 289 180 to positions 1, 2, and 3 shown below



Note: The adhesive at position 3 will be used to bond the air duct cover to the fender. See step 4 for additional instructions for this position.

4. Ensure the adhesive applied at position 3 is thick enough to extend outwards 5mm beyond the clip(4) shown below. This is to ensure adequate bonding to the fender.



5. Carefully position the air duct and air duct cover onto the fender. Ensure that all 8 clips of the air duct engage the fender for a secure fit.



6. After 3 hours, the adhesive tape can be removed. Allow 24 hours of curing time before washing the vehicle.

### **PARTS INFORMATION**

Obtain and confirm the part numbers for your specific vehicle by entering the chassis number in either ETK or AIR which takes into account specific equipment and/or options.

| <b>Part Number</b> | <b>Description</b>                              | <b>Quantity</b>        |
|--------------------|---|------------------------|
| Refer to AIR/ETK   | Air Duct  | 2 (1 Left and 1 right) |
| Refer to AIR/ETK   | Cover, air duct                                 | 2 (1 Left and 1 right) |
| 83 19 2 289 180    | Windshield adhesive repair kit                  | See below              |
| 83 19 0 417 324    | Cleaner R2 (Brake Pedal assembly aid)<br>500 ml | Sublet as needed       |

### **WARRANTY INFORMATION**

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

|                     |                   |   |
|---------------------|-------------------|---|
| <b>Defect Code:</b> | <b>5113343700</b> | <b>Grille/air inlet, side panel Loose</b> |
| :                   |                   |   |

| Labor Operation | Description   | Labor Allowance |
|-----------------|---|-----------------|
| 51 13 046       | Removing and installing/replacing trim strips on <b>both</b> front side panels ( <b>Main work</b> ) | Refer to AIR    |
| Or:             |   |                 |
| 51 13 946       | Removing and installing/replacing trim strips on <b>both</b> front side panels ( <b>Plus Work</b> ) | Refer to AIR    |
| And:            |   |                 |
| 51 99 000       | Work time to bond the replacement air duct  | 3 FRU           |

If you are using a Main labor code for another repair, use the Plus code labor operation 51 13 946 instead of 51 13 046.

Refer to AIR for the corresponding flat rate unit (FRU) allowances.

As applicable to your center, please refer to **SI B01 01 20** or **B01 07 20** for claiming your diagnosis work time, job/repair work time (WT), RO/Claim WT and/or repair explanation procedures, unless otherwise required by State law.

And, as needed:

#### Sublet – Bulk Materials (RO and Claim Comments Required)

|                                |   |  |
|--------------------------------|---|--|
| <b>Sublet Code</b><br><b>4</b> | See the sublet reimbursement calculations below | Reimbursement for the repair-related bulk materials (Do not use the BMW part numbers for claim submission) |
|--------------------------------|---|--|

Sublet reimbursement calculation for claiming the applicable repair-related bulk materials (BMW part numbers) is at the dealer net price amount for the quantities used plus your center's handling.

Windshield adhesive repair kit (P/N 83 19 2 289 180) has a very limited shelf life after it is opened, if only one (1) vehicle will have this repair performed and no other vehicles currently in the workshop will also require this adhesive to perform a different repair, then claim the windshield adhesive repair kit part number at a quantity of one.

For all multi-vehicle repairs that require this windshield adhesive, claim this material in sublet for the calculated amount for one (1) portion of the kit as determined by the total number of vehicles being repaired.

Enter this material cost in sublet and itemize the amount on the repair order and in claim comment section.

#### QUESTIONS REGARDING THIS BULLETIN

|                     |  |
|---------------------|--|
| Technical inquiries | Submit feedback at the top of this bulletin  |
| Warranty inquiries  | Submit an IDS ticket to the Warranty Department or use the chat available in the Warranty Documentation Portal |
| Parts inquiries     | Submit an IDS ticket to the Parts Department   |