



---

# SERVICE BULLETIN

---

Classification: EL15-044	Reference: NTB16-001	Date: January 4, 2016
-----------------------------	-------------------------	--------------------------

---

## NISSAN; SERVICE INFORMATION FOR COMBINED BCM REPLACEMENT AND ADDING MORE INTELLIGENT KEYS

**APPLIED VEHICLES:** 2015 - 2016 Altima (L33)      2015 - 2016 Murano (Z52)  
2015 - 2016 Pathfinder (R52)      2015 - 2016 Rogue (T32)  
2016 Maxima (A36)

### SERVICE INFORMATION

When the BCM in an **APPLIED VEHICLE** is being replaced for any reason, all existing Intelligent Keys must be re-registered. If new Intelligent Keys are added to the existing Intelligent Keys at the same time the BCM is being replaced, the procedure below must be followed.

1. Initialize the new BCM using CONSULT-III plus (C-III plus).
  - The new BCM's memory contents for any Intelligent Keys has now been erased.
2. Re-register all existing Intelligent Keys first, and then register all new (added) Intelligent Keys.

**CAUTION:** If the new (additional) Intelligent Keys are registered BEFORE the existing Intelligent Keys, the existing Intelligent Keys will then not re-register, becoming permanently inoperable.

**NOTE:** This issue does not apply when adding new Intelligent Keys with existing Intelligent Keys and the BCM has not been replaced. In this case, all Intelligent Keys may be registered in any order.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.