## Special Service Message

NOTE: A Special Service Message is a formal communication issued by Jaguar and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Jaguar technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 75412 - XCL Smart key inoperative

Models: E-Pace / X540

F-Pace / X761

I-Pace / X590

XE / X760

XF / X260

Engineer Shilvock Matthew

Name:

Last 21 MAY 2021 17:17:42

Modified:

Category: Electrical

**Symptom**: 205000 Electrical Accessories

Content: Issue

Smart key inoperative. Insufficient or no power to the

smart key.

## Cause

Smart key coin cell upper tension pin lifted from the positive terminal, due to unnecessary force applied when replacing the coin cell. As such, there is not enough pressure on the coin cell with the negative terminal.

## Action

Remove the coin cell and press the upper positive terminal until the negative grid is touched. Upon recovering the position of the terminal, the coin cell shall have firm positive contact with the upper terminal. This should resolve the customer problem. If the problem persists, continue with the usual diagnostic steps to determine the faulty system component.

Jaguar Land Rover Limited 2000 - 2020 (Rel. 2691)