This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Document Information

Location: Electrical

Topic: Possible communication issue between IBS and MDS after upgrading to Generation 3 battery


Condition: Permanent

Diagnostic Trouble Codes: N/A

Measure

Please note that when updating from GEN1 or GEN2 12V battery to the latest GEN3 12V battery, communication to the IBS (Intelligent Battery Sensor) may not be possible.

This will result in the IBS displaying as "**IBS Base**" and missing the software version number, as shown in the below image.



This symptom is the result of a communication error between the MDS and the vehicle. It does not alter the operation of the battery or vehicle.

Currently this situation requires no action and will be rectified within a later software version.

Parts Information

N/A

Attachments

N/A

KA Update Information

N/A

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.