

Service Category Service

Section Function Group 214

Technician Skill Level A

Market North America

Applicability

| VOLVO | |
|-------|---------------|
| Years | Models |
| 2021 | VNL, VNR, VHD |

Introduction

Volvo has received reports of valve springs on some D11 and D13 engines exhibiting early life failures. Through further examination it was found some suspect valve springs do not meet Volvo's stringent quality requirements. To ensure product reliability, Volvo Trucks will be requiring replacement of all the affected valve springs on certain engines. The removed valve springs will need to be returned for inspection.

Production Change Information

This bulletin applies to vehicles built within the specified production changes below.

| Brand | Engine | Emission Level | Starting Build Date | Ending Build Date |
|-------|----------|-----------------------|---------------------|-------------------|
| Volvo | D11, D13 | EOBD U21 | 18-JAN-2021 | 21-JAN-2021 |

Warranty Information

| This repair is covered by an authorized Service Program. Reimbursement is obtained through the normal claim handling process. | | | | |
|---|---------------------------------|-------|--|--|
| Claim Type (used only when uploading from the Dealer Bus. Sys.) B | | | | |
| Main Labor Code | Description | Hours | | |
| 2144-03-03-03 | Valve Spring, Replacement (All) | 4.0 | | |
| 2146-01-01-01 | Rocker Arm Shaft, Removal | 1.7 | | |
| 2146-02-01-01 | Rocker Arm Shaft, Installation | 4.0 | | |
| Causal Part | 23803415, 23803420 | | | |
| SCC Authorization Code | S7598 | | | |
| Expiration Date | August 31, 2022 | | | |



Parts Information

Parts required for **D11**

| Part Numbers | Part Names | Quantity |
|--------------|---------------------------------|----------|
| 20510747 | Valve Cotter (Keeper) | 48 |
| 23803420 | Valve Spring Inner | 24 |
| 23803415 | Valve Spring Outer | 24 |
| 21487571 | Valve Cover Gasket, upper (D11) | 1 |
| 23002534 | Fuel Lines (left D11) | 3 |
| 23002543 | Fuel Lines (right D11) | 3 |
| 21344774 | Injector Hold Down Bolts | 6 |

Parts required for D13

| Part Numbers | Part Names | Quantity |
|--------------|---------------------------------|----------|
| 20510747 | Valve Cotter (Keeper) | 48 |
| 23803420 | Valve Spring Inner | 12 |
| 23803415 | Valve Spring Outer | 24 |
| 22777560 | Valve Cover Gasket, upper (D13) | 1 |
| 23000870 | Fuel Lines (left D13) | 3 |
| 23000879 | Fuel Lines (right D13) | 3 |
| 21344774 | Injector Hold Down Bolts | 6 |



Required Tools & Equipment

- Access to Trucks Dealer Portal and the IMPACT application.
- Special tools contained in the below procedures.

Calibration Information

• None

Repair Procedure

- 1. Secure Vehicle for service
- 2. Remove valve cover and rocker shaft using IMPACT operation ID 2146-01-01-01.
 - a. NOTE: Do not disassemble the rocker shaft.
- 3. Replace ALL valve springs using IMPACT operation ID 2144-03-03-03.
 - a. **NOTE**: Save all removed valve springs for inspection. Place the old springs in the packaging the new springs arrived in and mark the position on the bag from which the spring came (i.e. CYL 1 EXH). See shipping information below.
- 4. Reinstall rocker shaft, adjust valves, and reinstall valve cover using IMPACT operation ID 2146-02-01-01.
- 5. Package removed valve springs as mentioned above and as seen on next page.
- 6. Release the vehicle for service.



Valve Spring Return Process

The UCHP Claim (part return) will be arriving in your "MI Tab" within no later than 7 days after crediting. Please follow the below shipping instructions on the UCHP shipping documents

- As previously mentioned, place the used valve springs in the individual packaging from which the new valve springs arrived in.
- Write on the individual bag which position the used valve spring came from (i.e. CLY 1 EHX, as seen in the image below).
- Box all individually bagged springs in one container for shipping.



Sample of return packaging