

Date	Expiration	Release	Page
11.2018		5	1(15)

Revision: F                      Addition to Warranty section                      09/03/2021

## P20EE (diagnostic troubleshooting code) SOLUTION - NOX CONVERSION EFFICIENCY

Prevost vehicles

B13R (9700 us/can)

### DESCRIPTION

For the vehicles **on which a notification** for SP18-35 **exists**, perform the following checklist and operations. It has been determined that these vehicles had the code (DTC) P20EE activated.

DO NOT perform this special bulletin on a specific vehicle unless a notification exists, otherwise, no reimbursement will be awarded.

### MODEL YEAR(S) AND VEHICLES INVOLVED

<b>NOTICE TO SERVICE CENTERS</b> <i>Verify vehicle eligibility by checking warranty bulletin status with <b>SAP</b> or via <b>ONLINE WARRANTY SYSTEM</b> available on Service / Warranty tab of Prevost website.</i>	
H3-41, H3-45 coaches Model Year: 2017 - 2019	<u>GHG17</u> or <u>OBD18</u> compliant vehicles From 2PCH33494 <u>H9737335</u> up to 2PCH33492 <u>KC710467</u> (not incl.)
H3-45 VIP motorhomes Model Year: 2017 - 2019	
X3-45 coaches Model Year: 2017 - 2019	<u>GHG17</u> or <u>OBD18</u> compliant vehicles From <b>4RKG33491</b> <u>H9737417</u> up to <b>4RKG33490</b> <u>K9737576</u> (not incl.)
X3-45 coaches Model Year: 2017 - 2019	
X3-45 VIP commercial use Model Year: 2017 - 2019	<u>GHG17</u> or <u>OBD18</u> compliant vehicles From 2PCCS3495 <u>HC736180</u> up to 2PCCS3498 <u>KC736407</u> (not incl.)
X3-45 VIP motorhomes Model Year: 2017 - 2019	
VOLVO 9700 Model Year: 2017 - 2019	<u>GHG17</u> or <u>OBD18</u> compliant vehicles From 3CET2V927 <u>H5184392</u> up to 3CET2V926 <u>K5194709</u> incl.




Date	Expiration	Release	Page
11.2018		5	3(15)




## DANGER

Park vehicle safely, apply parking brake, stop the engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

### IMPORTANT NOTES

 DO NOT perform WB18-04 or WB18-84 EMS & ACM SOFTWARE UPDATE before the following checklist, otherwise useful diagnostic codes and monitor data could be erased.

Wb18-04 for Prevost coaches, Wb18-84 for Volvo 9700

 Any troubleshooting labor of active DTCs (Diagnostic Troubleshooting Codes) other than P20EE is considered as a separate operation of the RO (repair order) and cannot be charged to this special bulletin.

# PART 1


Vehicle identification		
H3	<input type="checkbox"/>	V.I.N (short) : _ _ - _ _ _ _ _
X3	<input type="checkbox"/>	
9700	<input type="checkbox"/>	

OPERATIONS TO BE PERFORMED IN ADVANCE BY THE SERVICE ADVISOR
<p>Ask the customer whether he/she noticed an abnormal consumption of oil or coolant.</p> <p>Search all relevant information concerning the aftertreatment system or severe turbo failure in the history of repairs of the vehicle and record. Attach to the repair order.</p> <p>Also check if SP18-35 has already been performed on that particular coach. If this is the case, do not perform SP18-35 once again, contact the Technical Publications for instructions. You can send a message to the Technical Publications functional mailbox: <i>technicalpublications_prev@volvo.com</i></p>
NOTE/RESULTS: ..... ..... .....





- 7 Check and record the engine ECU (a.k.a. Engine Control Module ECM) software number.  
To do so, check in the dashboard DID. Select DIAGNOSTICS > PART NUMBER > ENGINE ECU



➔ Engine ECU software number: \_\_\_\_\_

COMMENTS/RESULTS:





$$\text{ppm levels difference (\%)} = \frac{\text{highest value} - \text{lowest value}}{\text{lowest value}} \times 100$$


$$\text{Ex.: ppm levels difference (\%)} = \frac{(288-279)}{279} \times 100 = 3.2 (\%)$$

➔ Are both original NOx sensors good (ppm difference ≤10%)? YES  NO   
ppm levels difference = \_\_\_\_\_ %

Replace the defective sensor<sup>1</sup> if applicable and then perform a new NOx sensor test once again to make sure that the replacement sensor is good.

### NOx Conversion Test With engine ECU software number 23470183


Engine ECU software number 23470183 allows DEF dosing to continue during the last part of the NOx conversion test (just before shutdown). This causes continued low outlet NOx sensor ppm levels, as seen in the example below. **Take screen captures.**




**DIFFERENT BEHAVIOR.** In this example, the NOx sensors ppm levels are not close to each other because DEF is still injected during the last part of the test. **In this instance, review earlier sections of the test** to ensure that both sensors are responding to changes in the same manner. Examples of different stages to review are shown below.

<sup>1</sup> Change only one sensor, since both will eventually be replaced with the new SCR converter

## COMPARISON SHOULD BE DONE WHEN BOTH NOX SENSORS ARE READING BELOW 600 ppm



The NOx sensors levels are close to each but earlier during the test (images above & below).



If both NOx sensor ppm levels are **close to each other** at a point during the test as shown in the examples (image) above, then both NOx sensors are good.

If ppm levels difference is **greater than 10%**, then the sensor reading higher should be considered as defective.

COMMENTS/RESULTS:

**9** **If all of the five following conditions** are satisfied, **do not perform PART 2** of this bulletin. Send this checklist along with screen captures to the Technical Publications to request approval for the SCR converter replacement.

Conditions


- 1) Engine is free from major component failure/performance issues
- 2) Five most recent SCR efficiency values hovering around or below 80% (step 2)
- 3) DEF dosing amount tests showed normal values (step 4)
- 4) DEF concentration within GOOD range (step 5)
- 5) Both original NOx sensors are good (step 8)

All five conditions satisfied, bulletin ended at step 9 (no need to perform sulfur regeneration nor a road test):



**Authorization for the replacement of the SCR converter.** An analysis of this checklist with the comments/results must be done in order to allow the replacement of the SCR converter. Scan and send this checklist and all the relevant documents, photos, etc. to the Technical Publications functional mailbox: *technicalpublications\_prev@volvo.com*

Please indicate in the "subject line": SP18-35 and the short V.I.N. as in the example below...



COMMENTS/RESULTS:





Date	Expiration	Release	Page
11.2018		5	14(15)

## PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

## WARRANTY

This diagnostic is covered by Prevo's normal warranty. We will reimburse you the parts and labor upon receipt of a warranty claim according to the following:

### PARTS COVERED BY THIS BULLETIN

22677399	DEF injection nozzle gasket	Qty: 1
21376801	sealing plate	Qty: 1

Any other parts such as parts installed to correct exhaust leaks or for the replacement of sensors cannot be charged to this bulletin. These are covered by the normal warranty when applicable and must be charged on a different operation.

### LABOR COVERED BY THIS BULLETIN

The time allowed to complete PART 1 of this bulletin is 2 hours

The time allowed to complete PART 1 & PART 2 of this bulletin is 4 ¼ hours

This allowed time covers the execution of the procedure described in this document only. Any corrective work such as replacing the DEF injector, correcting exhaust leaks or any diagnostic work of active DTCs codes other than P20EE is considered a separate operation on the repair order and cannot be charged to this special bulletin.

Please submit claim via our Online Warranty System, available at [www.prevo.com](http://www.prevo.com) (under Service \ Warranty section). Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin SP18-35".

