

# Special Service Message

NOTE: A Special Service Message is a formal communication issued by Jaguar and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Jaguar technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 75536 - X540 Panoramic roof sun blind inoperable.

**Models :** E-Pace / X540

**Engineer** Skingle Paul

**Name :**

**Last** 20 SEP 2021 13:38:17

**Modified :**

**Category :** Body

**Symptom :** 105000 Roof Options

**Content :** Issue:

Panoramic roof sun blind inoperable from operation at the switch in the overhead console.

**Cause:**

Oxidisation build up on the commutator surface of the sunblind motor resulting in sun blind cover not working.

**Action:**

- Lower the overhead console and headliner as TOPIx procedure WSM-3046 to gain access to panoramic roof sun blind motor.
- Insert a 4mm Allen Key into emergency operation slot at the motor, rotate half turn clockwise and then half turn anti clockwise.
- Then operate by the sun blind switch approximately 7 full open and close cycles. This will then re-calibrate the sun blind motor.

Note:

Please see attached ppt for assistance.

**File :** [X540 Sunblind motor inop \(1\).pptx](#)