



Technical Service Bulletin

90 Audi virtual cockpit display is black, DTC B200049 is stored in the instrument cluster - A6, A7, Q7, and Q8

90 21 14 2064683/1 October 5, 2021.

| Model(s) | Year | VIN Range | Vehicle-Specific Equipment |
|--|------|-----------|----------------------------|
| A6, A6 allroad, A6 Avant, S6, RS 6, RS 6 Avant, A7, S7, RS 7, A7 PHEV, Q7, SQ7, Q8, SQ8, and RS Q8 | 2021 | All | Audi virtual cockpit |

Condition

Customer states:

- The Audi virtual cockpit is blank.
- The display failure is either intermittent or constant.

Workshop findings:

The following DTC may be stored in the instrument cluster, J285, (address word 0017):

- **DTC B200049** (Control Module Faulty).

Technical Background

There is a hardware defect in the Audi virtual cockpit.

Production Solution

An optimized hardware designed for Audi virtual cockpit was implemented.

Service

1. Please check the production date of the Audi virtual cockpit:
 - a. In ODIS, go to *Self-diagnosis >> Address: 0017 System name: 0017 >> Instrument cluster >> Production date.*



Technical Service Bulletin

2. If the Audi virtual cockpit has been produced **before** May 12th, 2021, then please replace the instrument cluster.

Warranty

| | | | |
|--------------------------|---|--------------|--|
| Claim Type: | <ul style="list-style-type: none"> • 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only. | | |
| Service Number: | 9025 | | |
| Damage Code: | 0040 | | |
| Labor Operations: | Remove and install/replace dash panel insert | 9025 XXXX | See SRT with associated operations |
| | Self-diagnosis: Readout the DTC memory | 0151 0000 | 10 TU |
| Diagnostic Time: | GFF | 0150 0000 | Time stated on the diagnostic protocol (Max 50 TU) |
| | Road test prior to the service procedure | No allowance | 0 TU |
| | Road test after the service procedure | No allowance | 0 TU |
| Claim Comment: | As per TSB #2064683/1 | | |

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

| Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. | | |
|---|--|---------------|
| Part Number | Part Description | Quantity |
| See ETKA | Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual | See ETKA/ELSA |
| See ETKA | Audi virtual cockpit | 01 |



Technical Service Bulletin

Additional Information

All parts and service references provided in this TSB (2064683) are subject to change and/or removal.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.