



Technical Service Bulletin

01 MIL on, DTCs P023600 and P060600 are stored in the ECM

01 21 14 2063394/2 October 26, 2021. Supersedes Technical Service Bulletin Group 01 number 21-05 dated May 19, 2021 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8	2017	All	2.0 TFSI
A4, A4 allroad, A6, A7, and Q7	2017 – 2021	All	2.0 TFSI
Q3	2017 – 2018, 2021	All	2.0 TFSI
A3 sportback	2017 – 2018	All	2.0 TFSI
A3, A3 Cabriolet, S3, TT, TTS, and TTRS	2017 – 2019	All	2.0 TFSI
A5, A5 Cabriolet, A5 sportback, and Q5	2018 – 2019, 2021	All	2.0 TFSI
Q8	2019 - 2021	All	2.0 TFSI

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Added Model Year)
1	05/20/2021	Initial publication

Customer states:

- MIL on.

Workshop findings:

The following DTCs and symptom code combinations are stored in the engine control module (ECM), J623 (address word 0001):

- **DTC P023600** (Charge air pressure sensor, Implausible signal) with symptom code 26363.



Technical Service Bulletin

- **DTC P060600** (Control module faulty) with symptom code 27740.

Technical Background

Due to a diagnosis overlap, DTC P060600 with symptom code 27740 may be stored simultaneously without a good reason.

Production Solution

Not applicable.

Service

1. Perform Guided Fault Finding for DTC P023600 and follow the instructions.
2. Erase DTC P060600 after repairs are completed for DTC P023600.



Note:

Do not replace the ECM. Claims for replaced ECM's will not be reimbursed

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (2063394) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.