



Technical Service Bulletin

PSS 90 Parking aid inop, DTC B107A16 stored in the driver assistance system with symptom code 233474

90 21 19 2061689/2 November 3, 2021. Supersedes Technical Service Bulletin Group 90 number 20-83 dated December 16, 2020 for reasons listed below.

| Model(s) | Year | VIN Range | Vehicle-Specific Equipment |
|--|-------------|-----------|----------------------------|
| A6, A7, A8, Q8, and Audi e-tron quattro | 2019 - 2022 | All | zFAS |
| A6 allroad, Audi e-tron sportback quattro, Q7, SQ7, SQ8, S6, S7, RS 7, and RS Q8 | 2020 - 2022 | All | zFAS |
| A6 Avant, RS 6 Avant | 2021 - 2022 | All | zFAS |
| Audi e-tron GT, Audi RS e-tron GT | 2022 | All | zFAS |

Condition

| REVISION HISTORY | | |
|------------------|------------|--|
| Revision | Date | Purpose |
| 2 | - | Revised header (Added Model) Revised <i>Service</i> (Updated expected release date) |
| 1 | 12/16/2020 | Initial publication |

Customer states:

- The vehicle's acoustical and optical parking aid system is inoperative.
- The message "Parking Aid: Malfunction!" is shown in the instrument cluster.

Workshop findings:

The following DTC is stored in the driver assistance systems control module, J1121 (address word 00A5):

- **DTC B107A16** (Supply voltage for park assist sensor Voltage too low) with symptom code 233474.



Technical Service Bulletin

Technical Background

A software malfunction can cause the DTC to be entered erroneously.

Production Solution

Not applicable.

Service

1. Clear the vehicle's DTCs.
2. Explain to the customer that a solution is forthcoming for the 1st quarter of 2022 and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*), or through the Technical Assistance page in Elsa.

Warranty

| | | | |
|-------------------------|---|--------------|--|
| Claim Type: | <ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only. | | |
| Service Number: | 9093 | | |
| Damage Code: | 0039 | | |
| Diagnostic Time: | GFF | 0151 0000 | Time stated on the diagnostic protocol (Max 25 TU) |
| | Road test prior to service procedure | No allowance | 0 TU |
| | Road test after service procedure | No allowance | 0 TU |
| Claim Comment: | As per TSB #2061689/2 | | |



Technical Service Bulletin

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (2061689) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.