



# Technical Service Bulletin

## 39 Quattro Ultra, DTC U030000 is stored in the all-wheel drive control module

39 21 45 2048671/5 November 12, 2021. Supersedes Technical Service Bulletin Group 39 number 20-26 dated March 17, 2020 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A4 allroad	2017 - 2021	All	Quattro Ultra
A5	2018 - 2021	All	Quattro Ultra
Q5	2019 - 2021	All	Quattro Ultra
A6, A7	2019 - 2021	All	Quattro Ultra

## Condition

REVISION HISTORY		
Revision	Date	Purpose
5	-	Revised header (Added Models and Model Years) Revised <i>Service</i> (Updated SVM software)
4	03/17/2020	Revised title Revised <i>Warranty</i> (Updated Service Number and Claim Types)
3	11/26/2018	Revised title Revised <i>Service</i> (SVM software update added, Part replacement removed) Revised <i>Warranty</i> (Updated Labor Operations) Revised <i>Required Parts and Tools</i> (Removed table)

### Customer states:

- “All Wheel Drive Malfunction Message” is displayed in the instrument cluster.

### Workshop findings:

The following DTC is logged in the all-wheel drive control module, J492 (address word 0022):

- **DTC U030000** (Internal Control Module Software Incompatibility active/static).

## Technical Background

Quattro Ultra software error.



# Technical Service Bulletin

## Production Solution

New software in the all-wheel drive control module, J492 (address word 0022) addressed the condition.

## Service

1. Check the software version number in the all-wheel drive control module, J492 (address word 0022) (Figure 1).

**Address: 0022 System name: 22 - All-Wheel Drive Electronics Log versions: UDS/ISOTP (Ereignisse: 1)**

<input type="checkbox"/> Identification:	
Hardware part number:	0CJ927749
Part number:	80A927755
Hardware version number:	H01
Software version number:	0004
Production date:	13.02.2017
Coding:	<input type="checkbox"/> +
Coding:	11070000
Ability to flash:	Unknown
System name:	Q5_DL3_N_SD4
ASAM base version:	BV_AllWheelContrUDS
ASAM 2D/ODX data set:	EV_AWDCQUOD31
ASAM 2D/ODX data set version:	001048
ASAM/ODX control module version being used:	EV_AWDCQUOD31_001
Equipment code:	00 00 00 00 00 00 00 00 00 00 00 00
System abbreviation:	J492

### DTC memory entries:

#### DTC memory entry

Number:	U030000: Internal Control Module Software Incompatibility
Error type 2:	active/static
Symptom:	34397
Status:	01100101

**Figure 1.** Software Part and Version Number.

2. Compare the installed software part number and software version number to the SVM table below. If the SVM table indicates a new software is available then perform the software update.

## SVM Update Instructions

3. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions.*



# Technical Service Bulletin

4. Update the all-wheel drive control module, J492 (address word 0022) using the SVM action code as listed in the table below, if necessary:

Model	Transmission	Old Software Part Number	Old Software Version (or lower)	New Software Part Number	New Software Version (or higher)	SVM Code Input
A4 allroad	0CJ	8W9927755	0006	8W9927755	0012	22A007
A4/A5 Automatic	0CJ	8W6927755A	0006	8W0927755C	0012	
		8W0927755C	0011	8W0927755C	0012	
		8W6927755A	0006	8W6927755C	0012	
A4/A5 manual	0CX	8W0927755	0006	8W0927755	0012	
	0CX	8W6927755	0006	8W6927755	0012	
Q5	0CJ	80A927755	0006	80A927755	0012	
		80A927755C	0008	80A927755C	0024	
A6/A7	0HL	4K0927755C	0008	4K0927755C	0024	
		4K0927755	0008	4K0927755	0024	
		4K0927755A	0007	4K0927755D	0027	

5. Road test after the update to confirm the repair.

## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"> <li>• 110 up to 48 Months/50,000 Miles.</li> <li>• G10 for CPO Covered Vehicles – Verify Owner</li> <li>• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li> </ul>
<b>Service Number:</b>	3993
<b>Damage Code:</b>	0039



# Technical Service Bulletin

<b>Labor Operations:</b>	SVM update	0151 0000	Time stated on the diagnostic protocol (Max 50 TU)
<b>Diagnostic Time:</b>	GFF	No allowance	0 TU
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	0121 0004	10 TU
<b>Claim Comment:</b>	As per TSB #2048671/5		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

The following Technical Service Bulletin will be necessary to complete this procedure:

- TSB 2011732, *00 Software Version Management (SVM), operating instructions*.

All parts and service references provided in this TSB (2048671) are subject to change and/or removal.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.