Service Alert

Mazda North American Operations Irvine, CA 92618-2922



Subject:

INFOTAINMENT REBOOT / SLOW REBOOT IN MORNING/ DISPLAY FROZEN / DISPLAY BLANK AND REAR VIEW MONITOR OPERATION NORMAL

Service Alert No.: SA-054/21

Last Issued: 11/22/2021

BULLETIN NOTES

This service alert supersedes the previously issued service alert listed below. The changes are noted in Red text.

| Previous SAs: | Date(s) Issued: |
|---------------|-----------------|
| SA-054/21 | 11/16/21 |

APPLICABLE MODEL(S)/VINS

2021 Mazda3

2021 CX-30

2021 CX-5

2021 CX-9

2022 MX-30

DESCRIPTION

Some customers may complain about any the following infotainment system concerns:

- Reboot
- · Slow reboot in morning
- · Display frozen
- Display blank

NOTE:

- · Rear view monitor operation is normal
- · No DTC stored

This may be caused by a CMU hardware malfunction.

REPAIR PROCEDURE

- 1. Verify customer concern.
- 2. Check for DTCs.

Is DTC stored?

- YES: This service information does not apply. Go to normal MGSS DTC diagnosis.
- NO: Go to next step.


Page 1 of 4

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Service Alert No.: SA-054/21 Last Issued : 11/22/2021


- 3. Retrieve 6 digit CMU Serial Number and document it on the repair order. Go to "CMU Serial Number Retrieval" Is the CMU Serial Number within the affected range? See "Affected CMU Serial Number Range" table.
 - YES: Replace the CMU (see Parts Information, part number exceptions) and confirm the CMU replacement part software is at the latest version (see MGSS -> Infotainment/TCU -> MAZDA CONNECT Updates).
 - NO: This service information does not apply. Go to MGSS SA-027/21 diagnostics.
- 4. Verify repair.

CMU Serial Number Retrieval



Page 2 of 4

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



Affected CMU Serial Number Range and Part Number Suffix

| Model | Serial Number Start | Serial Number End | Affected Part Number |
|---|---------------------|--------------------|----------------------|
| CX-5 and CX-9 | 687234 | 754800 | TC3P 66 9C0-F |
| Mazda3 (Japan built) | 622110 | 624748 | BDGF 66 9C0-W |
| Mazda3 (Japan built) | 500070 | 505859 | BGMC 66 9C0-D |
| Mazda3 (Mexico built) and CX-30 | 216848 | 227361 | DGH9 66 9C0-J |
| Mazda3 (Mexico built) and CX-30 | 104005 | 121788 | BGMR 66 9C0-D |
| Mazda3 Turbo (Japan built) | 512261 | Current Production | BFWM 66 9C0-B |
| Mazda3 Turbo (Mexico built) and CX-30 Turbo | 111827 | 113170 | BGCE 66 9C0-B |
| MX-30 | 500125 | 500664 | DN4E 66 9C0-C |


PARTS INFORMATION

| Part Number | Description | Qty. | Note |
|------------------|-----------------------|------|--|
| ****-66- 9C0* | UNIT, CONNECTIVITY | 1 | Confirm CMU replacement part software is at the latest version. See MGSS - Infotainment/TCU -> MAZDA CONNECT Updates Confirm CMU replacement part Serial Number is not affected. See "Affected CMU Serial Number Range and Part Number Suffix" table |

Page 3 of 4

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Service Alert No.: SA-054/21 Last Issued : 11/22/2021



Page 4 of 4

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.