



SERVICE BULLETIN

Classification: DA21-006	Reference: NTB21-114	Date: December 9, 2021
-----------------------------	-------------------------	---------------------------

FALSE ACTIVATION OF REAR AEB

APPLIED VEHICLES: 2021 Rogue (T33)
APPLIED SYSTEM: Automatic Emergency Braking

IF YOU CONFIRM

If the customer states that the Rear Automatic Emergency Braking (AEB) is activating when there does not appear to be anything behind the vehicle,

AND/OR

Rear AEB activation occurs while backing down a sloped driveway.

ACTION

Perform automatic reconfiguration of the sonar control unit with C-III plus.

IMPORTANT: The purpose of ACTION (above) is to give you a quick idea of the work you will be performing. You **MUST** closely follow the entire SERVICE PROCEDURE as it contains information that is essential to successfully completing this repair.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

IMPORTANT: Before starting, make sure:

- ASIST on the CONSULT PC has been synchronized (updated) to the current date.
- All CONSULT-III plus (C-III plus) software updates (if any) have been installed.

Sonar Control Unit Configuration

1. Connect the Vehicle Interface (VI) to the vehicle.
2. Turn the ignition ON with the engine OFF.
3. Start CONSULT-III plus (C-III plus) on the CONSULT PC.
 - The serial number will display when the VI is recognized.




Figure 1

4. Select **Re/programming, Configuration**.




Figure 2

5. Use the arrows (if needed) to view and read all precautions.
6. Check the box confirming the precautions have been read.
7. Select **Next**.




Figure 3

8. Select Automatic Selection(VIN).




Figure 4

9. Make sure **VIN or Chassis #** matches the vehicle's VIN.

10. If the correct VIN is displayed, select **Confirm**.




Figure 5

11. Select **Confirm**.




Figure 6

12. Select **SONAR**.




Figure 7

13. Select **Configuration**.




Figure 8

14. Select **START**.




Figure 9

15. When the configuration reaches 100%, select **End**.




Figure 10

16. Close C-III plus and disconnect the VI.

17. Turn the vehicle OFF.

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Reconfigure Sonar Control Unit	(1)	RX0TAA	ZE	32	0.3

- (1) Reference the electronic parts catalog and use the ADAS Controller Assembly (284E7 -*****) as the Primary Failed Part (PFP).

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
December 9, 2021	NTB21-114	Original bulletin published