

**Macan S, GTS, Turbo - “Warning: Oil Pressure Monitoring Fault” and Accompanying Engine Warning**

**Vehicles Affected**

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Macan S, GTS, Turbo	2019 - 2020	95BBH1, 95BBL1, 95BC11	N/A	N/A

**Revision History**

Revision	Release Date	Changes
0	June 23, 2020	Original document
1	December 9, 2020	Updated Service Information
2	January 10, 2022	Update of Model Year

**Condition**

Instrument cluster faults for oil pressure monitoring (00A048) and engine control warnings (00A016 and C12080) occurring in the wake of DME error entries **P052100 (00723D) - ‘Oil pressure sensor, front of engine block – signal’ and P25AD00 (0048AD) – ‘Oil pressure switch – signal implausible.’**

**Technical Background**

A sensitive diagnostic trigger threshold in connection with the manner in which adaptations related to oil pressure occur for some vehicles may lead to the aforementioned errors. This condition is not harmful to the engine.

A possible solution to alleviate this matter in the field by means of a software change is in progress and the information herein will be updated accordingly.

**Service Information**

After recording a Vehicle Analysis Log (VAL), delete the fault memory log and drive to ensure there are no further faults. **Please do not perform an automatic programming of the DME as an attempt to resolve this matter.** This could prolong the condition responsible for the faults by resetting specific default values.

### Warranty

As always, please document the case completely in PQIS.

Use the following troubleshooting labor operation:

03350000 On board diagnostic (Main work) Fault memory read out

03350053 On board diagnostic (Composite) VAL

For this repair, please code the "cause" as follows:

Cause location: 24700 DME control unit

Cause symptom: 4028 Reacts to Faults

### Search Items

P052100 (00723D) - Oil pressure sensor, front of engine block – signal' and P25AD00 (0048AD) – Oil pressure switch – signal implausible; warning for oil pressure monitoring fault (00A048), check engine control unit fault memory content (C12080), Macan PA –S , 3.0 liter V6

---

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

---