Ē

Assembled Camshaft - Injector Lobe Rotation Inspection; P025700, P2A1700, Or P2A1F00, Possible Lack Of Power – US17+OBD16 and Newer Emissions

r S S

> Internal Content

This procedure should be performed if the following conditions are present:

• Fault codes listed below are present on a DTC Readout:

P0257	Injection Pump Fuel Metering Control "B" Range/Performance (Cam/Rotor/Injector)
	(Cam/Rotor/Injector)
P2A17	Injection Pump Fuel Metering Control "D" Range/Performance (Cam/Rotor/Injector)
	(Cam/Rotor/Injector)
P2A1F	Injection Pump Fuel Metering Control "F" Range/Performance
	Injection Pump Fuel Metering Control "F" Range/Performance (Cam/Rotor/Injector)

Inspection Steps

1. Rotate the engine with the turning tool in the normal direction of rotation until the timing marks are aligned for the Injector Pump(s).


IMPORTANT

While the engine is being rotated, confirm each injector lobe is rotating with the camshaft and DOES NOT SLIP.


💭 Live UI

11L									
CAM POSITION	INLET	INJECTOR / PUMP	EXHAUST						
TDC/V3	_	_	Cylinder 3						
(P) 4	Cylinder 4	Pump 4	_						
V5	_	_	Cylinder 5						
(P) 2	Cylinder 2	Pump 2	_						
V1	_	-	Cylinder 1						
(P) 6	Cylinder 6	Pump 6	_						
V4	_	-	Cylinder 4						
3	Cylinder 3	-	_						
V2	_	_	Cylinder 2						
5	Cylinder 5	-	_						
V6	_	_	Cylinder 6						
1	Cylinder 1	_	_						

13L										
CAM POSITION	INLET	INJECTOR / PUMP	EXHAUST							
5/PE6	Cylinder 5	Pump 6	Cylinder 6							
3/PE2	Cylinder 3	Pump 2	Cylinder 2							
6/PE4	Cylinder 6	Pump 4	Cylinder 4							
2/E1	Cylinder 2	_	Cylinder 1							
4/E5	Cylinder 4	_	Cylinder 5							
1/E3	Cylinder 1	_	Cylinder 3							



2. Once the timing marks are aligned for a specific Injector Pump, verify the injector rocker roller is on the base circle of the injector Live UI efer to the illustration below.



If an injector lobe rotates on the camshaft, the rotation is normally by 60 degrees. It takes approximately 15 degrees of rotation before potentially causing the faults codes listed previously or a fault for a pumping injector during the Common Rail Fuel System Test.

k88992892	vi p0257-00	`ni r	p2a17-00	ер	p2a1f-00	parts as
needed. common rail	low pow	ver	p02570	0	p2a1700	
p2a1f00	mack	volvo				

Related links and attachments

No links or attachments available



Give feedback

to help improve the content of this article