



# Technical Service Bulletin

---

**48 Active steering malfunction - DTC B200FF0 (symptom code 12288)  
48 22 18 2065871/1 February 7, 2022.**

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
RS5, and RS5 Cabriolet	2019	All	Dynamic Steering
A4, A4 allroad, S4, A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, A6, A7, Q5, and SQ5	2019 – 2022	All	Dynamic Steering
A8 e quattro, and S8	2020 – 2021	All	Dynamic Steering
A6 allroad, S6, S7, and Q5 e quattro	2020 – 2022	All	Dynamic Steering
RS 5, RS 5 Sportback, RS 7, RS 6 Avant, Q5 Sportback, and SQ5 Sportback	2021 – 2022	All	Dynamic Steering

## Condition

### Customer states:

- The steering warning lamp lights up in the instrument cluster with the following message:

“Steering: fault. Adapt driving style. Turning circle larger”

### Workshop findings:

- DTC B200FF0 with symptom code 12288 is logged in the active steering control unit (diagnostic address 001B).

## Technical Background

---



# Technical Service Bulletin

---

Software issue.

## Production Solution

Not applicable.

## Service

Proceed according to the instructions below.

1. Delete the DTC in the active steering control unit (diagnostic address 001B).
2. Perform a short road test which includes a parking maneuver.
3. If the DTC does not return to the 001B control unit, return the vehicle to the customer.
4. If DTC returns, proceed with GFF and follow instructions described in the tester.

## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"><li>• 110 up to 48 Months/50,000 Miles</li><li>• G10 for CPO Covered vehicles – Verify Owner</li><li>• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li></ul>		
<b>Service Number:</b>	4869		
<b>Damage Code:</b>	0040		
<b>Diagnostic Time:</b>	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)
	Road test prior to the service procedure	0121 0002	10 TU
	Road test after the service Procedure	No allowance	0 TU
<b>Claim Comment:</b>	As per TSB 2065871/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



# Technical Service Bulletin

---

## Required Parts and Tools

Not Applicable

## Additional Information

All part and service references provided in this TSB (2065871) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.