



# Service Bulletin

Bulletin No.: 21-NA-283

Date: December, 2021

## TECHNICAL

**Subject: Service Front Suspension Lift System Message Displayed on Driver Information Center (DIC) – DTC C103C and/or C103E Symptom 64 Set**

**This bulletin replaces PIC6434A. Please discard PIC6434A.**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2020	2022	All	All	All	All

<b>Involved Region or Country</b>	North America, Europe, Middle East, Japan, Australia/New Zealand
<b>Additional Options (RPO)</b>	Front Suspension Lift System (RPO E60)
<b>Condition</b>	<p>Some customers may comment that they have seen a Service Front Lift System message displayed on the DIC.</p> <p>Technicians may find one or more of the following DTCs set:</p> <ul style="list-style-type: none"> <li>• C103C: Left Front Strut Position Sensor Signal</li> <li>• C103E: Left Front Strut Position Sensor Signal</li> <li>• Symptom 64: Signal Plausibility Failure (This sub type is used for failures where the control module detects a single input parameter is operating outside the plausible range.)</li> </ul>
<b>Cause</b>	<p><b>Note:</b> If there is low mileage on the vehicle or previous service work on this system has been identified, it is possible that air entrapment in the system may be the causing this issue.</p> <p>This condition may be caused by air entrapment in the lift system.</p>
<b>Correction</b>	<p>Attempt to operate the front lift system several times. Determine if the codes will reset or if the system will raise briefly and then sink back down. If this occurs, that may indicate that there is indeed air trapped within the front suspension lift system.</p> <p>Follow the published information in SI for these DTCs, paying particularly close attention to "Test B" at the end of the flowchart:</p> <ul style="list-style-type: none"> <li>⇒ First perform the Prime Front Suspension Pump procedure with the scan tool five times in an attempt to purge any trapped air bubbles from the system.</li> <li>⇒ Next, raise and lower the front suspension system through 10 complete cycles.</li> </ul> <p>If the DTCs reset, perform the Front Hydraulic Suspension Bleed procedure and re-evaluate the concern.</p> <p>As a way to double check the system, a technician can measure the distance between the floor and the lower portion of the vehicle's front fascia. A correctly operating vehicle should reach a front fascia height of at least 35 mm within 4 seconds of pump operation.</p>

## Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
8020652	Front Hydraulic Suspension Bleeding	Use Published Labor Operation Time

Version	1
Modified	Released December 06, 2021

