

**Complaint - Error Message "Engine Control Fault" Immediately After Starting the Vehicle:
Observe Specified Procedure (209/21)**

Vehicle Type: **Cayenne E-Hybrid (9YA) / Cayenne Turbo S E-Hybrid (9YA) / Cayenne E-Hybrid Coupé (9YB) / Cayenne Turbo S E-Hybrid Coupé (9YB)**

Model Year: **As of 2018**

Concerns: **DME control unit**


Information: Immediately after starting the vehicle, the yellow warning message "Engine control fault - Driving permitted - Visit workshop" appears in the instrument cluster.
The vehicle can be driven after switching the ignition off and on again. The fault memory entry "P060C00 - Function restriction (0078D5)" is stored in the fault memory of the DME control unit.



Information

The remedial action described below applies only to the fault memory entry P060C00 together with the data error code 0078D5.

- Action required:
- Read out and erase the fault memory of the DME control unit using **9900 - PIWIS Tester 3**.
 - To prevent this fault from occurring again, always press the brake pedal for as long as required when starting the vehicle until the "Ready" message lights up ⇒ *Instrument cluster: "Ready" message* in the instrument cluster and then release it.



Instrument cluster: "Ready" message



Information

The procedure for starting the vehicle is also described in the "Hybrid vehicle" section of the Owner's Manual. Please also inform your customer about this issue.

Invoicing

For documentation and invoicing in the event of a guarantee, state the work items required depending on the scope of work and the specified PCSS encryption in the guarantee claim:

APOS	Labor operation	I No.
03350000	On-board diagnosis	

PCSS encryption:

Location (FES5)	24700	DME control unit
Damage type (SA4)	1134	Programming error

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2022 Porsche Cars North America, Inc.