

Service

07/22 ENU 2470

2

# Engine Symptom – Rough-Running Engine and Engine Indicator Light has Come On: Re-Programming DME Control Unit (SY 07/22)

#### Change overview

Version	Date	Change
0	04/12/2022	First publication
		- Replaces Technical Information SY 55/20

Model Line: Macan (95B)

Model Year: As of 2019 up to 2021

Equipment: 2.0-liter 4-cylinder petrol engine (engine type: EA888)

Concerns: Engine electronics (DME) control unit

Symptom: Due to a software error in the DME control unit, the engine on the affected vehicles may experience rough running while driving at engine speeds near the idle range.

At least one of the following fault codes is stored in the fault memory of the DME control unit:

- P001100 Intake camshaft adjustment, bank 1 setpoint position not reached (003A16)
- P001400 Exhaust camshaft adjustment, bank 1 setpoint position not reached (003A15)

Cause: The adaptation values for camshaft control are out of tolerance.

Remedial Action:

Tool:

In the event of a customer complaint, re-program the DME control unit.



After programming the DME control unit, perform a test drive over various engine speed and load ranges. If the fault occurs again during or after the test drive, the camshaft will also need to be checked for excessive axial play.

This may well be the case, particularly in vehicles produced from the production period of March 2021 up to and including August 2021.

#### Tool required for programming the DME control unit

9900 - 9900 - PIWIS Tester 3 with PIWIS Tester software version 40.785.090 (or higher) installed.

Battery charger with a current rating of at least 90 A, e.g. VAS 5908 battery charger 90A.

## Service

2470 ENU 07/22

## Symptom-based workshop manual

For further information about the battery chargers to be used, see the corresponding Workshop Manual. ⇒ Workshop Manual '270689 Charging vehicle electrical system battery'

#### **Preliminary work**



Fault entry in the fault memory and control unit programming aborted due to low voltage.

- Increased current draw during diagnosis or control unit programming can cause a drop in voltage, which
  can result in one or more fault entries and the abnormal termination of the programming process.
- ⇒ Before starting control unit programming, connect a suitable battery charger with a current rating of at least 90 A to the vehicle.

## **NOTICE**

Control unit programming will be aborted if the WLAN connection is unstable.

- An unstable WiFi connection can interrupt communication between the PIWIS Tester and the vehicle communication module (VCI). As a result, control unit programming may be aborted.
- ⇒ During control unit programming, always connect the PIWIS Tester to the vehicle communication module (VCI) via the USB cable.

## NOTICE

Control unit programming will be aborted if the vehicle key is not recognized.

- If the driver's key is not recognized in vehicles with Porsche Entry & Drive, programming cannot be started or will be interrupted.
- ⇒ Switch on the ignition using the original driver's key. To do this, replace the control unit in the ignition lock with the original driver's key if necessary.

Work Procedure: 1

Carry out general preliminary work for control unit programming as described in  $\Rightarrow$  Workshop Manual '9X00IN Basic instructions and procedure for control unit programming – section on "Preliminary work".

#### Re-programming DME control unit

## NOTICE

Use of a PIWIS Tester software version that is older than the specified version.

- Measure is ineffective
- ⇒ Always use the specified version or a higher version of the PIWIS Tester software for control unit programming or coding.

Service

07/22 ENU 2470

2

Work Procedure:



#### Information

It is imperative that the PIWIS Tester remains online during control unit programming so that backup documentation of the software versions installed on the control units **before and after programming** is sent to the Porsche After Sales systems.

The total time required for control unit programming is **approx**. **13 minutes**.

1 The basic procedure for programming a control unit is described in the Workshop Manual ⇒ Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester - section on "Programming".

Specific information on control unit programming in the context of this Technical Information:

Required PIWIS Tester software version:	<b>40.785.090</b> (or higher)
Type of control unit programming:	Control unit programming using the 'Automatic programming' function of the DME control unit.
	'Engine electronics (DME)' control unit – 'Coding/programming' menu – 'Automatic programming' function.
Programming sequence:	Read and follow the <b>information and instructions on the PIWIS Tester</b> during the guided programming sequence. During the programming sequence, the <b>DME control unit</b> is <b>re-programmed</b> and then <b>auto-maticallyre-coded</b> .
	Do not interrupt programming and coding.
	Once the control units have been programmed and coded, you will be prompted to switch the ignition off and then back on again after a certain waiting time.
	Backup documentation of the new software versions is then performed.
Programming time (approx):	13 minutes
Data record (software part number and software version) programmed for the DME control unit during programming:	See the ⇒ Technical Information '9X00IN Overview of programmed software versions' section.

Procedure in the event of error messages appearing during the programming sequence:	⇒ Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester - section on "Fault finding".
Procedure in the event of abnormal termination of control unit programming:	Repeat control unit programming by restarting programming.

## Overview of the programmed DME software versions

Overview:



#### Information

The software part number and software version of the programmed data record are based on the specified PIWIS Tester software version. Please note that this may be different in a higher version.

#### Model year 2019:

Exhaust emission standard	Control unit	Software part No.	Software version
C6B without RDE (M No. 7CM)	DME	95B906259G	0011
EU 6 AG/H/I (M No. 7CP)	DME	95B906259AB	0002
EU 6 Plus / EU 4 or EOBD or CRT (M No. 7MM/7GH)	DME	95B906259T	0002
<b>LEV3 / Tier3 70</b> (M No. 7CE)	DME	95B906259AA	0003

#### Model year 2020:

Exhaust emission standard	Control unit	Software part No.	Software version
C6B without RDE (M No. 7CM)	DME	95B906259G	0012
EU 6 DG (M No. 4BF)	DME	95B906259F	0007
EU 6 Plus / EU 4 or EOBD or CRT (M No. 7MM/7GH)	DME	95B906259J	0009
<b>LEV3 / Tier3 70</b> (M No. 7CE)	DME	95B906259H	0007

Service

07/22 ENU 2470

# 2


#### Model year 2021:

Exhaust emission standard	Control unit	Software part No.	Software version
C6B without RDE (M No. 7CM)	DME	95B906259G	0012
EU6 AP (M No. 4BI)	DME	95B906259R	0003
EU 6 DG (M No. 4BF)	DME	95B906259F	0007
EU 6 Plus / EU 4 or EOBD or CRT (M No. 7MM/7GH)	DME	95B906259J	0009
<b>LEV3 / Tier3 70</b> (M No. 7CE)	DME	95B906259S	0003

#### Concluding work following control unit programming

Work Procedure: 1 Perform throttle valve adaptation.

- 1.1 Select the 'DME' control unit in the control unit selection screen ('Overview' menu) and press
  •F12" ('Next') to confirm your selection.
- 1.2 Once the DME control unit has been found and is displayed in the overview, select the 'Maintenance/repairs' menu.
- 1.3 Select menu item ⇒ 'Adaptations' and confirm your selection by pressing •F12" ('Next') ⇒ DME adaptations.



DME adaptations

1.4 Comply with the displayed preconditions and press • F12" ('Next') to confirm ⇒ Adaptation preconditions.



Adaptation preconditions

- 1.5 Select the ⇒ 'Throttle valve adaptation' function so that the corresponding text line turns blue and press F8" ('Start') to start throttle valve adaptation ⇒ Throttle valve adaptation.
- 1.6 Follow the instructions on the PIWIS Tester while throttle valve adaptation is being performed.

Once throttle valve adaptation is complete, a tick will appear in the "Value" field on the PIWIS Tester display.



Throttle valve adaptation

If throttle valve adaptation is **not** completed successfully, adaptation must be repeated.

- 1.7 Press •F8" ('Stop') to end throttle valve adaptation.
- 2 Perform radiator shutter adaptation.
  - 2.1 Select the ⇒ 'Radiator shutter adaptation' function so that the corresponding text line turns blue and then press •F8" ('Start') to start radiator shutter adaptation ⇒ Radiator shutter adaptation.
  - 2.2 Follow the instructions on the PIWIS Tester while radiator shutter adaptation is being performed ⇒ PIWIS instructions.

Once adaptation is complete, a tick will appear in the "Value" field on the PIWIS Tester display.




Radiator shutter adaptation


07/22 ENU 2470


If radiator shutter adaptation is **not** completed successfully, the adaptation must be repeated.

- 2.3 End radiator shutter adaptation by pressingF8" ('Stop').
- 2.4 Press •F11" ('Back') to return to the start page of the ⇒ 'Maintenance/repairs' menu.










PIWIS instructions



Control unit selection



#### Information

If the fault occurs again during or after the test drive, the camshaft will also need to be checked for excessive axial play. This may well be the case, particularly in vehicles produced from the production period of March 2021 up to and including August 2021.  $\Rightarrow$  Technical Information '9X00IN Checking axial play of camshaft'

#### Checking axial play of camshaft



#### Information

"Indirectly" check whether the axial play of the intake camshaft is outside of the tolerance range by checking for any signs of wear on the actuator for the camshaft controller or the camshaft itself.


Work Procedure: 1 Remove the actuator for the camshaft controller of the intake camshaft. For instructions, see:

⇒ Workshop Manual '153919 Removing and installing camshaft controller actuator (R4)'

2470 ENU **07/22** 

## Symptom-based workshop manual

- 2 Check the actuator for the camshaft controller of the intake camshaft for scoring and seizure marks.
  - 2.1 If the actuator for the camshaft controller of the intake camshaft does not ⇒ Appearance of scoring and seizure marks on the actuator for the camshaft controller -1 have any scoring or seizure marks, check the intake camshaft actuator and the intake camshaft itself for scoring and seizure marks as well. To do this, continue with Step 3.
  - 2.2 If the actuator for the camshaft controller of the intake camshaft ⇒ Appearance of scoring and seizure marks on the actuator for the camshaft controller -2- has scoring or mation '15 2010 Peoplesing intake camshaft'



Appearance of scoring and seizure marks on the actuator for the camshaft controller

for the camshaft controller -2- has scoring or seizure marks, continue with ⇒ Technical Information '153919 Replacing intake camshaft'.

- 3 Remove the intake camshaft actuator. For instructions, see:
  - ⇒ Workshop Manual '158419 Removing and installing camshaft actuator'
- 4 Check the intake camshaft actuator for scoring and seizure marks.



#### Information


The axial play of the intake camshaft is not guaranteed if the spacer of the intake camshaft actuator shows signs of wear.

Service

07/22 ENU 2470

2

- 5 Check the intake camshaft for scoring and seizure marks.
  - 5.1 If the intake camshaft and the actuator do not have scoring or seizure marks, the fault will need to be located and remedied another way. In this case, discuss and agree on how to proceed with the your contact person at Technical Support. For information on the subsequent work required for completing the vehicle, see ⇒ Technical Information '158419 Concluding work after checking or replacing the intake camshaft'.
  - 5.2 If the intake camshaft or the actuator has scoring or seizure marks, continue with ⇒ Technical Information '158419 Replacing intake camshaft'.



Appearance of scoring and seizure marks on the camshaft actuator

### Replacing intake camshaft

Work Procedure: 1 Replace the intake camshaft and damaged accessories.

For instructions, see:

⇒ Workshop Manual '158219 Removing and installing cylinder head cover'

#### Required parts and tools

Parts Info: Required Parts Info:

Part No.	Designation - Location	Number
9A714511320	⇒ Seal – Vacuum pump	2 ea.
9A710351710	⇒ Seal – Oil separator	1 ea.
N 91232801	<ul><li>⇒ Collared cheese head bolt with hexagon socket head, M6 x 52</li><li>– Bearing saddle</li></ul>	6 ea.
N 10451409	⇒ Internal hexagon round countersunk screw, self-locking, M6 x 16  – Bearing saddle	6 ea.

$\mathbf{}$		Service
_	2470	FNU 07/22

PAF105540	<ul><li>⇒ Countersunk screw, M6 x 35</li><li>– Cylinder head cover</li></ul>	22 ea.
WHT005184	⇒ O-ring, 31 x 2 – High-pressure pump	1 ea.
PAF108682	⇒ Internal serration screw, M8 x 22 – High-pressure pump	2 ea.
9A7109021	⇒ Camshaft – Intake	1 ea.
95810925911	⇒ Magnet – Intake camshaft	1 ea.
95810358300	⇒ Seal – Magnet	1 ea.
N 10451409	⇒ Internal hexagon round countersunk screw, self-locking, M6 x 16 – Magnet	3 ea.

Materials: **Required materials** (usually already available at the Porsche dealer):

Part No.	Designation	Quantity
00004330510	⇒ Sealing compound (1 tube)	5 grams/ 0.18 oz

Tool:

- T10352C T10352C Assembly tool
- T10352/4 T10352/4 Assembly tool
- VAS 6890 Spring band clamp pliers
- T10352C T10352C Assembly tool
- T10352/4 T10352/4 Assembly tool
- VAS 6079 Dial gauge
- T10170A T10170A Dial gauge adapter
- T40243 T40243 Lever
- T40267 T40267 Staking tool
- T40011 T40011 Staking pin
- T40271 T40271 Camshaft clamp
- T40266 T40266 Adapter

#### Concluding work after checking or replacing intake camshaft

Work Procedure: 1 Install camshaft actuator.

For instructions, see:

⇒ Workshop Manual '158419 Removing and installing camshaft actuator'

Service

07/22 ENU 2470

2

- 2 Install actuator for the camshaft controller of the intake camshaft. For instructions, see:
  - ⇒ Workshop Manual '153919 Removing and installing camshaft controller actuator (R4)'

#### Invoicing

For documentation and invoicing in the event of a guarantee, state the work items required depending on the scope of work and the specified PCSS encryption in the warranty claim:

APOS	Labor operation	I No.
15050141	Checking intake camshaft	
15821940	Removing and installing cylinder head cover	
24702541	Re-programming DME control unit	
15390141	Checking camshaft controller actuator	

#### PCSS encryption:

Location (FES5)	24700	DME control unit
Damage type (SA4)	1134	Programming error

#### References:

- ⇒ Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'
- ⇒ Workshop Manual '153919 Removing and installing camshaft controller actuator (R4)'
- ⇒ Workshop Manual '158219 Removing and installing cylinder head cover'
- ⇒ Workshop Manual '158419 Removing and installing camshaft actuator'

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.