

**Subject:**

**ACCESSORY SIDE ROCKER TRIM INSTALLATION INSPECTION INSTRUCTIONS**

**Service Alert No.: SA-022/22**

**Last Issued : 04/22/2022**

## BULLETIN NOTES

### APPLICABLE MODEL(S)/VINS

2023 CX-50

## DESCRIPTION



Before beginning the installation of the accessory side rocker trim (aka "garnish"), part number **VA40-V3-100**, read these instructions.

## REPAIR PROCEDURE

To ensure proper alignment of the side rocker trim parts to the vehicle door cladding, follow the steps below immediately after installing the side rocker trim parts using the original installation instructions.

**NOTE: If you do not have a copy of the installation instructions, they can be found here: [Accessories E-catalog \(Installation Instructions\)](#).**

1. Check for proper alignment to the door cladding tangency point as shown in the images below.
2. If parts are misaligned, immediately remove them and re-position.
3. If holes have been drilled incorrectly and are the cause of the misalignment, *the door cladding must be replaced*.



**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.