

Subject: CORROSION AT THE CONTACT PART BETWEEN THE ROOF MOLDING CLIPS AND THE ROOF PANEL	Bulletin No.: 09-017/22
	Last Issued : 04/29/2022

BULLETIN NOTES

APPLICABLE MODEL(S)/VINS

2019-2021 Mazda3 (Japan built) vehicles with VINS lower than JM1BP*****507106 (produced before December 4, 2021)

2019-2021 Mazda3 (Mexico built) vehicles with VINS lower than 3MZBP*****219987 (produced before December 2, 2021)

DESCRIPTION

Some vehicles may have rust (1) on the contact parts between the clips (for attaching the roof molding) and the roof panel (ditches of the roof rail).




This is caused by the gap between the roof molding attachment clips and the roof panel not being wide enough to allow paint to be appropriately applied to the roof panel. To eliminate this concern, the shape of the roof molding clip has been changed to enable paint application between the clip's rib and roof during the manufacturing process. Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify the customer concern.
2. Remove the roof molding clips, repair the rusted area, and replace the clips with new ones.
 - a. Remove the roof molding according to the procedure on MGSS (ROOF MOLDING REMOVAL).


CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

b. Remove all mounted "Clip A's" from the vehicle. (Two clips for 4-door SD and four clips for 5-door HB).




1	Clip A
2	Clip B
3	Roof Molding
4	Vehicle Front

c. Remove the rust (1), clean the surface, and repaint the rusted area.




CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

d. Paint the new "Clip A's" with the same paint of the vehicle, and then install "Clip A's" on the rectangular protrusion (1) on the body side.



e. Apply adhesive around each clip (1) (on the yellow rectangular areas) after installing "Clip A's" on the vehicle.



f. Reinstall the roof molding according to the procedure on MGSS (ROOF MOLDING INSTALLATION).

3. Verify the repair.

PARTS INFORMATION

Part Number	Description	Qty.	Notes
-	Super glue (Cyanoacrylate glue)	1	Adhesive (products on the market)
GJYA-50-629A	Clip, Roof Molding	2 (for 4-door SD) or 4 (for 5-door HB)	Clip A (both sides)

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

WARRANTY INFORMATION**NOTE:**

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	53
Damage Code	9Y
Part Number Main Cause	GJYA-50-629A
Quantity	2 (for 4-door SD) or 4 (for 5-door HB)
Operation Number / Labor Hours:	XXT4AXRX / 0.2 Hrs.

NOTE:

- MNAO Warranty requires 2 forms attached: D40 (for TSB and photos of paint/rust) and D14 (for the sublet of the paint work).
- Preauthorization is required for any total paint repair estimate over \$1000.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.