

CAMPAIGN LAUNCH STATUS

N627 H376 EMISSIONS RECALLS–AJ20 P6 ENGINE PCV



EMISSION RECALLS N627 H376 – 19-22 MY MODELS WITH P6 ENGINE	
AFFECTED MODEL	20-22MY Defender, Discovery, Range Rover, 21MY RR Velar 19-22MY Range Rover Sport,. 21MY F-PACE
VOLUME AFFECTED	Land Rover USA 44,240 CAN 3566 Jaguar USA 914 CAN 156
ISSUE/REPAIR	Air leaks within the crankcase ventilation system resulting in a MIL (Check engine lamp) with DTC P0507 may be caused by a damaged membrane in the Positive Crankcase Ventilation system, (PCV). Customers may observe a higher idle speed. A replacement PCV kit is to be installed with a rubber membrane more resilient to blow-by gas condensate acidity resulting from use of ethanol fuels
REPAIR TIME	0.2 hrs to replace PCV with possible additional 0.2 hrs to read & clear DTC if MIL is set. + Drive In/Out
CAMPAIGN LAUNCH TARGET	April 22nd, 2022
Notes	Owners will be notified by mail during the month of April

